

CORRIGENDA #3**TO THE DISCLOSURE STATEMENT**

for

2456965 ONTARIO INC.(hereinafter referred to as the “**Declarant**”)

in respect of the

RIVERVIEW CONDOMINIUM PROJECT(hereinafter referred to as this or the “**Condominium**” or the “**Condominium Corporation**”)

developed on the lands municipally located at 8, 18 and 38 Water Walk Drive, Markham, Ontario

Dated: March 30th, 2023

*The proposed declaration and condominium disclosure statement dated February 15th, 2019, prepared by the Declarant for the Condominium, as amended by Corrigenda #1 dated December 20th, 2019 (hereinafter referred to as “**Corrigenda #1**”) and by Corrigenda #2 dated May 30th, 2022 (hereinafter referred to as “**Corrigenda #2**”), is hereby further amended by this Corrigenda, and should therefore be read and construed in light of the following changes or corrections (on the express understanding that any words, terms or phrases defined in the proposed declaration of the Condominium shall have the same meanings respectively ascribed to them in said declaration, whenever same are used or referred to in this Corrigenda), namely:*

1. **Parking Units**

- a) Although Corrigenda #2 stated that the Condominium would contain 1,002 parking units, purchasers are hereby advised that 104 residential visitor parking spaces have been (or will be) converted to parking units, therefore increasing the number of parking units in the Condominium to 1,106, comprised of: (i) parking units 1, 8 to 58 inclusive and 268 to 371 inclusive on level A, (ii) parking units 1 to 20 inclusive, 22 to 166 inclusive and 173 to 321 inclusive on level B, (iii) parking units 1 to 20 inclusive, 22 to 167 inclusive and 174 to 323 inclusive on level C, and (iv) parking units 1 to 20 inclusive, 22 to 167 inclusive and 174 to 327 inclusive on level D (hereinafter collectively referred to as the “**Parking Units**”).

2. **Accessible Parking Units**

- a) Although Corrigenda #2 stated that the Condominium would contain 13 non-visitor accessible parking units, purchasers are hereby advised that said number has increased to 19 non-visitor accessible parking units, comprised of parking units 19, 268, 273, 320, 346 and 371 on level A, parking units 4, 106, 123, 159, 164 and 187 on level B, parking units 4, 107 and 188 on level C and parking units 4, 107, 165 and 188 on level D (hereinafter individually referred to as an “**Accessible Parking Unit**” and hereinafter collectively referred to as the “**Accessible Parking Units**”), and each of the Accessible Parking Units shall be clearly designated for accessible parking on the description plan sheet filed concurrently with the Condominium’s declaration.
- b) Non-disabled owners and/or occupants of an Accessible Parking Unit (including a disabled unit owner who is not personally using or occupying the Accessible Parking Unit) shall be obligated, upon notification by the Condominium Corporation, to exchange, at no cost to a disabled driver who is a resident of the Condominium (and who holds a valid accessible parking permit that is appropriately displayed or visible in their vehicle), the use of the Accessible Parking Unit with the disabled driver’s non-accessible parking unit, throughout the duration of such disabled person’s residency in the Condominium.

3. **Electrical Parking Units and Roughed-In Parking Units**

- a) Purchasers are hereby advised that the location of some of the 81 electrical parking units has changed since Corrigenda #2 was issued and the electrical parking units in the Condominium are now comprised of: (i) parking units 14 to 16 inclusive, 13 to 48 inclusive, 59 to 68 inclusive, 116 to 122 inclusive and 124 to 126 inclusive on level B, (ii) parking units 59 to 68 inclusive, 117 to 123 inclusive and 125 to 127 inclusive on level C, and (iii) parking units 59 to 68 inclusive, 117 to 123 inclusive and 125 to 127 inclusive on level D (hereinafter individually referred to as an “**Electrical Parking Unit**” and collectively referred to as the “**Electrical Parking Units**”). Each of the Electrical Parking Units has been (or will be) completed with an electrical outlet and an electrical charger or charging station as an appurtenance thereto, in order to accommodate (and to correspondingly service or charge) any electric vehicle that may be owned or operated by the owner or tenant of such Electrical Parking Unit. In addition, a separate electricity submeter has been (or will be) installed as an appurtenance to each Electrical Parking Unit, in order to measure and confirm the cost

of the electricity consumed or utilized by any electric vehicle parked from time to time within any such Electrical Parking Unit, on a monthly or other periodic basis.

- b) Although Corrigenda #2 stated that the Condominium would contain 19 roughed-in parking units, purchasers are hereby advised that said number has increased to 27 roughed-in parking units, comprised of parking units 2, 3, 80 to 95 inclusive, 99, 114, 115 and 152 to 157 inclusive on level B (hereinafter individually referred to as a “**Roughed-In Parking Unit**” and collectively referred to as the “**Roughed-In Parking Units**”). Each of the Roughed-In Parking Units has been (or will be) “roughed-in” with only an electrical outlet and a separate electricity submeter as an appurtenance thereto, in order to accommodate an electrical charger or charging station which may be installed by a unit owner as an appurtenance to their respective Roughed-In Parking Unit.

4. **Visitor Parking**

- a) Although Corrigenda #2 stated that the Condominium would contain 208 residential visitor parking spaces (inclusive of 10 accessible residential visitor parking spaces), purchasers are hereby advised that 104 residential visitor parking spaces have been (or will be) converted to parking units (as per paragraph 1 above), therefore decreasing the number of residential visitor parking spaces in the Condominium from 208 to 104 (of which 6 are situate outdoors on level 1 inclusive of 2 accessible residential visitor parking spaces, and of which 98 are situate indoors on level A inclusive of 3 accessible residential visitor parking spaces) (hereinafter collectively referred to as the “**Residential Visitor Parking Spaces**”). Each of the Residential Visitor Parking Spaces shall be used by the visitors and guests of the respective owners, residents and tenants of the dwelling units in the Condominium from time to time, and by the Declarant’s employees, agents, representatives, contractors, subcontractors and invitees from time to time.

5. **The Revised First-Year Budget Statement**

- a) Purchasers are hereby advised that the proposed first-year budget of the Condominium has increased from \$5,504,223.00 to \$5,551,010.52, resulting in a net increase of \$46,787.52, on the express understanding that said net increase in budgetary expenditures will be totally off-set by the monthly common expenses attributable to each of the additional Parking Units to be incorporated within the Condominium. In other words, the aforementioned increase in the first-year budget statement does not affect the projected monthly common expenses allocated and attributable to those dwelling units that have already been sold prior to the date of this Corrigenda. The revised first-year budget statement reflects all anticipated increases in the respective maintenance, insurance, utility consumption and replacement costs relative to the operation and administration of the Condominium, and in connection with the performance and fulfilment of the Condominium’s duties and obligations set forth in the Condominium’s declaration. **A copy of the revised first-year budget statement dated March 30th, 2023 is enclosed with this Corrigenda as Schedule “A” hereto, together with a revised Schedule “D” to the proposed declaration of the Condominium (reflecting the proportions of common interests and expenses attributable to each of the units in the Condominium), along with a revised schedule of common element assessments, outlining the monthly common element assessment (in dollar terms) attributable to each of the units in the Condominium, inclusive of the additional Parking Units described in paragraph 1 above.**
- b) Please also note that the proposed reserve fund figure set forth in the revised first-year budget statement (which is intended to cover the major repair and replacement cost of the common elements and assets of the Condominium, based on their respective replacement cost and life-expectancy) was updated and increased from the previous reserve fund figure utilized in the previous proposed first-year budget statement.

It is the Declarant’s position that the foregoing matters outlined in this Corrigenda, as well as the revised first-year budget statement enclosed herewith (including the revised schedule of common interests and expenses, and the revised schedule of common element assessments comprising part of the revised first-year budget) do not constitute (nor give rise to) a material change.

Riverview Condominiums

**1041 DWELLING UNITS + 7 COMMERCIAL/RETAIL UNITS + 1031 PARKING UNITS + 75 PARKING UNITS (TANDEM) +
1017 LOCKER UNITS + 18 PARKING/LOCKER UNITS + 1 COMMERCIAL/RETAIL GARBAGE ROOM UNIT + 21
COMMERCIAL/RETAIL PARKING UNITS + 9 PARKING/LOCKER UNITS (TANDEM) + 7 COMMERCIAL/RETAIL STORAGE
UNITS**

SUMMARY OF THE FIRST YEAR OPERATING BUDGET

REVENUE

| | | |
|---------------------------|-----------|---------------------|
| Total Common Element Fees | \$ | 5,551,010.52 |
| Total Revenue | \$ | 5,551,010.52 |

OPERATING EXPENSES

| | | | |
|-----------------------------------|----------------|-----------|---------------------|
| Service and Maintenance Contracts | (Schedule "1") | \$ | 866,100.00 |
| Repairs and Maintenance | (Schedule "2") | \$ | 388,180.00 |
| Utilities | (Schedule "3") | \$ | 1,407,000.00 |
| Administrative Expenses | (Schedule "4") | \$ | 1,401,885.67 |
| Concierge Service | (Schedule "5") | \$ | 725,000.00 |
| Recreational Facilities | (Schedule "6") | \$ | 38,800.00 |
| Total Operating Expenses | | \$ | 4,826,965.67 |
| Reserve Fund Contribution at 15% | | \$ | 724,044.85 |

| | | |
|---|-----------|---------------------|
| Total Funds Required/Common Element Assessment | \$ | 5,551,010.52 |
|---|-----------|---------------------|

NOTES

1 Defined Terms

In addition to any words, terms or phrases specifically defined elsewhere in this budget statement, the defined words, terms or phrases set forth in the declaration of this Condominium shall have the same meaning ascribed to them in the said declaration whenever same are used or referred to in this budget statement.

2 Reserve Fund

The reserve fund noted above is established for the major repair and replacement of the common elements and assets of the Condominium (i.e. the repair and replacement of the mechanical equipment, the electrical and plumbing systems, repairs to the roof, etc.). The reserve fund figure used in this budget statement is based on the assumption that there will be in existence, at all times during the life span of the condominium building, a program of regular repair and maintenance, the costs of which shall be reflected in the Condominium's annual operating budget(s). The anticipated reserve fund pertaining to the Condominium is expected to be \$724,044.85 by the end of the first year of the Condominium's operation.

The Condominium is obliged to establish and maintain one or more reserve funds to cover the costs of the major repair and replacement of the common elements and assets of the Condominium. In turn, the Condominium is obliged to retain an independent and qualified consultant (being a member of one of the prescribed classes of persons authorized to conduct a reserve fund study) in accordance with section 32 of O. Reg. 48/01 to the Act (a "Qualified Consultant") to conduct a reserve fund study, for and on behalf of the Condominium, within the first year following registration, in accordance with the provisions of subsection 94(4) of the Act which will confirm, amongst other things, the adequacy of the reserve fund, and the annual appropriation necessary to cover the anticipated repair and replacement costs of the common elements and other assets of the Condominium, based on their respective life expectancy. The reserve fund study must be updated on a periodic basis, at the times and in the manner prescribed by the Act.

3 No Pending Lawsuits

There are no pending lawsuits material to the property of the Condominium of which the Declarant has actual knowledge, and that may affect the property of the Condominium after the registration of any deed or transfer to any unit in the Condominium by the Declarant to any unit purchaser.

4 Inflation Factor

This budget statement incorporates an assumed inflation factor of 3.5% per annum, compounded annually, based upon a projected Condominium registration date of July 31, 2023, and in the event that registration occurs sometime thereafter, then this budget statement (and all figures reflecting expenses set forth herein) should be read and construed as automatically being increased by the said inflation factor of 3.5% per annum, compounded annually (with said inflation rate applying to increase the budget figures for all or any portion of a year following the aforementioned target registration date). However, nothing set forth in this budget statement should be construed or interpreted as a representation or warranty that the actual registration of the Condominium will take place by the aforementioned date.

Please also note that the figures in the budget have already been increased by 3.5% per annum (in whole or in part) from those figures set forth in the last proposed budget dated December 19, 2019 (based on the inflationary factor of 3.5% set out in said budget, and triggered by the fact that the Condominium was not registered by March 2022, as originally anticipated).

Riverview Condominiums

1041 DWELLING UNITS + 7 COMMERCIAL/RETAIL UNITS + 1031 PARKING UNITS + 75 PARKING UNITS (TANDEM) + 1017 LOCKER UNITS + 18 PARKING/LOCKER UNITS + 1 COMMERCIAL/RETAIL GARBAGE ROOM UNIT + 21 COMMERCIAL/RETAIL PARKING UNITS + 9 PARKING/LOCKER UNITS (TANDEM) + 7 COMMERCIAL/RETAIL STORAGE UNITS

5 Riverview Condominiums

The Condominium is proposed to have 1041 Dwelling Units, 7 Commercial/Retail Units, 1031 Parking Units, 75 Parking Units (Tandem), 1017 Locker Units, 18 Parking/Locker Units, 1 Commercial/Retail Garbage Room Unit, 21 Commercial/Retail Parking Units, 9 Parking/Locker Units (Tandem) and 7 Commercial/Retail Storage Units.

6 Budget Notes

a) Save and except for the monthly common expenses contributions allocated and attributable to each unit in this Condominium (in accordance with Schedule "D" to the declaration, and as more particularly set out in this budget statement), there are no current or expected fees, charges, rents or other revenue to be paid to or by the Condominium Corporation, or by any of the owners for the use of the common elements or other facilities related to the property of the Condominium, save for:

i. a minimal damage / security deposit of \$250, together with a service/cleaning charge of \$75, payable in advance for each day or night of use or occupancy of the multi-purpose/party room situate in this Condominium (which fees are subject to change from time to time by the board or Condominium's property manager).

b) There are no services which have been excluded from this budget that the Declarant provides (or intends to provide) to this Condominium or its residents, and there are no expenses that the Declarant pays (or intends to pay) which might reasonably be expected to become, at any subsequent time, a common expense, and that have not already been included, reflected or addressed in this budget statement, save and except as expressly provided or qualified below, namely:

i. the elevator installation contract which has been (or will be) entered into by the Declarant for this Condominium already includes or incorporates (or will include or incorporate) the cost of all requisite maintenance and servicing work with respect to the elevators for the first year following the registration of the Condominium, and therefore although the first year budget statement quite properly excludes any elevator maintenance or repair costs, such costs will nevertheless have to be incurred by the Condominium in subsequent years, and will accordingly have to be properly budgeted for by the Condominium in subsequent

ii. various components of the Condominium building may be covered by existing or outstanding maintenance or repair warranties from third party suppliers / installers, and which warranties may correspondingly endure beyond the first year following the registration of the Condominium, and such circumstances will accordingly obviate the need to delineate (or make any requisite allowance for) the maintenance or repair costs with respect to such components in the first year budget. However, any requisite maintenance or repairs costs anticipated to arise or be incurred after the expiry of the applicable warranties (i.e. beyond the first year after registration) will thereafter have to be properly budgeted for by the Condominium in subsequent years;

iii. various components of the Condominium building will not have expected maintenance or repair costs within the first year following registration, simply because such components are relatively new, but will nevertheless give rise to future maintenance and repair costs as a result of normal wear and tear, and all such anticipated costs beyond the first year after registration will have to be properly budgeted for by the Condominium in subsequent years; and

iv. a provision for future reserve fund studies/updates will be required in subsequent years.

7 Budget Figures and Taxes

All figures are inclusive of applicable taxes unless otherwise indicated.

8 Other Factors That Can Impact This Budget

Although this budget is based upon best available information as at the date of its preparation, purchasers should be aware that budget predictions of future servicing and utility costs are, by their very nature, subject to change based upon regulatory and other changes which are beyond the Declarant's control and reasonable expectations. In particular, utility rates since deregulation have been extremely volatile and therefore difficult to predict with any certainty. Accordingly, the final first year budget implemented at the time of registration may be revised to reflect the then prevailing market conditions and rates.

9 Additional Costs, if and/or when applicable

All unit purchasers are hereby advised that although this proposed first year budget does not currently incorporate or reflect:

a) any realty taxes that may ultimately be assessed against any unit(s) that the Condominium Corporation is obliged to accept title to, from the Declarant as the transferor, pursuant to (or in accordance with) the provisions of the declaration, inasmuch as the formal assessment of same by the Municipal Property Assessment Corporation has not yet been completed, and no formal tax bill has yet been issued by the local municipality in connection therewith; and

b) any levies, charges and/or fees that the Condominium Corporation will ultimately be obliged to fund or pay for, pursuant to any municipal or provincial regulation, ordinance, by-law, policy, directive or requirement that may have been announced before (or after) the date of registration of this Condominium and/or the date of preparation of this first year budget, but which levies, charges and/or fees have not yet been formally announced or are not yet capable of being finally determined, quantified or calculated as at the date of this budget.

Nevertheless all of the foregoing realty taxes outlined in subparagraph (a) above (if applicable) and all of the foregoing levies, charges and/or fees outlined in subparagraph (b) above (if applicable) shall comprise part of the common expenses, as and when same are assessed, quantified and/or payable by the Condominium Corporation, and therefore this first year budget statement shall be deemed to be amended accordingly, so as to incorporate same as an integral part of the budget.

Riverview Condominiums

**1041 DWELLING UNITS + 7 COMMERCIAL/RETAIL UNITS + 1031 PARKING UNITS + 75 PARKING UNITS (TANDEM) +
1017 LOCKER UNITS + 18 PARKING/LOCKER UNITS + 1 COMMERCIAL/RETAIL GARBAGE ROOM UNIT + 21
COMMERCIAL/RETAIL PARKING UNITS + 9 PARKING/LOCKER UNITS (TANDEM) + 7 COMMERCIAL/RETAIL STORAGE
UNITS**

Service and Maintenance Contracts

Schedule "1"

Ground Maintenance

| | | |
|--|----|------------|
| 70010 Snow plowing and landscaping contracts | \$ | 88,000.00 |
| 70030 Flowers and shrubs | \$ | 28,000.00 |
| 70060 Sand, salt and ice melt | \$ | 15,000.00 |
| Total | \$ | 131,000.00 |

Heating and Air Conditioning

| | | |
|--------------------------------------|----|-----------|
| 72010 Preventive maintenance program | \$ | 62,000.00 |
| 72020 HVAC Repairs | \$ | 12,500.00 |
| 72040 Filters | \$ | 18,000.00 |
| Total | \$ | 92,500.00 |

Elevator Maintenance

| | | |
|--------------------------------------|----|------------|
| 71010 Preventive maintenance program | \$ | 71,000.00 |
| 71015 Monitoring | \$ | 4,600.00 |
| 71020 Licenses | \$ | 12,600.00 |
| 71030 Non-contract repairs | \$ | 28,500.00 |
| 71040 Inspection | \$ | 3,200.00 |
| Total | \$ | 119,900.00 |

Waste Disposal

| | | |
|---|----|-----------|
| 73050 Repairs and maintenance of compactor | \$ | 21,000.00 |
| 73040 Cleaning of compactor and garbage chute | \$ | 14,000.00 |
| 73020 Ecology - garbage odour control | \$ | 16,000.00 |
| Total | \$ | 51,000.00 |

Cleaning

| | | |
|--|----|------------|
| 74010 Cleaning contract | \$ | 325,000.00 |
| 74030 Annual window washing | \$ | 29,000.00 |
| 74200 Underground garage power washing | \$ | 25,000.00 |
| 74060 Pest control | \$ | 10,000.00 |
| 74080 Steam cleaning common area carpets | \$ | 22,000.00 |
| 74050 Cleaning supplies and paper products | \$ | 14,200.00 |
| Total | \$ | 425,200.00 |

Fire Prevention

| | | |
|---|----|-----------|
| 77020 Fire alarm and sprinkler inspection | \$ | 17,600.00 |
| 77030 Monthly fire alarm testing | \$ | 14,900.00 |
| 77010 Fire alarm monitoring | \$ | 7,500.00 |
| 77040 Fire alarm repairs | \$ | 6,500.00 |
| Total | \$ | 46,500.00 |

TOTAL SCHEDULE "1"

\$ 866,100.00

Repairs and Maintenance

Schedule "2"

Electrical Repairs & Supplies

| | | |
|---|----|-----------|
| 75010 Electrical repairs | \$ | 23,500.00 |
| 75020 Electrical supplies (light bulbs) | \$ | 12,000.00 |
| 77070 Service diesel generator | \$ | 5,500.00 |
| Total | \$ | 41,000.00 |

Plumbing Repairs & Supplies

| | | |
|---|----|-----------|
| 76020 Plumbing repairs and supplies | \$ | 28,000.00 |
| 76030 Cleaning catch basins, sump pump pits | \$ | 7,880.00 |
| Total | \$ | 35,880.00 |

Building General

| | | |
|--|----|------------|
| 79010 Superintendents and Handymen | \$ | 265,000.00 |
| 78140 Misc. maintenance repairs | \$ | 19,500.00 |
| 78080 Misc. plaster and painting | \$ | 8,800.00 |
| 78010 Doors/Locks/Glass repairs | \$ | 6,500.00 |
| 78090 Miscellaneous maintenance supplies | \$ | 7,000.00 |
| 90210 Roof anchors inspection | \$ | 4,500.00 |
| Total | \$ | 311,300.00 |

Riverview Condominiums

**1041 DWELLING UNITS + 7 COMMERCIAL/RETAIL UNITS + 1031 PARKING UNITS + 75 PARKING UNITS (TANDEM) +
1017 LOCKER UNITS + 18 PARKING/LOCKER UNITS + 1 COMMERCIAL/RETAIL GARBAGE ROOM UNIT + 21
COMMERCIAL/RETAIL PARKING UNITS + 9 PARKING/LOCKER UNITS (TANDEM) + 7 COMMERCIAL/RETAIL STORAGE
UNITS**

Heating and Air Conditioning

The amount has been allowed for a preventive maintenance program on the pumps, make-up air unit, exhaust fans and recreational amenities. For the first year all equipment is under warranty and covered by the manufacturer.

Elevator Maintenance

The amount indicated in this budget ensures safety and maximum availability this amount has been allowed for a full preventive maintenance program on the elevators. For the first year all equipment is under warranty.

Waste Disposal

Allowances for the repair, maintenance and cleaning of the waste compactor and garbage bins, as well as for chute cleaning and the purchase of odour control products.

Cleaning

Allowances for a cleaning contract for the cleaning of the common areas of this Condominium, for annual window washing, for power washing the underground parking garage, for pest control treatments for the common areas of this Condominium, for steam cleaning the corridor carpets and weather mats twice a year and for the purchase of cleaning supplies and maintenance products in relation to the common areas of this Condominium.

Fire Prevention

The amount has been allowed for the repair, maintenance and monthly/annual inspection and testing of the fire alarm and sprinkler systems in accordance with the Ontario Fire Code.

REPAIRS AND MAINTENANCE

SCHEDULE "2"

Electrical Repairs and Supplies

The budgeted amount represents the costs for the purchase of electrical supplies, as well as for the repairs and service to the electrical equipment and components not covered under warranty.

Plumbing Repairs & Supplies

The budgeted amount represents the costs of for the purchase of plumbing supplies, as well as for the repairs to the plumbing equipment and components not covered under warranty and for the cleaning of the catch basins and sump pump pits.

Building General

The amount represents the costs for general repairs and maintenance of the common area (i.e. touch up painting, minor repairs to doors and locks, window repairs, internal and external signs, purchase of hardware, maintenance of indoor plants, etc.). An allowance has been included for the hiring of one (1) full-time live-out superintendent, one (1) full-time live-in superintendent and two (2) handymen.

Pool Maintenance

The budgeted amount represents the costs of regular pool maintenance.

Gym Equipment Maintenance

The budgeted amount represents the costs of regular gym equipment maintenance.

UTILITIES

SCHEDULE "3"

Electricity

Represents the cost of all electricity used for the common elements of the Condominium. Each of the dwelling units (together with any electrical parking unit) will be separately submetered (and each dwelling unit owner will be separately invoiced) for the electricity service utilized or consumed by the dwelling unit (and any electrical parking unit and any exclusive-use common element areas appurtenant to said dwelling unit), pursuant to a submeter appurtenant to the dwelling unit (or the electrical parking unit, if any) that is read by the Utility Monitor, so that the cost of the consumption of electricity by the dwelling unit (and any electrical parking unit and any exclusive-use common element areas appurtenant to said dwelling unit) shall not comprise part of the common expenses, but rather shall be borne and paid for solely by the dwelling unit owner. Furthermore, each of the commercial/retail units (together with any electrical parking unit) will be separately submetered (and each commercial/retail unit owner will be separately invoiced) for the electricity service utilized or consumed by the commercial/retail unit (and any electrical parking unit and any exclusive-use common element areas appurtenant to said commercial/retail unit), pursuant to a submeter appurtenant to the commercial/retail (or the electrical parking unit, if any) that is read by the Utility Monitor, so that the cost of the consumption of electricity by the commercial/retail unit (and any electrical parking unit and any exclusive-use common element areas appurtenant to said commercial/retail unit) shall not comprise part of the common expenses, but rather shall be borne and paid for solely by the commercial/retail unit owner.

Riverview Condominiums

1041 DWELLING UNITS + 7 COMMERCIAL/RETAIL UNITS + 1031 PARKING UNITS + 75 PARKING UNITS (TANDEM) + 1017 LOCKER UNITS + 18 PARKING/LOCKER UNITS + 1 COMMERCIAL/RETAIL GARBAGE ROOM UNIT + 21 COMMERCIAL/RETAIL PARKING UNITS + 9 PARKING/LOCKER UNITS (TANDEM) + 7 COMMERCIAL/RETAIL STORAGE UNITS

Water

Represents the cost of all water used for the common elements of the Condominium. Each of the dwelling units will be separately submetered (and correspondingly separately invoiced) for the hot water and cold water service utilized or consumed by the dwelling unit (and any exclusive-use common element area appurtenant thereto), pursuant to a submeter appurtenant to the dwelling unit that is read by the Utility Monitor, so that the cost of the consumption of hot water and cold water by the dwelling unit (and by any exclusive-use common element area appurtenant thereto) shall not comprise part of the common expenses, but rather shall be borne and paid for solely by the dwelling unit owner. Furthermore, each of the commercial/retail units will be separately submetered (and correspondingly separately invoiced) for the cold water service utilized or consumed by the commercial/retail (and any exclusive-use common element area appurtenant thereto), pursuant to a submeter appurtenant to the commercial/retail unit that is read by the Utility Monitor, so that the cost of the consumption of cold water by the commercial/retail unit (and by any exclusive-use common element area appurtenant thereto) shall not comprise part of the common expenses, but rather shall be borne and paid for solely by the commercial/retail unit owner. The recovery for water (see Estimated Variable Energy Costs) is typically more than the actual cost of water consumption and therefore an amount of zero is budgeted.

Annual Fixed Capacity Charges

The Condominium Corporation will be responsible for a fixed charge in respect of the thermal energy capacity and it is based upon a fixed KW/h rate for both chilled and hot water consumption.

Estimated Variable Energy Costs

Estimated Variable Energy Costs account for "Chilled Water Energy Charge" and "Hot Water Energy Charge". These charges are based on the Condominium's actual metered usage of chilled water and hot water. The Chilled Water Energy Charge is calculated based on the equivalent electricity charges and associated utility fees which would have been incurred by the Condominium had the Condominium produced the chilled water using conventional on-site equipment. The Hot Water Energy Charge is calculated based on the equivalent natural gas charges and associated utility fees which would have been incurred by the Condominium had the Condominium produced the hot water using conventional on-site equipment.

ADMINISTRATIVE EXPENSES

SCHEDULE "4"

Legal Fees

An allocation for the Condominium Corporation to engage a legal consultant.

Annual Financial Audit

This figure represents the cost of having the Condominium's auditor prepare a set of annual audited financial statements of the Condominium Corporation (including a balance sheet, a statement of general operations, a statement of changes in financial position, a statement of reserve fund operations and such other additional statements and information as may be required or prescribed by the Act), and presenting them before the annual general meeting of the owners, together with the cost of having the Condominium's auditor make a formal report on such financial statements to the Condominium Corporation (on behalf of the owners), in accordance with sections 66-71 of the Act.

Condominium Authority of Ontario Fees

Represents fees charged by (and payable to) the Condominium Authority of Ontario pursuant to the provisions of the *Protecting Condominium Owners Act, 2015*.

Automated Parcel Delivery Maintenance

An allowance for maintenance services with respect to the automated parcel delivery system.

Bank Charges

Represents the cost of bank service charges and account maintenance.

Insurance

The coverage obtained does not cover the contents in (nor improvements) to any unit, nor improvements to exclusive use common elements, nor does the insurance cover the liability of any unit owner for any occurrences within his or her unit. This cost represents a one year premium for all risk insurance for the full replacement value of the units and common elements, and includes comprehensive general liability insurance, and boilers and machinery insurance, as well as directors' errors and omissions insurance.

Reserve Fund Study / Performance Audit

a) Reserve Fund Study

This figure represents the projected cost to engage or retain an independent and qualified consultant (being a member of one of the prescribed classes of persons authorized to conduct a reserve fund study, in accordance with section 32 of O. Reg. 48/01 to the Act) to conduct the reserve fund study for and on behalf of the Condominium within the first year following registration, pursuant to section 94(4) of the Act. This reserve fund study will confirm, amongst other things, the requisite reserve fund for this Condominium, and the annual appropriation necessary to cover the anticipated repair and replacement costs of the common elements and other assets of the Condominium, based on their respective life expectancy.

Riverview Condominiums

1041 DWELLING UNITS + 7 COMMERCIAL/RETAIL UNITS + 1031 PARKING UNITS + 75 PARKING UNITS (TANDEM) + 1017 LOCKER UNITS + 18 PARKING/LOCKER UNITS + 1 COMMERCIAL/RETAIL GARBAGE ROOM UNIT + 21 COMMERCIAL/RETAIL PARKING UNITS + 9 PARKING/LOCKER UNITS (TANDEM) + 7 COMMERCIAL/RETAIL STORAGE UNITS

It is presently intended that the Condominium Corporation will retain an independent and qualified consultant to conduct the requisite reserve fund study forthwith following the registration of the Condominium, with the expectation that said study will be completed and available for review on or about the date of the Condominium's turnover meeting, convened in accordance with the provisions of section 43 of the Act. The consultant that is qualified to undertake the reserve fund study may likewise be qualified to undertake the performance audit described below, and the Act does not in any way preclude the same consulting firm being retained to undertake both matters for and on behalf of the Condominium. In light of the foregoing, the figures set out in this budget representing the respective costs of the reserve fund study and the performance audit are predicated on the presumption that for the purposes of economies of scale, the firm or consultant that is retained to undertake the reserve fund study for and on behalf of the Condominium, will also thereafter be retained by the Condominium to undertake the requisite performance audit mandated by section 44 of the Act, and described below. This economy in overall costs to the Condominium (and its corresponding beneficial impact on the first year budget) stems from the fact that the same firm or consultant retained to undertake the initial reserve study and the subsequent performance audit will have already attained, in the course of undertaking the study, a thorough knowledge and familiarity with the Condominium's building components, etc., and would generally be charging a lower overall fee for both matters because of the opportunity to undertake both assignments for and on behalf of the Condominium. In the event that the Condominium Corporation ultimately retains a different consultant to undertake the reserve fund study or the performance audit, at a cost or charge higher than that proposed in this budget, then in the absence of some unforeseen matter, event or circumstance arising which justifies the higher figure, the Declarant will disclaim any liability or responsibility for the discrepancy in cost.

b) Performance Audit

This figure represents the projected cost to engage or retain an independent and qualified consultant (who holds a certificate of authorization within the meaning of the *Professional Engineers Act*, or alternatively a certificate of practice within the meaning of the *Architects Act*) to conduct a performance audit of the common elements, for and on behalf of the Condominium, in accordance with the provisions of section 44 of the Act, and to correspondingly inspect (and report on) the condition or state of repair of all major components of the building(s) comprising part of the Condominium (including, without limitation, the foundation, the parking garage, the wall construction, air and vapour barriers, windows, doors, elevators, roofing, mechanical and electrical systems, fire protection systems and all other components that are prescribed by the regulations to the Act from time to time, and specifically the Condominium's elevating devices, telecommunication systems, sprinkler systems and outside parking areas, if any, that service or comprise part of the Condominium, as expressly provided by section 12 of O. Reg. 48/01 to the Act), and which performance audit shall be conducted no earlier than six (6) months and no later than ten (10) months following the registration of the Condominium.

Management Fees (includes one full time onsite condominium manager and one full time onsite administrator)

The management fees (which are based on \$28.00 per month plus HST per dwelling unit and per commercial/retail unit) paid to the professional property manager Times Property Management Inc. include, among other things, the following services:

I) Financial:

- a) Preparing the annual operating budget for approval by the Board of Directors.
- b) Accounting for the common expense monies, including the collection and disbursement of same.
- c) Advising the Board of Directors monthly of any accounts receivable and initiating appropriate legal action to collect overdue accounts if requested to do so by the Board of Directors.
- d) Preparing and submitting annually financial statements, and providing comparisons of actual revenues and expenditures to those set out in the budget.

II) Administration:

- a) Maintaining a register of unit owners, based upon information received.
- b) Enforcing the terms and conditions of the declaration, the by-laws and the rules, and making recommendations for the modifications thereto.
- c) Preparing building inspection reports and following up said reports to ensure that outstanding matters have been rectified and attended to.
- d) Participating at monthly Board of Directors' meetings and as may be further reasonably required.
- e) Assisting the Board of Directors in hiring personnel and supervising all Condominium Corporation staff.
- f) Causing to be repaired common elements when required.
- g) Establishing a preventive maintenance program for the common elements and preparing a workload schedule for on-site personnel.
- h) Furnishing all unit owners with a procedure to follow and people to call in case of an emergency.
- i) Conducting management functions.

Telephone

This account provides for the necessary phone lines required in the operation of this Condominium.

Bulk Internet

Internet services that will be offered to the occupants on a bulk billing basis and included in each unit owner's common expenses.

Riverview Condominiums

1041 DWELLING UNITS + 7 COMMERCIAL/RETAIL UNITS + 1031 PARKING UNITS + 75 PARKING UNITS (TANDEM) + 1017 LOCKER UNITS + 18 PARKING/LOCKER UNITS + 1 COMMERCIAL/RETAIL GARBAGE ROOM UNIT + 21 COMMERCIAL/RETAIL PARKING UNITS + 9 PARKING/LOCKER UNITS (TANDEM) + 7 COMMERCIAL/RETAIL STORAGE UNITS

Cable TV

The budgeted amount represents the costs of cable TV for monitors attached to the gym equipment and on gym walls.

AGM Expenses

The budgeted amount represents the costs of preparation of AGM packages and delivery of same.

Holiday / Social Expenses

The budgeted amount represents the costs of holiday and social event decorations.

Office Expenses

An allocation for the purchase of supplies (i.e. photocopier, paper, etc.) as required to operate the management office for the Condominium and any repairs to same.

Turnover Audit

This figure represents the cost of having audited financial statement of the Condominium Corporation, as of the last day of the month in which the turnover meeting is scheduled to be held, prepared by the Condominium's auditor (on behalf of the owners), and which financial statements are obliged to be delivered by the Declarant to the board of directors within sixty (60) days after the turnover meeting, in accordance with subsection 43(7) of the Act.

Investment Plan

An allowance for the preparation of an investment plan in accordance with subsection 115(8) of the Act.

Green Loan Repayment

The estimated annual cost related for the acquisition of various energy efficient equipment and building materials used in the construction of the building based on a loan of \$1,500,000.00 bearing interest at a rate of 6% per annum with an amortization period of 10 years and a term of 10 years. Please refer to this Condominium's declaration for further details.

Maintenance/Security/Miscellaneous Equipment Acquisition

This Condominium will be obliged to purchase the Maintenance/Security/Miscellaneous Equipment in the amount of \$250,000.00, inclusive of H.S.T., on the first anniversary of the date of registration of this Condominium.

CONCIERGE SERVICE

SCHEDULE "5"

Concierge Contract

The Condominium will have three (3) concierge personnel stationed in this Condominium and they will be operating on a 24 hour per day basis, 7 days a week. The concierge personnel will be paid hourly plus over time for working on ten (10) statutory holidays. Each concierge personnel's shift shall not exceed eight (8) hours per day.

RECREATIONAL FACILITIES

SCHEDULE "6"

Pool Maintenance

An allowance for pool maintenance including, without limitation, the supply and application of all required chemicals.

Gym Equipment Maintenance

An allowance for gym equipment maintenance including, without limitation, the replacement of miscellaneous parts with respect to the fitness equipment in the Condominium's gym.

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|-------------------------------------|----------|-----------|--|-----------|-----------|
| | | | | | | |
| Building C | Dwelling Unit | 1 | 1 | 0.087329% | x 1 = | 0.087329% |
| | Dwelling Unit | 2 | 1 | 0.093304% | x 1 = | 0.093304% |
| | Dwelling Unit | 3 | 1 | 0.080558% | x 1 = | 0.080558% |
| | Dwelling Unit | 4 | 1 | 0.080558% | x 1 = | 0.080558% |
| | Dwelling Unit | 5 | 1 | 0.080558% | x 1 = | 0.080558% |
| | Dwelling Unit | 6 | 1 | 0.102962% | x 1 = | 0.102962% |
| | Dwelling Unit | 7 | 1 | 0.083943% | x 1 = | 0.083943% |
| Retail C | Commercial/Retail Unit | 8 | 1 | 0.223052% | x 1 = | 0.223052% |
| | Commercial/Retail Unit | 9 | 1 | 0.126463% | x 1 = | 0.126463% |
| | Commercial/Retail Unit | 10 | 1 | 0.197262% | x 1 = | 0.197262% |
| | Commercial/Retail Unit | 11 | 1 | 0.136122% | x 1 = | 0.136122% |
| | Commercial/Retail Unit | 12 | 1 | 0.136122% | x 1 = | 0.136122% |
| | Commercial/Retail Unit | 13 | 1 | 0.136122% | x 1 = | 0.136122% |
| | Commercial/Retail Unit | 14 | 1 | 0.139308% | x 1 = | 0.139308% |
| Building B | Dwelling Unit | 15 | 1 | 0.065721% | x 1 = | 0.065721% |
| | Dwelling Unit | 16 | 1 | 0.086931% | x 1 = | 0.086931% |
| | Dwelling Unit | 17 | 1 | 0.098780% | x 1 = | 0.098780% |
| Building A | Dwelling Unit | 18 | 1 | 0.086333% | x 1 = | 0.086333% |
| | Dwelling Unit | 19 | 1 | 0.067414% | x 1 = | 0.067414% |
| | Dwelling Unit | 20 | 1 | 0.059547% | x 1 = | 0.059547% |
| | Dwelling Unit | 21 | 1 | 0.112523% | x 1 = | 0.112523% |
| | Dwelling Unit | 22 | 1 | 0.081255% | x 1 = | 0.081255% |
| | Dwelling Unit | 23 | 1 | 0.082151% | x 1 = | 0.082151% |
| | Dwelling Unit | 24 | 1 | 0.077670% | x 1 = | 0.077670% |
| | Dwelling Unit | 25 | 1 | 0.123475% | x 1 = | 0.123475% |
| Dwelling Unit | 26 | 1 | 0.099577% | x 1 = | 0.099577% | |
| Building C | Commercial/Retail Garbage Room Unit | 27 | 1 | 0.000001% | x 1 = | 0.000001% |
| Building C | Dwelling Unit | 1 | 2 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 2 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 2 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 2 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 2 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 2 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 2 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 2 | 0.095893% | x 1 = | 0.095893% |
| | Dwelling Unit | 9 | 2 | 0.080060% | x 1 = | 0.080060% |
| | Dwelling Unit | 10 | 2 | 0.063231% | x 1 = | 0.063231% |
| | Dwelling Unit | 11 | 2 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 12 | 2 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 13 | 2 | 0.064924% | x 1 = | 0.064924% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 14 | 2 | 0.071596% | x 1 = | 0.071596% |
| | Dwelling Unit | 15 | 2 | 0.107742% | x 1 = | 0.107742% |
| | Dwelling Unit | 16 | 2 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 17 | 2 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 18 | 2 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 19 | 2 | 0.085039% | x 1 = | 0.085039% |
| | Dwelling Unit | 20 | 2 | 0.083844% | x 1 = | 0.083844% |
| | Dwelling Unit | 21 | 2 | 0.086731% | x 1 = | 0.086731% |
| | Dwelling Unit | 22 | 2 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 23 | 2 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 24 | 2 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 25 | 2 | 0.061439% | x 1 = | 0.061439% |
| | Dwelling Unit | 26 | 2 | 0.058452% | x 1 = | 0.058452% |
| | Dwelling Unit | 27 | 2 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 28 | 2 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 29 | 2 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 30 | 2 | 0.092706% | x 1 = | 0.092706% |
| | Dwelling Unit | 31 | 2 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 32 | 2 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 33 | 2 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 34 | 2 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 35 | 2 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 36 | 2 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 37 | 2 | 0.094598% | x 1 = | 0.094598% |
| | Dwelling Unit | 38 | 2 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 39 | 2 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 40 | 2 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 41 | 2 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 42 | 2 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 43 | 2 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 44 | 2 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 45 | 2 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 46 | 2 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 3 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 3 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 3 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 3 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 3 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 3 | 0.101369% | x 1 = | 0.101369% |
| | Dwelling Unit | 7 | 3 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 3 | 0.095893% | x 1 = | 0.095893% |
| | Dwelling Unit | 9 | 3 | 0.080060% | x 1 = | 0.080060% |
| | Dwelling Unit | 10 | 3 | 0.063231% | x 1 = | 0.063231% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 11 | 3 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 12 | 3 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 13 | 3 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 14 | 3 | 0.071596% | x 1 = | 0.071596% |
| | Dwelling Unit | 15 | 3 | 0.107742% | x 1 = | 0.107742% |
| | Dwelling Unit | 16 | 3 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 17 | 3 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 18 | 3 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 19 | 3 | 0.085039% | x 1 = | 0.085039% |
| | Dwelling Unit | 20 | 3 | 0.083844% | x 1 = | 0.083844% |
| | Dwelling Unit | 21 | 3 | 0.086731% | x 1 = | 0.086731% |
| | Dwelling Unit | 22 | 3 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 23 | 3 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 24 | 3 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 25 | 3 | 0.061439% | x 1 = | 0.061439% |
| | Dwelling Unit | 26 | 3 | 0.058452% | x 1 = | 0.058452% |
| | Dwelling Unit | 27 | 3 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 28 | 3 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 29 | 3 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 30 | 3 | 0.104357% | x 1 = | 0.104357% |
| | Dwelling Unit | 31 | 3 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 32 | 3 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 33 | 3 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 34 | 3 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 35 | 3 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 36 | 3 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 37 | 3 | 0.094598% | x 1 = | 0.094598% |
| | Dwelling Unit | 38 | 3 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 39 | 3 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 40 | 3 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 41 | 3 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 42 | 3 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 43 | 3 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 44 | 3 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 45 | 3 | 0.126064% | x 1 = | 0.126064% |
| | Dwelling Unit | 46 | 3 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 4 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 4 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 4 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 4 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 4 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 4 | 0.101369% | x 1 = | 0.101369% |
| | Dwelling Unit | 7 | 4 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 4 | 0.095893% | x 1 = | 0.095893% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 9 | 4 | 0.080060% | x 1 = | 0.080060% |
| | Dwelling Unit | 10 | 4 | 0.063231% | x 1 = | 0.063231% |
| | Dwelling Unit | 11 | 4 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 12 | 4 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 13 | 4 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 14 | 4 | 0.071596% | x 1 = | 0.071596% |
| | Dwelling Unit | 15 | 4 | 0.107742% | x 1 = | 0.107742% |
| | Dwelling Unit | 16 | 4 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 17 | 4 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 18 | 4 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 19 | 4 | 0.085039% | x 1 = | 0.085039% |
| | Dwelling Unit | 20 | 4 | 0.083844% | x 1 = | 0.083844% |
| | Dwelling Unit | 21 | 4 | 0.086731% | x 1 = | 0.086731% |
| | Dwelling Unit | 22 | 4 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 23 | 4 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 24 | 4 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 25 | 4 | 0.061439% | x 1 = | 0.061439% |
| | Dwelling Unit | 26 | 4 | 0.058452% | x 1 = | 0.058452% |
| | Dwelling Unit | 27 | 4 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 28 | 4 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 29 | 4 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 30 | 4 | 0.092706% | x 1 = | 0.092706% |
| | Dwelling Unit | 31 | 4 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 32 | 4 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 33 | 4 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 34 | 4 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 35 | 4 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 36 | 4 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 37 | 4 | 0.094598% | x 1 = | 0.094598% |
| | Dwelling Unit | 38 | 4 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 39 | 4 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 40 | 4 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 41 | 4 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 42 | 4 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 43 | 4 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 44 | 4 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 45 | 4 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 46 | 4 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 5 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 5 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 5 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 5 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 5 | 0.076475% | x 1 = | 0.076475% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 6 | 5 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 5 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 5 | 0.095893% | x 1 = | 0.095893% |
| | Dwelling Unit | 9 | 5 | 0.080060% | x 1 = | 0.080060% |
| | Dwelling Unit | 10 | 5 | 0.063231% | x 1 = | 0.063231% |
| | Dwelling Unit | 11 | 5 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 12 | 5 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 13 | 5 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 14 | 5 | 0.071596% | x 1 = | 0.071596% |
| | Dwelling Unit | 15 | 5 | 0.107742% | x 1 = | 0.107742% |
| | Dwelling Unit | 16 | 5 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 17 | 5 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 18 | 5 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 19 | 5 | 0.085039% | x 1 = | 0.085039% |
| | Dwelling Unit | 20 | 5 | 0.083844% | x 1 = | 0.083844% |
| | Dwelling Unit | 21 | 5 | 0.086731% | x 1 = | 0.086731% |
| | Dwelling Unit | 22 | 5 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 23 | 5 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 24 | 5 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 25 | 5 | 0.061439% | x 1 = | 0.061439% |
| | Dwelling Unit | 26 | 5 | 0.058452% | x 1 = | 0.058452% |
| | Dwelling Unit | 27 | 5 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 28 | 5 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 29 | 5 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 30 | 5 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 31 | 5 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 32 | 5 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 33 | 5 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 34 | 5 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 35 | 5 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 36 | 5 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 37 | 5 | 0.119592% | x 1 = | 0.119592% |
| | Dwelling Unit | 38 | 5 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 39 | 5 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 40 | 5 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 41 | 5 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 42 | 5 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 43 | 5 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 44 | 5 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 45 | 5 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 46 | 5 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 6 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 6 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 6 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 6 | 0.104058% | x 1 = | 0.104058% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 5 | 6 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 6 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 6 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 6 | 0.095893% | x 1 = | 0.095893% |
| | Dwelling Unit | 9 | 6 | 0.080060% | x 1 = | 0.080060% |
| | Dwelling Unit | 10 | 6 | 0.063231% | x 1 = | 0.063231% |
| | Dwelling Unit | 11 | 6 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 12 | 6 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 13 | 6 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 14 | 6 | 0.071596% | x 1 = | 0.071596% |
| | Dwelling Unit | 15 | 6 | 0.107742% | x 1 = | 0.107742% |
| | Dwelling Unit | 16 | 6 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 17 | 6 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 18 | 6 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 19 | 6 | 0.085039% | x 1 = | 0.085039% |
| | Dwelling Unit | 20 | 6 | 0.083844% | x 1 = | 0.083844% |
| | Dwelling Unit | 21 | 6 | 0.086731% | x 1 = | 0.086731% |
| | Dwelling Unit | 22 | 6 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 23 | 6 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 24 | 6 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 25 | 6 | 0.061439% | x 1 = | 0.061439% |
| | Dwelling Unit | 26 | 6 | 0.058452% | x 1 = | 0.058452% |
| | Dwelling Unit | 27 | 6 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 28 | 6 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 29 | 6 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 30 | 6 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 31 | 6 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 32 | 6 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 33 | 6 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 34 | 6 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 35 | 6 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 36 | 6 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 37 | 6 | 0.119592% | x 1 = | 0.119592% |
| | Dwelling Unit | 38 | 6 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 39 | 6 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 40 | 6 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 41 | 6 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 42 | 6 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 43 | 6 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 44 | 6 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 45 | 6 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 46 | 6 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 7 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 7 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 7 | 0.056958% | x 1 = | 0.056958% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 4 | 7 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 7 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 7 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 7 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 7 | 0.095893% | x 1 = | 0.095893% |
| | Dwelling Unit | 9 | 7 | 0.080060% | x 1 = | 0.080060% |
| | Dwelling Unit | 10 | 7 | 0.063231% | x 1 = | 0.063231% |
| | Dwelling Unit | 11 | 7 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 12 | 7 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 13 | 7 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 14 | 7 | 0.071596% | x 1 = | 0.071596% |
| | Dwelling Unit | 15 | 7 | 0.107742% | x 1 = | 0.107742% |
| | Dwelling Unit | 16 | 7 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 17 | 7 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 18 | 7 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 19 | 7 | 0.085039% | x 1 = | 0.085039% |
| | Dwelling Unit | 20 | 7 | 0.083844% | x 1 = | 0.083844% |
| | Dwelling Unit | 21 | 7 | 0.086731% | x 1 = | 0.086731% |
| | Dwelling Unit | 22 | 7 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 23 | 7 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 24 | 7 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 25 | 7 | 0.061439% | x 1 = | 0.061439% |
| | Dwelling Unit | 26 | 7 | 0.058452% | x 1 = | 0.058452% |
| | Dwelling Unit | 27 | 7 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 28 | 7 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 29 | 7 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 30 | 7 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 31 | 7 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 32 | 7 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 33 | 7 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 34 | 7 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 35 | 7 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 36 | 7 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 37 | 7 | 0.119592% | x 1 = | 0.119592% |
| | Dwelling Unit | 38 | 7 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 39 | 7 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 40 | 7 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 41 | 7 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 42 | 7 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 43 | 7 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 44 | 7 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 45 | 7 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 46 | 7 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 8 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 8 | 0.055464% | x 1 = | 0.055464% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 3 | 8 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 8 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 8 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 8 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 8 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 8 | 0.095893% | x 1 = | 0.095893% |
| | Dwelling Unit | 9 | 8 | 0.080060% | x 1 = | 0.080060% |
| | Dwelling Unit | 10 | 8 | 0.063231% | x 1 = | 0.063231% |
| | Dwelling Unit | 11 | 8 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 12 | 8 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 13 | 8 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 14 | 8 | 0.071596% | x 1 = | 0.071596% |
| | Dwelling Unit | 15 | 8 | 0.107742% | x 1 = | 0.107742% |
| | Dwelling Unit | 16 | 8 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 17 | 8 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 18 | 8 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 19 | 8 | 0.085039% | x 1 = | 0.085039% |
| | Dwelling Unit | 20 | 8 | 0.083844% | x 1 = | 0.083844% |
| | Dwelling Unit | 21 | 8 | 0.086731% | x 1 = | 0.086731% |
| | Dwelling Unit | 22 | 8 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 23 | 8 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 24 | 8 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 25 | 8 | 0.061439% | x 1 = | 0.061439% |
| | Dwelling Unit | 26 | 8 | 0.058452% | x 1 = | 0.058452% |
| | Dwelling Unit | 27 | 8 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 28 | 8 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 29 | 8 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 30 | 8 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 31 | 8 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 32 | 8 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 33 | 8 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 34 | 8 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 35 | 8 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 36 | 8 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 37 | 8 | 0.119592% | x 1 = | 0.119592% |
| | Dwelling Unit | 38 | 8 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 39 | 8 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 40 | 8 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 41 | 8 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 42 | 8 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 43 | 8 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 44 | 8 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 45 | 8 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 46 | 8 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 9 | 0.105153% | x 1 = | 0.105153% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|---|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 2 | 9 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 9 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 9 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 9 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 9 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 9 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 9 | 0.095893% | x 1 = | 0.095893% |
| | Dwelling Unit | 9 | 9 | 0.080060% | x 1 = | 0.080060% |
| | Dwelling Unit | 10 | 9 | 0.063231% | x 1 = | 0.063231% |
| | Dwelling Unit | 11 | 9 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 12 | 9 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 13 | 9 | 0.064924% | x 1 = | 0.064924% |
| | Dwelling Unit | 14 | 9 | 0.071596% | x 1 = | 0.071596% |
| | Dwelling Unit | 15 | 9 | 0.107742% | x 1 = | 0.107742% |
| | Dwelling Unit | 16 | 9 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 17 | 9 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 18 | 9 | 0.071098% | x 1 = | 0.071098% |
| | Dwelling Unit | 19 | 9 | 0.085039% | x 1 = | 0.085039% |
| | Dwelling Unit | 20 | 9 | 0.083844% | x 1 = | 0.083844% |
| | Dwelling Unit | 21 | 9 | 0.086731% | x 1 = | 0.086731% |
| | Dwelling Unit | 22 | 9 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 23 | 9 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 24 | 9 | 0.063530% | x 1 = | 0.063530% |
| | Dwelling Unit | 25 | 9 | 0.061439% | x 1 = | 0.061439% |
| | Dwelling Unit | 26 | 9 | 0.058452% | x 1 = | 0.058452% |
| | Dwelling Unit | 27 | 9 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 28 | 9 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 29 | 9 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 30 | 9 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 31 | 9 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 32 | 9 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 33 | 9 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 34 | 9 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 35 | 9 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 36 | 9 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 37 | 9 | 0.119592% | x 1 = | 0.119592% |
| | Dwelling Unit | 38 | 9 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 39 | 9 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 40 | 9 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 41 | 9 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 42 | 9 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 43 | 9 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 44 | 9 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 45 | 9 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 46 | 9 | 0.069505% | x 1 = | 0.069505% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| Building C | Dwelling Unit | 1 | 10 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 10 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 10 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 10 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 10 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 10 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 10 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 10 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 10 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 10 | 10 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 11 | 10 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 12 | 10 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 13 | 10 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 14 | 10 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 15 | 10 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 16 | 10 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 17 | 10 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 18 | 10 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 19 | 10 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 20 | 10 | 0.119592% | x 1 = | 0.119592% |
| | Dwelling Unit | 21 | 10 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 22 | 10 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 23 | 10 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 24 | 10 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 25 | 10 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 26 | 10 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 10 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 28 | 10 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 29 | 10 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 11 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 11 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 11 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 11 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 11 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 11 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 11 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 11 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 11 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 10 | 11 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 11 | 11 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 12 | 11 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 13 | 11 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 14 | 11 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 15 | 11 | 0.102763% | x 1 = | 0.102763% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 16 | 11 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 17 | 11 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 18 | 11 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 19 | 11 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 20 | 11 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 21 | 11 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 22 | 11 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 23 | 11 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 24 | 11 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 25 | 11 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 26 | 11 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 11 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 28 | 11 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 29 | 11 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 12 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 12 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 12 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 12 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 12 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 12 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 12 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 12 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 12 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 10 | 12 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 11 | 12 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 12 | 12 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 13 | 12 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 14 | 12 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 15 | 12 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 16 | 12 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 17 | 12 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 18 | 12 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 19 | 12 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 20 | 12 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 21 | 12 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 22 | 12 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 23 | 12 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 24 | 12 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 25 | 12 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 26 | 12 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 12 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 28 | 12 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 29 | 12 | 0.069505% | x 1 = | 0.069505% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-----------|-----------|
| | | | | | | |
| Building C | Dwelling Unit | 1 | 13 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 13 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 13 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 13 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 13 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 13 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 13 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 13 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 13 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 10 | 13 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 11 | 13 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 12 | 13 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 13 | 13 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 14 | 13 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 15 | 13 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 16 | 13 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 17 | 13 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 18 | 13 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 19 | 13 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 20 | 13 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 21 | 13 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 22 | 13 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 23 | 13 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 24 | 13 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 25 | 13 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 26 | 13 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 13 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 28 | 13 | 0.101469% | x 1 = | 0.101469% |
| Dwelling Unit | 29 | 13 | 0.069505% | x 1 = | 0.069505% | |
| Building C | Dwelling Unit | 1 | 14 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 14 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 14 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 14 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 14 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 14 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 14 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 14 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 14 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 10 | 14 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 11 | 14 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 12 | 14 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 13 | 14 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 14 | 14 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 15 | 14 | 0.102763% | x 1 = | 0.102763% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 16 | 14 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 17 | 14 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 18 | 14 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 19 | 14 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 20 | 14 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 21 | 14 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 22 | 14 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 23 | 14 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 24 | 14 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 25 | 14 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 26 | 14 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 14 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 28 | 14 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 29 | 14 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 15 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 15 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 15 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 15 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 15 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 15 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 15 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 15 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 15 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 10 | 15 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 11 | 15 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 12 | 15 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 13 | 15 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 14 | 15 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 15 | 15 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 16 | 15 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 17 | 15 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 18 | 15 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 19 | 15 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 20 | 15 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 21 | 15 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 22 | 15 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 23 | 15 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 24 | 15 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 25 | 15 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 26 | 15 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 15 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 28 | 15 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 29 | 15 | 0.069505% | x 1 = | 0.069505% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-----------|-----------|
| | | | | | | |
| Building C | Dwelling Unit | 1 | 16 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 16 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 16 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 16 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 16 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 16 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 16 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 16 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 16 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 10 | 16 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 11 | 16 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 12 | 16 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 13 | 16 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 14 | 16 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 15 | 16 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 16 | 16 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 17 | 16 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 18 | 16 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 19 | 16 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 20 | 16 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 21 | 16 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 22 | 16 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 23 | 16 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 24 | 16 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 25 | 16 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 26 | 16 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 16 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 28 | 16 | 0.101469% | x 1 = | 0.101469% |
| Dwelling Unit | 29 | 16 | 0.069505% | x 1 = | 0.069505% | |
| Building C | Dwelling Unit | 1 | 17 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 17 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 17 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 17 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 17 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 17 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 17 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 17 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 17 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 10 | 17 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 11 | 17 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 12 | 17 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 13 | 17 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 14 | 17 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 15 | 17 | 0.102763% | x 1 = | 0.102763% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 16 | 17 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 17 | 17 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 18 | 17 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 19 | 17 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 20 | 17 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 21 | 17 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 22 | 17 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 23 | 17 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 24 | 17 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 25 | 17 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 26 | 17 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 17 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 28 | 17 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 29 | 17 | 0.069505% | x 1 = | 0.069505% |
| Building C | Dwelling Unit | 1 | 18 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 18 | 0.055464% | x 1 = | 0.055464% |
| | Dwelling Unit | 3 | 18 | 0.056958% | x 1 = | 0.056958% |
| | Dwelling Unit | 4 | 18 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 5 | 18 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 6 | 18 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 7 | 18 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 8 | 18 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 18 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 10 | 18 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 11 | 18 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 12 | 18 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 13 | 18 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 14 | 18 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 15 | 18 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 16 | 18 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 17 | 18 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 18 | 18 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 19 | 18 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 20 | 18 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 21 | 18 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 22 | 18 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 23 | 18 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 24 | 18 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 25 | 18 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 26 | 18 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 18 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 28 | 18 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 29 | 18 | 0.069505% | x 1 = | 0.069505% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| Building C | Dwelling Unit | 1 | 19 | 0.105153% | x 1 = | 0.105153% |
| | Dwelling Unit | 2 | 19 | 0.111825% | x 1 = | 0.111825% |
| | Dwelling Unit | 3 | 19 | 0.104058% | x 1 = | 0.104058% |
| | Dwelling Unit | 4 | 19 | 0.076475% | x 1 = | 0.076475% |
| | Dwelling Unit | 5 | 19 | 0.100473% | x 1 = | 0.100473% |
| | Dwelling Unit | 6 | 19 | 0.063928% | x 1 = | 0.063928% |
| | Dwelling Unit | 7 | 19 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 8 | 19 | 0.093403% | x 1 = | 0.093403% |
| | Dwelling Unit | 9 | 19 | 0.070899% | x 1 = | 0.070899% |
| Building B | Dwelling Unit | 10 | 19 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 11 | 19 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 12 | 19 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 13 | 19 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 14 | 19 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 15 | 19 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 16 | 19 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 17 | 19 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 18 | 19 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 19 | 19 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 20 | 19 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 21 | 19 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 22 | 19 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 23 | 19 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 24 | 19 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 25 | 19 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 26 | 19 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 27 | 19 | 0.101469% | x 1 = | 0.101469% |
| Building B | Dwelling Unit | 1 | 20 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 20 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 20 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 20 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 20 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 20 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 20 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 20 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 20 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 20 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 20 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 20 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 20 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 20 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 20 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 20 | 0.062236% | x 1 = | 0.062236% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 17 | 20 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 20 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 20 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 21 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 21 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 21 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 21 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 21 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 21 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 21 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 21 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 21 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 21 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 21 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 21 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 21 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 21 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 21 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 21 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 21 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 21 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 21 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 22 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 22 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 22 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 22 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 22 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 22 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 22 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 22 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 22 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 22 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 22 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 22 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 22 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 22 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 22 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 22 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 22 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 22 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 22 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 23 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 23 | 0.070102% | x 1 = | 0.070102% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 3 | 23 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 23 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 23 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 23 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 23 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 23 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 23 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 23 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 23 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 23 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 23 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 23 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 23 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 23 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 23 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 23 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 23 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 24 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 24 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 24 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 24 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 24 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 24 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 24 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 24 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 24 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 24 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 24 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 24 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 24 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 24 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 24 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 24 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 24 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 24 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 24 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 25 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 25 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 25 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 25 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 25 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 25 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 25 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 25 | 0.079661% | x 1 = | 0.079661% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|-------------------|---------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Dwelling Unit | 9 | 25 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 25 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 25 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 25 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 25 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 25 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 25 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 25 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 25 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 25 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 25 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 26 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 26 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 26 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 26 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 26 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 26 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 26 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 26 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 26 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 26 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 26 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 26 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 26 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 26 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 26 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 26 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 26 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 26 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 26 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 27 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 27 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 27 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 27 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 27 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 27 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 27 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 27 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 27 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 27 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 27 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 27 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 27 | 0.107644% | x 1 = | 0.107644% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 14 | 27 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 27 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 27 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 27 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 27 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 27 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 28 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 28 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 28 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 28 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 28 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 28 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 28 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 28 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 28 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 28 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 28 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 28 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 28 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 28 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 28 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 28 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 28 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 28 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 28 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 29 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 29 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 29 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 29 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 29 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 29 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 29 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 29 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 29 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 29 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 29 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 29 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 29 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 29 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 29 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 29 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 29 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 29 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 29 | 0.069505% | x 1 = | 0.069505% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|---|-----------|-----------|
| | | | | | | |
| Building B | Dwelling Unit | 1 | 30 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 30 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 30 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 30 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 30 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 30 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 30 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 30 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 30 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 30 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 30 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 30 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 30 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 30 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 30 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 30 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 30 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 30 | 0.101469% | x 1 = | 0.101469% |
| Dwelling Unit | 19 | 30 | 0.069505% | x 1 = | 0.069505% | |
| Building B | Dwelling Unit | 1 | 31 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 31 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 31 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 31 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 31 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 31 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 31 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 31 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 31 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 31 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 31 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 31 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 31 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 31 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 31 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 31 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 31 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 31 | 0.101469% | x 1 = | 0.101469% |
| Dwelling Unit | 19 | 31 | 0.069505% | x 1 = | 0.069505% | |
| Building B | Dwelling Unit | 1 | 32 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 32 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 32 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 32 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 32 | 0.102763% | x 1 = | 0.102763% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 6 | 32 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 32 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 32 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 32 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 32 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 32 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 32 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 32 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 32 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 32 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 32 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 32 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 32 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 32 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 33 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 33 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 33 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 33 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 33 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 33 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 33 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 33 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 33 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 33 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 33 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 33 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 33 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 33 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 33 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 33 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 33 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 33 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 33 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 34 | 0.064625% | x 1 = | 0.064625% |
| | Dwelling Unit | 2 | 34 | 0.070102% | x 1 = | 0.070102% |
| | Dwelling Unit | 3 | 34 | 0.104954% | x 1 = | 0.104954% |
| | Dwelling Unit | 4 | 34 | 0.102564% | x 1 = | 0.102564% |
| | Dwelling Unit | 5 | 34 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 6 | 34 | 0.067812% | x 1 = | 0.067812% |
| | Dwelling Unit | 7 | 34 | 0.102763% | x 1 = | 0.102763% |
| | Dwelling Unit | 8 | 34 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 9 | 34 | 0.064028% | x 1 = | 0.064028% |
| Building A | Dwelling Unit | 10 | 34 | 0.119593% | x 1 = | 0.119593% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 11 | 34 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 34 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 34 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 34 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 34 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 34 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 34 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 34 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 34 | 0.069505% | x 1 = | 0.069505% |
| Building B | Dwelling Unit | 1 | 35 | 0.140503% | x 1 = | 0.140503% |
| | Dwelling Unit | 2 | 35 | 0.135922% | x 1 = | 0.135922% |
| | Dwelling Unit | 3 | 35 | 0.159821% | x 1 = | 0.159821% |
| | Dwelling Unit | 4 | 35 | 0.189594% | x 1 = | 0.189594% |
| | Dwelling Unit | 5 | 35 | 0.190988% | x 1 = | 0.190988% |
| | Dwelling Unit | 6 | 35 | 0.165298% | x 1 = | 0.165298% |
| | Dwelling Unit | 7 | 35 | 0.186707% | x 1 = | 0.186707% |
| | Dwelling Unit | 8 | 35 | 0.156236% | x 1 = | 0.156236% |
| | Dwelling Unit | 9 | 35 | 0.132437% | x 1 = | 0.132437% |
| Building A | Dwelling Unit | 10 | 35 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 11 | 35 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 12 | 35 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 13 | 35 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 14 | 35 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 15 | 35 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 16 | 35 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 17 | 35 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 18 | 35 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 19 | 35 | 0.069505% | x 1 = | 0.069505% |
| Building A | Dwelling Unit | 1 | 36 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 2 | 36 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 3 | 36 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 4 | 36 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 5 | 36 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 6 | 36 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 7 | 36 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 8 | 36 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 36 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 10 | 36 | 0.069505% | x 1 = | 0.069505% |
| Building A | Dwelling Unit | 1 | 37 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 2 | 37 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 3 | 37 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 4 | 37 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 5 | 37 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 6 | 37 | 0.113419% | x 1 = | 0.113419% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|-------------------|---------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 7 | 37 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 8 | 37 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 37 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 10 | 37 | 0.069505% | x 1 = | 0.069505% |
| Building A | Dwelling Unit | 1 | 38 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 2 | 38 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 3 | 38 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 4 | 38 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 5 | 38 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 6 | 38 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 7 | 38 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 8 | 38 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 38 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 10 | 38 | 0.069505% | x 1 = | 0.069505% |
| Building A | Dwelling Unit | 1 | 39 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 2 | 39 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 3 | 39 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 4 | 39 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 5 | 39 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 6 | 39 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 7 | 39 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 8 | 39 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 39 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 10 | 39 | 0.069505% | x 1 = | 0.069505% |
| Building A | Dwelling Unit | 1 | 40 | 0.119593% | x 1 = | 0.119593% |
| | Dwelling Unit | 2 | 40 | 0.073886% | x 1 = | 0.073886% |
| | Dwelling Unit | 3 | 40 | 0.072193% | x 1 = | 0.072193% |
| | Dwelling Unit | 4 | 40 | 0.107644% | x 1 = | 0.107644% |
| | Dwelling Unit | 5 | 40 | 0.079661% | x 1 = | 0.079661% |
| | Dwelling Unit | 6 | 40 | 0.113419% | x 1 = | 0.113419% |
| | Dwelling Unit | 7 | 40 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 8 | 40 | 0.062236% | x 1 = | 0.062236% |
| | Dwelling Unit | 9 | 40 | 0.101469% | x 1 = | 0.101469% |
| | Dwelling Unit | 10 | 40 | 0.069505% | x 1 = | 0.069505% |
| Building A | Dwelling Unit | 1 | 41 | 0.160220% | x 1 = | 0.160220% |
| | Dwelling Unit | 2 | 41 | 0.136620% | x 1 = | 0.136620% |
| | Dwelling Unit | 3 | 41 | 0.166891% | x 1 = | 0.166891% |
| | Dwelling Unit | 4 | 41 | 0.130346% | x 1 = | 0.130346% |
| | Dwelling Unit | 5 | 41 | 0.124770% | x 1 = | 0.124770% |
| | Dwelling Unit | 6 | 41 | 0.128554% | x 1 = | 0.128554% |
| Building A | Dwelling Unit | 1 | 42 | 0.296840% | x 1 = | 0.296840% |
| | Dwelling Unit | 2 | 42 | 0.166891% | x 1 = | 0.166891% |
| | Dwelling Unit | 3 | 42 | 0.130346% | x 1 = | 0.130346% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|------------------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Dwelling Unit | 4 | 42 | 0.124770% | x 1 = | 0.124770% |
| | Dwelling Unit | 5 | 42 | 0.128554% | x 1 = | 0.128554% |
| | Parking Unit (Tandem) | 1 | A | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit (Tandem) | 2 | A | 0.010422% | x 1 = | 0.010422% |
| | Parking/Locker Unit (Tandem) | 3 | A | 0.010422% | x 1 = | 0.010422% |
| | Parking/Locker Unit (Tandem) | 4 | A | 0.010422% | x 1 = | 0.010422% |
| | Parking/Locker Unit (Tandem) | 5 | A | 0.010422% | x 1 = | 0.010422% |
| | Parking/Locker Unit (Tandem) | 6 | A | 0.010422% | x 1 = | 0.010422% |
| | Parking/Locker Unit (Tandem) | 7 | A | 0.010422% | x 1 = | 0.010422% |
| | Parking Unit (Tandem) | 8 | A | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 9 | A | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 10 | A | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 11 | A | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 12 | A | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 13 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 14 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 15 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 16 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 17 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 18 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 19 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 20 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 21 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 22 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 23 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 24 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 25 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 26 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 27 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 28 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 29 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 30 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 31 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 32 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 33 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 34 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 35 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 36 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 37 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 38 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 39 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 40 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 41 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 42 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 43 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 44 | A | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 45 | A | 0.009263% | x 1 = | 0.009263% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|--------------------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit (Tandem) | 46 | A | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 47 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 48 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 49 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 50 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 51 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 52 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 53 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 54 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 55 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 56 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 57 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 58 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 59 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 60 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 61 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 62 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 63 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 64 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 65 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 66 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 67 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 68 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 69 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 70 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 71 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 72 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 73 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 74 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 75 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 76 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 77 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 78 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Parking Unit | 79 | A | 0.008104% | x 1 = | 0.008104% |
| | Commercial/Retail Storage Unit | 80 | A | 0.004631% | x 1 = | 0.004631% |
| | Commercial/Retail Storage Unit | 81 | A | 0.004631% | x 1 = | 0.004631% |
| | Commercial/Retail Storage Unit | 82 | A | 0.004631% | x 1 = | 0.004631% |
| | Commercial/Retail Storage Unit | 83 | A | 0.004631% | x 1 = | 0.004631% |
| | Commercial/Retail Storage Unit | 84 | A | 0.004631% | x 1 = | 0.004631% |
| | Commercial/Retail Storage Unit | 85 | A | 0.004631% | x 1 = | 0.004631% |
| | Commercial/Retail Storage Unit | 86 | A | 0.004631% | x 1 = | 0.004631% |
| | Locker Unit | 87 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 88 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 89 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 90 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 91 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 92 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 93 | A | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Locker Unit | 94 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 95 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 96 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 97 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 98 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 99 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 100 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 101 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 102 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 103 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 104 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 105 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 106 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 107 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 108 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 109 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 110 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 111 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 112 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 113 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 114 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 115 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 116 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 117 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 118 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 119 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 120 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 121 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 122 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 123 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 124 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 125 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 126 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 127 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 128 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 129 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 130 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 131 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 132 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 133 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 134 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 135 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 136 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 137 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 138 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 139 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 140 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 141 | A | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-------------|----------|-----------|---|-------|-----------|
| | | | | | | |
| | Locker Unit | 142 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 143 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 144 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 145 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 146 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 147 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 148 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 149 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 150 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 151 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 152 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 153 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 154 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 155 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 156 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 157 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 158 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 159 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 160 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 161 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 162 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 163 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 164 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 165 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 166 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 167 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 168 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 169 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 170 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 171 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 172 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 173 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 174 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 175 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 176 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 177 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 178 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 179 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 180 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 181 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 182 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 183 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 184 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 185 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 186 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 187 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 188 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 189 | A | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 190 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 191 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 192 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 193 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 194 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 195 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 196 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 197 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 198 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 199 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 200 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 201 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 202 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 203 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 204 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 205 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 206 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 207 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 208 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 209 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 210 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 211 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 212 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 213 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 214 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 215 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 216 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 217 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 218 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 219 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 220 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 221 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 222 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 223 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 224 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 225 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 226 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 227 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 228 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 229 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 230 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 231 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 232 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 233 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 234 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 235 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 236 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 237 | A | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|--------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 238 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 239 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 240 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 241 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 242 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 243 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 244 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 245 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 246 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 247 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 248 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 249 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 250 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 251 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 252 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 253 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 254 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 255 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 256 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 257 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 258 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 259 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 260 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 261 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 262 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 263 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 264 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 265 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 266 | A | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 267 | A | 0.001853% | x 1 = | 0.001853% |
| | Parking Unit | 268 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 269 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 270 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 271 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 272 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 273 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 274 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 275 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 276 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 277 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 278 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 279 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 280 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 281 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 282 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 283 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 284 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 285 | A | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|--------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 286 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 287 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 288 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 289 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 290 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 291 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 292 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 293 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 294 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 295 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 296 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 297 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 298 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 299 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 300 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 301 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 302 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 303 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 304 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 305 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 306 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 307 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 308 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 309 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 310 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 311 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 312 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 313 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 314 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 315 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 316 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 317 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 318 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 319 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 320 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 321 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 322 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 323 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 324 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 325 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 326 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 327 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 328 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 329 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 330 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 331 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 332 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 333 | A | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-----------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 334 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 335 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 336 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 337 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 338 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 339 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 340 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 341 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 342 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 343 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 344 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 345 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 346 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 347 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 348 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 349 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 350 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 351 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 352 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 353 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 354 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 355 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 356 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 357 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 358 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 359 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 360 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 361 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 362 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 363 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 364 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 365 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 366 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 367 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 368 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 369 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 370 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 371 | A | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 1 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 2 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 3 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 4 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 5 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 6 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 7 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 8 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 9 | B | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|------------------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 10 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 11 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 12 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 13 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 14 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 15 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 16 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 17 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 18 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 19 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 20 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking/Locker Unit (Tandem) | 21 | B | 0.010422% | x 1 = | 0.010422% |
| | Parking Unit (Tandem) | 22 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 23 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 24 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 25 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 26 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 27 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 28 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 29 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 30 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 31 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 32 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 33 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 34 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 35 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 36 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 37 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 38 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 39 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 40 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 41 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 42 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 43 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 44 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 45 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 46 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 47 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 48 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 49 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 50 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 51 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 52 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 53 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 54 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 55 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 56 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 57 | B | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-----------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 58 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 59 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 60 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 61 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 62 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 63 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 64 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 65 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 66 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 67 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 68 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 69 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 70 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 71 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 72 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 73 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 74 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 75 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 76 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 77 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 78 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 79 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 80 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 81 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 82 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 83 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 84 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 85 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 86 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 87 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 88 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 89 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 90 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 91 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 92 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 93 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 94 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 95 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 96 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 97 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 98 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 99 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 100 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 101 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 102 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 103 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 104 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 105 | B | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|--------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 106 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 107 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 108 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 109 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 110 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 111 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 112 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 113 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 114 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 115 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 116 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 117 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 118 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 119 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 120 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 121 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 122 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 123 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 124 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 125 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 126 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 127 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 128 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 129 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 130 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 131 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 132 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 133 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 134 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 135 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 136 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 137 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 138 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 139 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 140 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 141 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 142 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 143 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 144 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 145 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 146 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 147 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 148 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 149 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 150 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 151 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 152 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 153 | B | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-----------------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 154 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 155 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 156 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 157 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 158 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 159 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 160 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 161 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 162 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 163 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 164 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 165 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 166 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking/Locker Unit | 167 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 168 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 169 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 170 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 171 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 172 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 173 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 174 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 175 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 176 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 177 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 178 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 179 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 180 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 181 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 182 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 183 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 184 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 185 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 186 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 187 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 188 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 189 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 190 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 191 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 192 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 193 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 194 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 195 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 196 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 197 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 198 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 199 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 200 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 201 | B | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|--------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 202 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 203 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 204 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 205 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 206 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 207 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 208 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 209 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 210 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 211 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 212 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 213 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 214 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 215 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 216 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 217 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 218 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 219 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 220 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 221 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 222 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 223 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 224 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 225 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 226 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 227 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 228 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 229 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 230 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 231 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 232 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 233 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 234 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 235 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 236 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 237 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 238 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 239 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 240 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 241 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 242 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 243 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 244 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 245 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 246 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 247 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 248 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 249 | B | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-----------------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 250 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 251 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 252 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 253 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 254 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 255 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 256 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 257 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 258 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 259 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 260 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 261 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 262 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 263 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 264 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 265 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 266 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 267 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 268 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 269 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 270 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 271 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 272 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 273 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 274 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 275 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 276 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 277 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 278 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 279 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 280 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 281 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 282 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 283 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 284 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 285 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 286 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 287 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 288 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 289 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 290 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 291 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 292 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 293 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 294 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 295 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 296 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 297 | B | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-----------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 298 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 299 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 300 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 301 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 302 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 303 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 304 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 305 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 306 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 307 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 308 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 309 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 310 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 311 | B | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 312 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 313 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 314 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 315 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 316 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 317 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 318 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 319 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 320 | B | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 321 | B | 0.008104% | x 1 = | 0.008104% |
| | Locker Unit | 322 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 323 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 324 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 325 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 326 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 327 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 328 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 329 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 330 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 331 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 332 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 333 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 334 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 335 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 336 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 337 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 338 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 339 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 340 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 341 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 342 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 343 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 344 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 345 | B | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 346 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 347 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 348 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 349 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 350 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 351 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 352 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 353 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 354 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 355 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 356 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 357 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 358 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 359 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 360 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 361 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 362 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 363 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 364 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 365 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 366 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 367 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 368 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 369 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 370 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 371 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 372 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 373 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 374 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 375 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 376 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 377 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 378 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 379 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 380 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 381 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 382 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 383 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 384 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 385 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 386 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 387 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 388 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 389 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 390 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 391 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 392 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 393 | B | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-------------|----------|-----------|--|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 394 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 395 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 396 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 397 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 398 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 399 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 400 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 401 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 402 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 403 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 404 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 405 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 406 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 407 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 408 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 409 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 410 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 411 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 412 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 413 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 414 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 415 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 416 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 417 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 418 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 419 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 420 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 421 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 422 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 423 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 424 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 425 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 426 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 427 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 428 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 429 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 430 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 431 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 432 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 433 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 434 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 435 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 436 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 437 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 438 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 439 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 440 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 441 | B | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Locker Unit | 442 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 443 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 444 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 445 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 446 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 447 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 448 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 449 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 450 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 451 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 452 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 453 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 454 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 455 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 456 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 457 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 458 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 459 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 460 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 461 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 462 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 463 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 464 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 465 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 466 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 467 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 468 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 469 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 470 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 471 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 472 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 473 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 474 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 475 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 476 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 477 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 478 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 479 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 480 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 481 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 482 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 483 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 484 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 485 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 486 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 487 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 488 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 489 | B | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 490 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 491 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 492 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 493 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 494 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 495 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 496 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 497 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 498 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 499 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 500 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 501 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 502 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 503 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 504 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 505 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 506 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 507 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 508 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 509 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 510 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 511 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 512 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 513 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 514 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 515 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 516 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 517 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 518 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 519 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 520 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 521 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 522 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 523 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 524 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 525 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 526 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 527 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 528 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 529 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 530 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 531 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 532 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 533 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 534 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 535 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 536 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 537 | B | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Locker Unit | 538 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 539 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 540 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 541 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 542 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 543 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 544 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 545 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 546 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 547 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 548 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 549 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 550 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 551 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 552 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 553 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 554 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 555 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 556 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 557 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 558 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 559 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 560 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 561 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 562 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 563 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 564 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 565 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 566 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 567 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 568 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 569 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 570 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 571 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 572 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 573 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 574 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 575 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 576 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 577 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 578 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 579 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 580 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 581 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 582 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 583 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 584 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 585 | B | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|------------------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Locker Unit | 586 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 587 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 588 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 589 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 590 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 591 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 592 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 593 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 594 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 595 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 596 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 597 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 598 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 599 | B | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 600 | B | 0.001853% | x 1 = | 0.001853% |
| | Parking Unit | 1 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 2 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 3 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 4 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 5 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 6 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 7 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 8 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 9 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 10 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 11 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 12 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 13 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 14 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 15 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 16 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 17 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 18 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 19 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 20 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking/Locker Unit (Tandem) | 21 | C | 0.010422% | x 1 = | 0.010422% |
| | Parking Unit (Tandem) | 22 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 23 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 24 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 25 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 26 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 27 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 28 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 29 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 30 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 31 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 32 | C | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|--------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 33 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 34 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 35 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 36 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 37 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 38 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 39 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 40 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 41 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 42 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 43 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 44 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 45 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 46 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 47 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 48 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 49 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 50 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 51 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 52 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 53 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 54 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 55 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 56 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 57 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 58 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 59 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 60 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 61 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 62 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 63 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 64 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 65 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 66 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 67 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 68 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 69 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 70 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 71 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 72 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 73 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 74 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 75 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 76 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 77 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 78 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 79 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 80 | C | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-----------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 81 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 82 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 83 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 84 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 85 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 86 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 87 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 88 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 89 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 90 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 91 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 92 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 93 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 94 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 95 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 96 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 97 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 98 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 99 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 100 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 101 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 102 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 103 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 104 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 105 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 106 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 107 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 108 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 109 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 110 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 111 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 112 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 113 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 114 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 115 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 116 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 117 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 118 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 119 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 120 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 121 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 122 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 123 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 124 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 125 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 126 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 127 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 128 | C | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|---------------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 129 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 130 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 131 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 132 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 133 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 134 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 135 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 136 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 137 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 138 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 139 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 140 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 141 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 142 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 143 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 144 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 145 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 146 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 147 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 148 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 149 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 150 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 151 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 152 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 153 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 154 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 155 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 156 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 157 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 158 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 159 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 160 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 161 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 162 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 163 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 164 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 165 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 166 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 167 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking/Locker Unit | 168 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 169 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 170 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 171 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 172 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 173 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 174 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 175 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 176 | C | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-----------------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 177 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 178 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 179 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 180 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 181 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 182 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 183 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 184 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 185 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 186 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 187 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 188 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 189 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 190 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 191 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 192 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 193 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 194 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 195 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 196 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 197 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 198 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 199 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 200 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 201 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 202 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 203 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 204 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 205 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 206 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 207 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 208 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 209 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 210 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 211 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 212 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 213 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 214 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 215 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 216 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 217 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 218 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 219 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 220 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 221 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 222 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 223 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 224 | C | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-----------------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 225 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 226 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 227 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 228 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 229 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 230 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 231 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 232 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 233 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 234 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 235 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 236 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 237 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 238 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 239 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 240 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 241 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 242 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 243 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 244 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 245 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 246 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 247 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 248 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 249 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 250 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 251 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 252 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 253 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 254 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 255 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 256 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 257 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 258 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 259 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 260 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 261 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 262 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 263 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 264 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 265 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 266 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 267 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 268 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 269 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 270 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 271 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 272 | C | 0.009263% | x 1 = | 0.009263% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-----------------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit (Tandem) | 273 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 274 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 275 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 276 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 277 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 278 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 279 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 280 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 281 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 282 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 283 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 284 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 285 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 286 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 287 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 288 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 289 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 290 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 291 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 292 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 293 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 294 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 295 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 296 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 297 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 298 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 299 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 300 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 301 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 302 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 303 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 304 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 305 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 306 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 307 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 308 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 309 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 310 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 311 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 312 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 313 | C | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 314 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 315 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 316 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 317 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 318 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 319 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 320 | C | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|--------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 321 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 322 | C | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 323 | C | 0.008104% | x 1 = | 0.008104% |
| | Locker Unit | 324 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 325 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 326 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 327 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 328 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 329 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 330 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 331 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 332 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 333 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 334 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 335 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 336 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 337 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 338 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 339 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 340 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 341 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 342 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 343 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 344 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 345 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 346 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 347 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 348 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 349 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 350 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 351 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 352 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 353 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 354 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 355 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 356 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 357 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 358 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 359 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 360 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 361 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 362 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 363 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 364 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 365 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 366 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 367 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 368 | C | 0.001853% | x 1 = | 0.001853% |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D**

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Locker Unit | 369 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 370 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 371 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 372 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 373 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 374 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 375 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 376 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 377 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 378 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 379 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 380 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 381 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 382 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 383 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 384 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 385 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 386 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 387 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 388 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 389 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 390 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 391 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 392 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 393 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 394 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 395 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 396 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 397 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 398 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 399 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 400 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 401 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 402 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 403 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 404 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 405 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 406 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 407 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 408 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 409 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 410 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 411 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 412 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 413 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 414 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 415 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 416 | C | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 417 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 418 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 419 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 420 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 421 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 422 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 423 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 424 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 425 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 426 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 427 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 428 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 429 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 430 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 431 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 432 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 433 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 434 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 435 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 436 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 437 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 438 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 439 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 440 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 441 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 442 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 443 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 444 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 445 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 446 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 447 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 448 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 449 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 450 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 451 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 452 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 453 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 454 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 455 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 456 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 457 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 458 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 459 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 460 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 461 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 462 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 463 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 464 | C | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 465 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 466 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 467 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 468 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 469 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 470 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 471 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 472 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 473 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 474 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 475 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 476 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 477 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 478 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 479 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 480 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 481 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 482 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 483 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 484 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 485 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 486 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 487 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 488 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 489 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 490 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 491 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 492 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 493 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 494 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 495 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 496 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 497 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 498 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 499 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 500 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 501 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 502 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 503 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 504 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 505 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 506 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 507 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 508 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 509 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 510 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 511 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 512 | C | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-------------|----------|-----------|--|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 513 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 514 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 515 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 516 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 517 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 518 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 519 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 520 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 521 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 522 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 523 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 524 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 525 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 526 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 527 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 528 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 529 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 530 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 531 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 532 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 533 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 534 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 535 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 536 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 537 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 538 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 539 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 540 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 541 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 542 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 543 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 544 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 545 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 546 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 547 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 548 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 549 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 550 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 551 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 552 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 553 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 554 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 555 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 556 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 557 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 558 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 559 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 560 | C | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-----------------------|----------|-----------|--|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 561 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 562 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 563 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 564 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 565 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 566 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 567 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 568 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 569 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 570 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 571 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 572 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 573 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 574 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 575 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 576 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 577 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 578 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 579 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 580 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 581 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 582 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 583 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 584 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 585 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 586 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 587 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 588 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 589 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 590 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 591 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 592 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 593 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 594 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 595 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 596 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 597 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 598 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 599 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 600 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 601 | C | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 602 | C | 0.001853% | x 1 = | 0.001853% |
| | Parking Unit | 1 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 2 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 3 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 4 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 5 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 6 | D | 0.009263% | x 1 = | 0.009263% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|------------------------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit (Tandem) | 7 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 8 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 9 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 10 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 11 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 12 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 13 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 14 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 15 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 16 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 17 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 18 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 19 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 20 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking/Locker Unit (Tandem) | 21 | D | 0.010422% | x 1 = | 0.010422% |
| | Parking Unit (Tandem) | 22 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 23 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 24 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 25 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 26 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 27 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 28 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 29 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 30 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 31 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 32 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 33 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 34 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 35 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 36 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 37 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 38 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 39 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 40 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 41 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 42 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 43 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 44 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 45 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 46 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 47 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 48 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 49 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 50 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 51 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 52 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 53 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 54 | D | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-----------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 55 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 56 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 57 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 58 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 59 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 60 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 61 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 62 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 63 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 64 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 65 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 66 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 67 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 68 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 69 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 70 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 71 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 72 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 73 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 74 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 75 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 76 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 77 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 78 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 79 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 80 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 81 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 82 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 83 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 84 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 85 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 86 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 87 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 88 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 89 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 90 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 91 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 92 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 93 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 94 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 95 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 96 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 97 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 98 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 99 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 100 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 101 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 102 | D | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|--------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 103 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 104 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 105 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 106 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 107 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 108 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 109 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 110 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 111 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 112 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 113 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 114 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 115 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 116 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 117 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 118 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 119 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 120 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 121 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 122 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 123 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 124 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 125 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 126 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 127 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 128 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 129 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 130 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 131 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 132 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 133 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 134 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 135 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 136 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 137 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 138 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 139 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 140 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 141 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 142 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 143 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 144 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 145 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 146 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 147 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 148 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 149 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 150 | D | 0.008104% | x 1 = | 0.008104% |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D**

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-----------------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 151 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 152 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 153 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 154 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 155 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 156 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 157 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 158 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 159 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 160 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 161 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 162 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 163 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 164 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 165 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 166 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 167 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking/Locker Unit | 168 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 169 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 170 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 171 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 172 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking/Locker Unit | 173 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 174 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 175 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 176 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 177 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 178 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 179 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 180 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 181 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 182 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 183 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 184 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 185 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 186 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 187 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 188 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 189 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 190 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 191 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 192 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 193 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 194 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 195 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 196 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 197 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 198 | D | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|--------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Parking Unit | 199 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 200 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 201 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 202 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 203 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 204 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 205 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 206 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 207 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 208 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 209 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 210 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 211 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 212 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 213 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 214 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 215 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 216 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 217 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 218 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 219 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 220 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 221 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 222 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 223 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 224 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 225 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 226 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 227 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 228 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 229 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 230 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 231 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 232 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 233 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 234 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 235 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 236 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 237 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 238 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 239 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 240 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 241 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 242 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 243 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 244 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 245 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 246 | D | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-----------------------|----------|-----------|---|-------|-----------|
| | | | | | | |
| | Parking Unit | 247 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 248 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 249 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 250 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 251 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 252 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 253 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 254 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 255 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 256 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 257 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 258 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 259 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 260 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 261 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 262 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 263 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 264 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 265 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 266 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 267 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 268 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 269 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 270 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 271 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 272 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 273 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 274 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 275 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 276 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 277 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 278 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 279 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 280 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 281 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 282 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 283 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 284 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 285 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 286 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 287 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 288 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 289 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 290 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 291 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 292 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 293 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 294 | D | 0.008104% | x 1 = | 0.008104% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-----------------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Parking Unit | 295 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 296 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 297 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 298 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 299 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 300 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 301 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 302 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 303 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 304 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 305 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 306 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 307 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 308 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 309 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 310 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit (Tandem) | 311 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 312 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 313 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 314 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit (Tandem) | 315 | D | 0.009263% | x 1 = | 0.009263% |
| | Parking Unit | 316 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 317 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 318 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 319 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 320 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 321 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 322 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 323 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 324 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 325 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 326 | D | 0.008104% | x 1 = | 0.008104% |
| | Parking Unit | 327 | D | 0.008104% | x 1 = | 0.008104% |
| | Locker Unit | 328 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 329 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 330 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 331 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 332 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 333 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 334 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 335 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 336 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 337 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 338 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 339 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 340 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 341 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 342 | D | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-------------|----------|-----------|---|-------|-----------|
| | | | | | | |
| | Locker Unit | 343 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 344 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 345 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 346 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 347 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 348 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 349 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 350 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 351 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 352 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 353 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 354 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 355 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 356 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 357 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 358 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 359 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 360 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 361 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 362 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 363 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 364 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 365 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 366 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 367 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 368 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 369 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 370 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 371 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 372 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 373 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 374 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 375 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 376 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 377 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 378 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 379 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 380 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 381 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 382 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 383 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 384 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 385 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 386 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 387 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 388 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 389 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 390 | D | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Locker Unit | 391 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 392 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 393 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 394 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 395 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 396 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 397 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 398 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 399 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 400 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 401 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 402 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 403 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 404 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 405 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 406 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 407 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 408 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 409 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 410 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 411 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 412 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 413 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 414 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 415 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 416 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 417 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 418 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 419 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 420 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 421 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 422 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 423 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 424 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 425 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 426 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 427 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 428 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 429 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 430 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 431 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 432 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 433 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 434 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 435 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 436 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 437 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 438 | D | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-------------|----------|-----------|--|-------|-----------|
| | | | | | | |
| | Locker Unit | 439 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 440 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 441 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 442 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 443 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 444 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 445 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 446 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 447 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 448 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 449 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 450 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 451 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 452 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 453 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 454 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 455 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 456 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 457 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 458 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 459 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 460 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 461 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 462 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 463 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 464 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 465 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 466 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 467 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 468 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 469 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 470 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 471 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 472 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 473 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 474 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 475 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 476 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 477 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 478 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 479 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 480 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 481 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 482 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 483 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 484 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 485 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 486 | D | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 487 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 488 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 489 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 490 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 491 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 492 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 493 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 494 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 495 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 496 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 497 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 498 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 499 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 500 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 501 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 502 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 503 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 504 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 505 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 506 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 507 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 508 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 509 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 510 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 511 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 512 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 513 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 514 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 515 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 516 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 517 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 518 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 519 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 520 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 521 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 522 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 523 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 524 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 525 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 526 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 527 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 528 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 529 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 530 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 531 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 532 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 533 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 534 | D | 0.001853% | x 1 = | 0.001853% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses | | |
|----------|-------------|----------|-----------|---|-------|-----------|
| | | | | (expressed as percentages to each unit) | | |
| | Locker Unit | 535 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 536 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 537 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 538 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 539 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 540 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 541 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 542 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 543 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 544 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 545 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 546 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 547 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 548 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 549 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 550 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 551 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 552 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 553 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 554 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 555 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 556 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 557 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 558 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 559 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 560 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 561 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 562 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 563 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 564 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 565 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 566 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 567 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 568 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 569 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 570 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 571 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 572 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 573 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 574 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 575 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 576 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 577 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 578 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 579 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 580 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 581 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 582 | D | 0.001853% | x 1 = | 0.001853% |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule D**

| Building | Unit Type | Unit No. | Level No. | Proportion of Common Interests and Expenses (expressed as percentages to each unit) | | |
|----------|-------------|----------|-----------|--|-------|--------------------|
| | | | | | | |
| | Locker Unit | 583 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 584 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 585 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 586 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 587 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 588 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 589 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 590 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 591 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 592 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 593 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 594 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 595 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 596 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 597 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 598 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 599 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 600 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 601 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 602 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 603 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 604 | D | 0.001853% | x 1 = | 0.001853% |
| | Locker Unit | 605 | D | 0.001853% | x 1 = | 0.001853% |
| | | | | | | 100.000000% |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|------------------------|-------------------|-------------------------------------|-----------|--------------|----------|-----------|--|-----------------------------------|
| Building C | Dwelling Unit | 101 | C/2H | 877 | 1 | 1 | 0.087329% | \$403.97 |
| | Dwelling Unit | 102 | C/2J | 937 | 2 | 1 | 0.093304% | \$431.61 |
| | Dwelling Unit | 103 | C/2D | 809 | 3 | 1 | 0.080558% | \$372.65 |
| | Dwelling Unit | 105 | C/2D | 809 | 4 | 1 | 0.080558% | \$372.65 |
| | Dwelling Unit | 106 | C/2D | 809 | 5 | 1 | 0.080558% | \$372.65 |
| | Dwelling Unit | 107 | C/2M+D | 1,034 | 6 | 1 | 0.102962% | \$476.29 |
| | Dwelling Unit | 108 | C/1M+D | 843 | 7 | 1 | 0.083943% | \$388.31 |
| | Retail C | Commercial/Retail Unit | 3851 | 3851 | 2,240 | 8 | 1 | 0.223052% |
| Commercial/Retail Unit | | 3853 | 3853 | 1,270 | 9 | 1 | 0.126463% | \$585.00 |
| Commercial/Retail Unit | | 3855 | 3855 | 1,981 | 10 | 1 | 0.197262% | \$912.50 |
| Commercial/Retail Unit | | 3857 | 3857 | 1,367 | 11 | 1 | 0.136122% | \$629.68 |
| Commercial/Retail Unit | | 3859 | 3859 | 1,367 | 12 | 1 | 0.136122% | \$629.68 |
| Commercial/Retail Unit | | 3861 | 3861 | 1,367 | 13 | 1 | 0.136122% | \$629.68 |
| Commercial/Retail Unit | | 3863 | 3863 | 1,399 | 14 | 1 | 0.139308% | \$644.42 |
| Building B | Dwelling Unit | 101 | B/1E+D | 660 | 15 | 1 | 0.065721% | \$304.01 |
| | Dwelling Unit | 102 | B/2B+D | 873 | 16 | 1 | 0.086931% | \$402.13 |
| | Dwelling Unit | 103 | B/3B | 992 | 17 | 1 | 0.098780% | \$456.94 |
| Building A | Dwelling Unit | 101 | A/1H+D | 867 | 18 | 1 | 0.086333% | \$399.36 |
| | Dwelling Unit | 102 | A/1A+D | 677 | 19 | 1 | 0.067414% | \$311.85 |
| | Dwelling Unit | 103 | A/1B | 598 | 20 | 1 | 0.059547% | \$275.46 |
| | Dwelling Unit | 105 | A/3B | 1,130 | 21 | 1 | 0.112523% | \$520.51 |
| | Dwelling Unit | 106 | A/2D | 816 | 22 | 1 | 0.081255% | \$375.87 |
| | Dwelling Unit | 107 | A/1G+D | 825 | 23 | 1 | 0.082151% | \$380.02 |
| | Dwelling Unit | 108 | A/1F+D | 780 | 24 | 1 | 0.077670% | \$359.29 |
| | Dwelling Unit | 109 | A/3D+D | 1,240 | 25 | 1 | 0.123475% | \$571.18 |
| | Dwelling Unit | 110 | A/2G+D | 1,000 | 26 | 1 | 0.099577% | \$460.63 |
| | Building C | Commercial/Retail Garbage Room Unit | 101 | C/Garbage Ro | 0 | 27 | 1 | 0.000001% |
| Building C | Dwelling Unit | 201 | C/2P+D | 1,056 | 1 | 2 | 0.105153% | \$486.42 |
| | Dwelling Unit | 202 | C/1A | 557 | 2 | 2 | 0.055464% | \$256.57 |
| | Dwelling Unit | 203 | C/1B | 572 | 3 | 2 | 0.056958% | \$263.48 |
| | Dwelling Unit | 205 | C/2N+D BF | 1,045 | 4 | 2 | 0.104058% | \$481.36 |
| | Dwelling Unit | 206 | C/2B | 768 | 5 | 2 | 0.076475% | \$353.76 |
| | Dwelling Unit | 207 | C/3A | 1,009 | 6 | 2 | 0.100473% | \$464.77 |
| | Dwelling Unit | 208 | C/1H+D | 642 | 7 | 2 | 0.063928% | \$295.72 |
| | Dwelling Unit | 209 | C/2L+D | 963 | 8 | 2 | 0.095893% | \$443.59 |
| | Dwelling Unit | 210 | C/2C | 804 | 9 | 2 | 0.080060% | \$370.34 |
| | Dwelling Unit | 211 | C/1F+D | 635 | 10 | 2 | 0.063231% | \$292.50 |
| | Dwelling Unit | 212 | C/1J+D BF | 652 | 11 | 2 | 0.064924% | \$300.33 |
| | Dwelling Unit | 215 | C/1J+D BF | 652 | 12 | 2 | 0.064924% | \$300.33 |
| | Dwelling Unit | 216 | C/1J+D BF | 652 | 13 | 2 | 0.064924% | \$300.33 |
| | Dwelling Unit | 217 | C/2A | 719 | 14 | 2 | 0.071596% | \$331.19 |
| | Dwelling Unit | 218 | C/2Q+D | 1,082 | 15 | 2 | 0.107742% | \$498.40 |
| | Dwelling Unit | 219 | C/1L+D | 714 | 16 | 2 | 0.071098% | \$328.89 |
| | Dwelling Unit | 220 | C/1L+D | 714 | 17 | 2 | 0.071098% | \$328.89 |
| | Dwelling Unit | 221 | C/1L+D | 714 | 18 | 2 | 0.071098% | \$328.89 |
| | Dwelling Unit | 222 | C/2F | 854 | 19 | 2 | 0.085039% | \$393.38 |
| | Dwelling Unit | 223 | C/2E | 842 | 20 | 2 | 0.083844% | \$387.85 |
| | Dwelling Unit | 225 | C/2G | 871 | 21 | 2 | 0.086731% | \$401.20 |
| | Dwelling Unit | 226 | C/1G+D BF | 638 | 22 | 2 | 0.063530% | \$293.88 |
| | Dwelling Unit | 227 | C/1G+D BF | 638 | 23 | 2 | 0.063530% | \$293.88 |
| Dwelling Unit | 228 | C/1G+D BF | 638 | 24 | 2 | 0.063530% | \$293.88 | |
| Dwelling Unit | 229 | C/1D+D | 617 | 25 | 2 | 0.061439% | \$284.21 | |
| Dwelling Unit | 230 | C/1C+D | 587 | 26 | 2 | 0.058452% | \$270.39 | |
| Dwelling Unit | 231 | C/1K+D | 712 | 27 | 2 | 0.070899% | \$327.97 | |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment | |
|-------------------|-------------------|---------------|-----------|---------|----------|-----------|--|-----------------------------------|----------|
| Building B | Dwelling Unit | 201 | B/1B BF | 649 | 28 | 2 | 0.064625% | \$298.95 | |
| | Dwelling Unit | 202 | B/1D+D | 704 | 29 | 2 | 0.070102% | \$324.28 | |
| | Dwelling Unit | 203 | B/2D+D BF | 931 | 30 | 2 | 0.092706% | \$428.84 | |
| | Dwelling Unit | 205 | B/2F+D | 1,030 | 31 | 2 | 0.102564% | \$474.44 | |
| | Dwelling Unit | 206 | B/2E+D | 1,032 | 32 | 2 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 207 | B/1C+D | 681 | 33 | 2 | 0.067812% | \$313.69 | |
| | Dwelling Unit | 208 | B/2G+D | 1,032 | 34 | 2 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 209 | B/2A | 800 | 35 | 2 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 210 | B/1A+D | 643 | 36 | 2 | 0.064028% | \$296.18 | |
| Building A | Dwelling Unit | 201 | A/2E | 950 | 37 | 2 | 0.094598% | \$437.60 | |
| | Dwelling Unit | 202 | A/2B | 742 | 38 | 2 | 0.073886% | \$341.78 | |
| | Dwelling Unit | 203 | A/2A | 725 | 39 | 2 | 0.072193% | \$333.95 | |
| | Dwelling Unit | 205 | A/2J+D | 1,081 | 40 | 2 | 0.107644% | \$497.93 | |
| | Dwelling Unit | 206 | A/2C BF | 800 | 41 | 2 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 207 | A/2K+D | 1,139 | 42 | 2 | 0.113419% | \$524.66 | |
| | Dwelling Unit | 208 | A/1C+D | 625 | 43 | 2 | 0.062236% | \$287.89 | |
| | Dwelling Unit | 209 | A/1C+D | 625 | 44 | 2 | 0.062236% | \$287.89 | |
| | Dwelling Unit | 210 | A/3A | 1,081 | 45 | 2 | 0.107644% | \$497.94 | |
| | Dwelling Unit | 211 | A/1E+D | 698 | 46 | 2 | 0.069505% | \$321.52 | |
| | Building C | Dwelling Unit | 301 | C/2P+D | 1,056 | 1 | 3 | 0.105153% | \$486.42 |
| Dwelling Unit | | 302 | C/1A | 557 | 2 | 3 | 0.055464% | \$256.57 | |
| Dwelling Unit | | 303 | C/1B | 572 | 3 | 3 | 0.056958% | \$263.48 | |
| Dwelling Unit | | 305 | C/2N+D BF | 1,045 | 4 | 3 | 0.104058% | \$481.36 | |
| Dwelling Unit | | 306 | C/2B | 768 | 5 | 3 | 0.076475% | \$353.76 | |
| Dwelling Unit | | 307 | C/3C BF | 1,018 | 6 | 3 | 0.101369% | \$468.92 | |
| Dwelling Unit | | 308 | C/1H+D | 642 | 7 | 3 | 0.063928% | \$295.72 | |
| Dwelling Unit | | 309 | C/2L+D | 963 | 8 | 3 | 0.095893% | \$443.59 | |
| Dwelling Unit | | 310 | C/2C | 804 | 9 | 3 | 0.080060% | \$370.34 | |
| Dwelling Unit | | 311 | C/1F+D | 635 | 10 | 3 | 0.063231% | \$292.50 | |
| Dwelling Unit | | 312 | C/1J+D BF | 652 | 11 | 3 | 0.064924% | \$300.33 | |
| Dwelling Unit | | 315 | C/1J+D BF | 652 | 12 | 3 | 0.064924% | \$300.33 | |
| Dwelling Unit | | 316 | C/1J+D BF | 652 | 13 | 3 | 0.064924% | \$300.33 | |
| Dwelling Unit | | 317 | C/2A | 719 | 14 | 3 | 0.071596% | \$331.19 | |
| Dwelling Unit | | 318 | C/2Q+D | 1,082 | 15 | 3 | 0.107742% | \$498.40 | |
| Dwelling Unit | | 319 | C/1L+D | 714 | 16 | 3 | 0.071098% | \$328.89 | |
| Dwelling Unit | | 320 | C/1L+D | 714 | 17 | 3 | 0.071098% | \$328.89 | |
| Dwelling Unit | | 321 | C/1L+D | 714 | 18 | 3 | 0.071098% | \$328.89 | |
| Dwelling Unit | | 322 | C/2F | 854 | 19 | 3 | 0.085039% | \$393.38 | |
| Dwelling Unit | | 323 | C/2E | 842 | 20 | 3 | 0.083844% | \$387.85 | |
| Dwelling Unit | | 325 | C/2G | 871 | 21 | 3 | 0.086731% | \$401.20 | |
| Dwelling Unit | | 326 | C/1G+D BF | 638 | 22 | 3 | 0.063530% | \$293.88 | |
| Dwelling Unit | | 327 | C/1G+D BF | 638 | 23 | 3 | 0.063530% | \$293.88 | |
| Dwelling Unit | | 328 | C/1G+D BF | 638 | 24 | 3 | 0.063530% | \$293.88 | |
| Dwelling Unit | | 329 | C/1D+D | 617 | 25 | 3 | 0.061439% | \$284.21 | |
| Dwelling Unit | | 330 | C/1C+D | 587 | 26 | 3 | 0.058452% | \$270.39 | |
| Dwelling Unit | | 331 | C/1K+D | 712 | 27 | 3 | 0.070899% | \$327.97 | |
| Building B | | Dwelling Unit | 301 | B/1B BF | 649 | 28 | 3 | 0.064625% | \$298.95 |
| | | Dwelling Unit | 302 | B/1D+D | 704 | 29 | 3 | 0.070102% | \$324.28 |
| | | Dwelling Unit | 303 | B/3A BF | 1,048 | 30 | 3 | 0.104357% | \$482.74 |
| | | Dwelling Unit | 305 | B/2F+D | 1,030 | 31 | 3 | 0.102564% | \$474.44 |
| | | Dwelling Unit | 306 | B/2E+D | 1,032 | 32 | 3 | 0.102763% | \$475.37 |
| | | Dwelling Unit | 307 | B/1C+D | 681 | 33 | 3 | 0.067812% | \$313.69 |
| | Dwelling Unit | 308 | B/2G+D | 1,032 | 34 | 3 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 309 | B/2A | 800 | 35 | 3 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 310 | B/1A+D | 643 | 36 | 3 | 0.064028% | \$296.18 | |
| | Building A | Dwelling Unit | 301 | A/2E | 950 | 37 | 3 | 0.094598% | \$437.60 |
| Dwelling Unit | | 302 | A/2B | 742 | 38 | 3 | 0.073886% | \$341.78 | |
| Dwelling Unit | | 303 | A/2A | 725 | 39 | 3 | 0.072193% | \$333.95 | |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses based as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 305 | A/2J+D | 1,081 | 40 | 3 | 0.107644% | \$497.93 |
| | Dwelling Unit | 306 | A/2C BF | 800 | 41 | 3 | 0.079661% | \$368.50 |
| | Dwelling Unit | 307 | A/2K+D | 1,139 | 42 | 3 | 0.113419% | \$524.66 |
| | Dwelling Unit | 308 | A/1C+D | 625 | 43 | 3 | 0.062236% | \$287.89 |
| | Dwelling Unit | 309 | A/1C+D | 625 | 44 | 3 | 0.062236% | \$287.89 |
| | Dwelling Unit | 310 | A/3E+D | 1,266 | 45 | 3 | 0.126064% | \$583.15 |
| | Dwelling Unit | 311 | A/1E+D | 698 | 46 | 3 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 501 | C/2P+D | 1,056 | 1 | 4 | 0.105153% | \$486.42 |
| | Dwelling Unit | 502 | C/1A | 557 | 2 | 4 | 0.055464% | \$256.57 |
| | Dwelling Unit | 503 | C/1B | 572 | 3 | 4 | 0.056958% | \$263.48 |
| | Dwelling Unit | 505 | C/2N+D BF | 1,045 | 4 | 4 | 0.104058% | \$481.36 |
| | Dwelling Unit | 506 | C/2B | 768 | 5 | 4 | 0.076475% | \$353.76 |
| | Dwelling Unit | 507 | C/3C BF | 1,018 | 6 | 4 | 0.101369% | \$468.92 |
| | Dwelling Unit | 508 | C/1H+D | 642 | 7 | 4 | 0.063928% | \$295.72 |
| | Dwelling Unit | 509 | C/2L+D | 963 | 8 | 4 | 0.095893% | \$443.59 |
| | Dwelling Unit | 510 | C/2C | 804 | 9 | 4 | 0.080060% | \$370.34 |
| | Dwelling Unit | 511 | C/1F+D | 635 | 10 | 4 | 0.063231% | \$292.50 |
| | Dwelling Unit | 512 | C/1J+D BF | 652 | 11 | 4 | 0.064924% | \$300.33 |
| | Dwelling Unit | 515 | C/1J+D BF | 652 | 12 | 4 | 0.064924% | \$300.33 |
| | Dwelling Unit | 516 | C/1J+D BF | 652 | 13 | 4 | 0.064924% | \$300.33 |
| | Dwelling Unit | 517 | C/2A | 719 | 14 | 4 | 0.071596% | \$331.19 |
| | Dwelling Unit | 518 | C/2Q+D | 1,082 | 15 | 4 | 0.107742% | \$498.40 |
| | Dwelling Unit | 519 | C/1L+D | 714 | 16 | 4 | 0.071098% | \$328.89 |
| | Dwelling Unit | 520 | C/1L+D | 714 | 17 | 4 | 0.071098% | \$328.89 |
| | Dwelling Unit | 521 | C/1L+D | 714 | 18 | 4 | 0.071098% | \$328.89 |
| | Dwelling Unit | 522 | C/2F | 854 | 19 | 4 | 0.085039% | \$393.38 |
| | Dwelling Unit | 523 | C/2E | 842 | 20 | 4 | 0.083844% | \$387.85 |
| | Dwelling Unit | 525 | C/2G | 871 | 21 | 4 | 0.086731% | \$401.20 |
| | Dwelling Unit | 526 | C/1G+D BF | 638 | 22 | 4 | 0.063530% | \$293.88 |
| | Dwelling Unit | 527 | C/1G+D BF | 638 | 23 | 4 | 0.063530% | \$293.88 |
| | Dwelling Unit | 528 | C/1G+D BF | 638 | 24 | 4 | 0.063530% | \$293.88 |
| | Dwelling Unit | 529 | C/1D+D | 617 | 25 | 4 | 0.061439% | \$284.21 |
| | Dwelling Unit | 530 | C/1C+D | 587 | 26 | 4 | 0.058452% | \$270.39 |
| | Dwelling Unit | 531 | C/1K+D | 712 | 27 | 4 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 501 | B/1B BF | 649 | 28 | 4 | 0.064625% | \$298.95 |
| | Dwelling Unit | 502 | B/1D+D | 704 | 29 | 4 | 0.070102% | \$324.28 |
| | Dwelling Unit | 503 | B/2D+D BF | 931 | 30 | 4 | 0.092706% | \$428.84 |
| | Dwelling Unit | 505 | B/2F+D | 1,030 | 31 | 4 | 0.102564% | \$474.44 |
| | Dwelling Unit | 506 | B/2E+D | 1,032 | 32 | 4 | 0.102763% | \$475.37 |
| | Dwelling Unit | 507 | B/1C+D | 681 | 33 | 4 | 0.067812% | \$313.69 |
| | Dwelling Unit | 508 | B/2G+D | 1,032 | 34 | 4 | 0.102763% | \$475.37 |
| | Dwelling Unit | 509 | B/2A | 800 | 35 | 4 | 0.079661% | \$368.50 |
| | Dwelling Unit | 510 | B/1A+D | 643 | 36 | 4 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 501 | A/2E | 950 | 37 | 4 | 0.094598% | \$437.60 |
| | Dwelling Unit | 502 | A/2B | 742 | 38 | 4 | 0.073886% | \$341.78 |
| | Dwelling Unit | 503 | A/2A | 725 | 39 | 4 | 0.072193% | \$333.95 |
| | Dwelling Unit | 505 | A/2J+D | 1,081 | 40 | 4 | 0.107644% | \$497.93 |
| | Dwelling Unit | 506 | A/2C BF | 800 | 41 | 4 | 0.079661% | \$368.50 |
| | Dwelling Unit | 507 | A/2K+D | 1,139 | 42 | 4 | 0.113419% | \$524.66 |
| | Dwelling Unit | 508 | A/1C+D | 625 | 43 | 4 | 0.062236% | \$287.89 |
| | Dwelling Unit | 509 | A/1C+D | 625 | 44 | 4 | 0.062236% | \$287.89 |
| | Dwelling Unit | 510 | A/3A | 1,081 | 45 | 4 | 0.107644% | \$497.94 |
| | Dwelling Unit | 511 | A/1E+D | 698 | 46 | 4 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 601 | C/2P+D | 1,056 | 1 | 5 | 0.105153% | \$486.42 |
| | Dwelling Unit | 602 | C/1A | 557 | 2 | 5 | 0.055464% | \$256.57 |
| | Dwelling Unit | 603 | C/1B | 572 | 3 | 5 | 0.056958% | \$263.48 |
| | Dwelling Unit | 605 | C/2N+D BF | 1,045 | 4 | 5 | 0.104058% | \$481.36 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 606 | C/2B | 768 | 5 | 5 | 0.076475% | \$353.76 |
| | Dwelling Unit | 607 | C/3A | 1,009 | 6 | 5 | 0.100473% | \$464.77 |
| | Dwelling Unit | 608 | C/1H+D | 642 | 7 | 5 | 0.063928% | \$295.72 |
| | Dwelling Unit | 609 | C/2L+D | 963 | 8 | 5 | 0.095893% | \$443.59 |
| | Dwelling Unit | 610 | C/2C | 804 | 9 | 5 | 0.080060% | \$370.34 |
| | Dwelling Unit | 611 | C/1F+D | 635 | 10 | 5 | 0.063231% | \$292.50 |
| | Dwelling Unit | 612 | C/1J+D BF | 652 | 11 | 5 | 0.064924% | \$300.33 |
| | Dwelling Unit | 615 | C/1J+D BF | 652 | 12 | 5 | 0.064924% | \$300.33 |
| | Dwelling Unit | 616 | C/1J+D BF | 652 | 13 | 5 | 0.064924% | \$300.33 |
| | Dwelling Unit | 617 | C/2A | 719 | 14 | 5 | 0.071596% | \$331.19 |
| | Dwelling Unit | 618 | C/2Q+D | 1,082 | 15 | 5 | 0.107742% | \$498.40 |
| | Dwelling Unit | 619 | C/1L+D | 714 | 16 | 5 | 0.071098% | \$328.89 |
| | Dwelling Unit | 620 | C/1L+D | 714 | 17 | 5 | 0.071098% | \$328.89 |
| | Dwelling Unit | 621 | C/1L+D | 714 | 18 | 5 | 0.071098% | \$328.89 |
| | Dwelling Unit | 622 | C/2F | 854 | 19 | 5 | 0.085039% | \$393.38 |
| | Dwelling Unit | 623 | C/2E | 842 | 20 | 5 | 0.083844% | \$387.85 |
| | Dwelling Unit | 625 | C/2G | 871 | 21 | 5 | 0.086731% | \$401.20 |
| | Dwelling Unit | 626 | C/1G+D BF | 638 | 22 | 5 | 0.063530% | \$293.88 |
| | Dwelling Unit | 627 | C/1G+D BF | 638 | 23 | 5 | 0.063530% | \$293.88 |
| | Dwelling Unit | 628 | C/1G+D BF | 638 | 24 | 5 | 0.063530% | \$293.88 |
| | Dwelling Unit | 629 | C/1D+D | 617 | 25 | 5 | 0.061439% | \$284.21 |
| | Dwelling Unit | 630 | C/1C+D | 587 | 26 | 5 | 0.058452% | \$270.39 |
| | Dwelling Unit | 631 | C/1K+D | 712 | 27 | 5 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 601 | B/1B BF | 649 | 28 | 5 | 0.064625% | \$298.95 |
| | Dwelling Unit | 602 | B/1D+D | 704 | 29 | 5 | 0.070102% | \$324.28 |
| | Dwelling Unit | 603 | B/2H+D BF | 1,054 | 30 | 5 | 0.104954% | \$485.50 |
| | Dwelling Unit | 605 | B/2F+D | 1,030 | 31 | 5 | 0.102564% | \$474.44 |
| | Dwelling Unit | 606 | B/2E+D | 1,032 | 32 | 5 | 0.102763% | \$475.37 |
| | Dwelling Unit | 607 | B/1C+D | 681 | 33 | 5 | 0.067812% | \$313.69 |
| | Dwelling Unit | 608 | B/2G+D | 1,032 | 34 | 5 | 0.102763% | \$475.37 |
| | Dwelling Unit | 609 | B/2A | 800 | 35 | 5 | 0.079661% | \$368.50 |
| | Dwelling Unit | 610 | B/1A+D | 643 | 36 | 5 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 601 | A/3C BF | 1,201 | 37 | 5 | 0.119592% | \$553.20 |
| | Dwelling Unit | 602 | A/2B | 742 | 38 | 5 | 0.073886% | \$341.78 |
| | Dwelling Unit | 603 | A/2A | 725 | 39 | 5 | 0.072193% | \$333.95 |
| | Dwelling Unit | 605 | A/2J+D | 1,081 | 40 | 5 | 0.107644% | \$497.93 |
| | Dwelling Unit | 606 | A/2C BF | 800 | 41 | 5 | 0.079661% | \$368.50 |
| | Dwelling Unit | 607 | A/2K+D | 1,139 | 42 | 5 | 0.113419% | \$524.66 |
| | Dwelling Unit | 608 | A/1C+D | 625 | 43 | 5 | 0.062236% | \$287.89 |
| | Dwelling Unit | 609 | A/1C+D | 625 | 44 | 5 | 0.062236% | \$287.89 |
| | Dwelling Unit | 610 | A/2H+D | 1,019 | 45 | 5 | 0.101469% | \$469.38 |
| | Dwelling Unit | 611 | A/1D+D BF | 698 | 46 | 5 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 701 | C/2P+D | 1,056 | 1 | 6 | 0.105153% | \$486.42 |
| | Dwelling Unit | 702 | C/1A | 557 | 2 | 6 | 0.055464% | \$256.57 |
| | Dwelling Unit | 703 | C/1B | 572 | 3 | 6 | 0.056958% | \$263.48 |
| | Dwelling Unit | 705 | C/2N+D BF | 1,045 | 4 | 6 | 0.104058% | \$481.36 |
| | Dwelling Unit | 706 | C/2B | 768 | 5 | 6 | 0.076475% | \$353.76 |
| | Dwelling Unit | 707 | C/3A | 1,009 | 6 | 6 | 0.100473% | \$464.77 |
| | Dwelling Unit | 708 | C/1H+D | 642 | 7 | 6 | 0.063928% | \$295.72 |
| | Dwelling Unit | 709 | C/2L+D | 963 | 8 | 6 | 0.095893% | \$443.59 |
| | Dwelling Unit | 710 | C/2C | 804 | 9 | 6 | 0.080060% | \$370.34 |
| | Dwelling Unit | 711 | C/1F+D | 635 | 10 | 6 | 0.063231% | \$292.50 |
| | Dwelling Unit | 712 | C/1J+D BF | 652 | 11 | 6 | 0.064924% | \$300.33 |
| | Dwelling Unit | 715 | C/1J+D BF | 652 | 12 | 6 | 0.064924% | \$300.33 |
| | Dwelling Unit | 716 | C/1J+D BF | 652 | 13 | 6 | 0.064924% | \$300.33 |
| | Dwelling Unit | 717 | C/2A | 719 | 14 | 6 | 0.071596% | \$331.19 |
| | Dwelling Unit | 718 | C/2Q+D | 1,082 | 15 | 6 | 0.107742% | \$498.40 |
| | Dwelling Unit | 719 | C/1L+D | 714 | 16 | 6 | 0.071098% | \$328.89 |
| | Dwelling Unit | 720 | C/1L+D | 714 | 17 | 6 | 0.071098% | \$328.89 |
| | Dwelling Unit | 721 | C/1L+D | 714 | 18 | 6 | 0.071098% | \$328.89 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 722 | C/2F | 854 | 19 | 6 | 0.085039% | \$393.38 |
| | Dwelling Unit | 723 | C/2E | 842 | 20 | 6 | 0.083844% | \$387.85 |
| | Dwelling Unit | 725 | C/2G | 871 | 21 | 6 | 0.086731% | \$401.20 |
| | Dwelling Unit | 726 | C/1G+D BF | 638 | 22 | 6 | 0.063530% | \$293.88 |
| | Dwelling Unit | 727 | C/1G+D BF | 638 | 23 | 6 | 0.063530% | \$293.88 |
| | Dwelling Unit | 728 | C/1G+D BF | 638 | 24 | 6 | 0.063530% | \$293.88 |
| | Dwelling Unit | 729 | C/1D+D | 617 | 25 | 6 | 0.061439% | \$284.21 |
| | Dwelling Unit | 730 | C/1C+D | 587 | 26 | 6 | 0.058452% | \$270.39 |
| | Dwelling Unit | 731 | C/1K+D | 712 | 27 | 6 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 701 | B/1B BF | 649 | 28 | 6 | 0.064625% | \$298.95 |
| | Dwelling Unit | 702 | B/1D+D | 704 | 29 | 6 | 0.070102% | \$324.28 |
| | Dwelling Unit | 703 | B/2H+D BF | 1,054 | 30 | 6 | 0.104954% | \$485.50 |
| | Dwelling Unit | 705 | B/2F+D | 1,030 | 31 | 6 | 0.102564% | \$474.44 |
| | Dwelling Unit | 706 | B/2E+D | 1,032 | 32 | 6 | 0.102763% | \$475.37 |
| | Dwelling Unit | 707 | B/1C+D | 681 | 33 | 6 | 0.067812% | \$313.69 |
| | Dwelling Unit | 708 | B/2G+D | 1,032 | 34 | 6 | 0.102763% | \$475.37 |
| | Dwelling Unit | 709 | B/2A | 800 | 35 | 6 | 0.079661% | \$368.50 |
| | Dwelling Unit | 710 | B/1A+D | 643 | 36 | 6 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 701 | A/3C BF | 1,201 | 37 | 6 | 0.119592% | \$553.20 |
| | Dwelling Unit | 702 | A/2B | 742 | 38 | 6 | 0.073886% | \$341.78 |
| | Dwelling Unit | 703 | A/2A | 725 | 39 | 6 | 0.072193% | \$333.95 |
| | Dwelling Unit | 705 | A/2J+D | 1,081 | 40 | 6 | 0.107644% | \$497.93 |
| | Dwelling Unit | 706 | A/2C BF | 800 | 41 | 6 | 0.079661% | \$368.50 |
| | Dwelling Unit | 707 | A/2K+D | 1,139 | 42 | 6 | 0.113419% | \$524.66 |
| | Dwelling Unit | 708 | A/1C+D | 625 | 43 | 6 | 0.062236% | \$287.89 |
| | Dwelling Unit | 709 | A/1C+D | 625 | 44 | 6 | 0.062236% | \$287.89 |
| | Dwelling Unit | 710 | A/2H+D | 1,019 | 45 | 6 | 0.101469% | \$469.38 |
| | Dwelling Unit | 711 | A/1D+D BF | 698 | 46 | 6 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 801 | C/2P+D | 1,056 | 1 | 7 | 0.105153% | \$486.42 |
| | Dwelling Unit | 802 | C/1A | 557 | 2 | 7 | 0.055464% | \$256.57 |
| | Dwelling Unit | 803 | C/1B | 572 | 3 | 7 | 0.056958% | \$263.48 |
| | Dwelling Unit | 805 | C/2N+D BF | 1,045 | 4 | 7 | 0.104058% | \$481.36 |
| | Dwelling Unit | 806 | C/2B | 768 | 5 | 7 | 0.076475% | \$353.76 |
| | Dwelling Unit | 807 | C/3A | 1,009 | 6 | 7 | 0.100473% | \$464.77 |
| | Dwelling Unit | 808 | C/1H+D | 642 | 7 | 7 | 0.063928% | \$295.72 |
| | Dwelling Unit | 809 | C/2L+D | 963 | 8 | 7 | 0.095893% | \$443.59 |
| | Dwelling Unit | 810 | C/2C | 804 | 9 | 7 | 0.080060% | \$370.34 |
| | Dwelling Unit | 811 | C/1F+D | 635 | 10 | 7 | 0.063231% | \$292.50 |
| | Dwelling Unit | 812 | C/1J+D BF | 652 | 11 | 7 | 0.064924% | \$300.33 |
| | Dwelling Unit | 815 | C/1J+D BF | 652 | 12 | 7 | 0.064924% | \$300.33 |
| | Dwelling Unit | 816 | C/1J+D BF | 652 | 13 | 7 | 0.064924% | \$300.33 |
| | Dwelling Unit | 817 | C/2A | 719 | 14 | 7 | 0.071596% | \$331.19 |
| | Dwelling Unit | 818 | C/2Q+D | 1,082 | 15 | 7 | 0.107742% | \$498.40 |
| | Dwelling Unit | 819 | C/1L+D | 714 | 16 | 7 | 0.071098% | \$328.89 |
| | Dwelling Unit | 820 | C/1L+D | 714 | 17 | 7 | 0.071098% | \$328.89 |
| | Dwelling Unit | 821 | C/1L+D | 714 | 18 | 7 | 0.071098% | \$328.89 |
| | Dwelling Unit | 822 | C/2F | 854 | 19 | 7 | 0.085039% | \$393.38 |
| | Dwelling Unit | 823 | C/2E | 842 | 20 | 7 | 0.083844% | \$387.85 |
| | Dwelling Unit | 825 | C/2G | 871 | 21 | 7 | 0.086731% | \$401.20 |
| | Dwelling Unit | 826 | C/1G+D BF | 638 | 22 | 7 | 0.063530% | \$293.88 |
| | Dwelling Unit | 827 | C/1G+D BF | 638 | 23 | 7 | 0.063530% | \$293.88 |
| | Dwelling Unit | 828 | C/1G+D BF | 638 | 24 | 7 | 0.063530% | \$293.88 |
| | Dwelling Unit | 829 | C/1D+D | 617 | 25 | 7 | 0.061439% | \$284.21 |
| | Dwelling Unit | 830 | C/1C+D | 587 | 26 | 7 | 0.058452% | \$270.39 |
| | Dwelling Unit | 831 | C/1K+D | 712 | 27 | 7 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 801 | B/1B BF | 649 | 28 | 7 | 0.064625% | \$298.95 |
| | Dwelling Unit | 802 | B/1D+D | 704 | 29 | 7 | 0.070102% | \$324.28 |
| | Dwelling Unit | 803 | B/2H+D BF | 1,054 | 30 | 7 | 0.104954% | \$485.50 |
| | Dwelling Unit | 805 | B/2F+D | 1,030 | 31 | 7 | 0.102564% | \$474.44 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 806 | B/2E+D | 1,032 | 32 | 7 | 0.102763% | \$475.37 |
| | Dwelling Unit | 807 | B/1C+D | 681 | 33 | 7 | 0.067812% | \$313.69 |
| | Dwelling Unit | 808 | B/2G+D | 1,032 | 34 | 7 | 0.102763% | \$475.37 |
| | Dwelling Unit | 809 | B/2A | 800 | 35 | 7 | 0.079661% | \$368.50 |
| | Dwelling Unit | 810 | B/1A+D | 643 | 36 | 7 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 801 | A/3C BF | 1,201 | 37 | 7 | 0.119592% | \$553.20 |
| | Dwelling Unit | 802 | A/2B | 742 | 38 | 7 | 0.073886% | \$341.78 |
| | Dwelling Unit | 803 | A/2A | 725 | 39 | 7 | 0.072193% | \$333.95 |
| | Dwelling Unit | 805 | A/2J+D | 1,081 | 40 | 7 | 0.107644% | \$497.93 |
| | Dwelling Unit | 806 | A/2C BF | 800 | 41 | 7 | 0.079661% | \$368.50 |
| | Dwelling Unit | 807 | A/2K+D | 1,139 | 42 | 7 | 0.113419% | \$524.66 |
| | Dwelling Unit | 808 | A/1C+D | 625 | 43 | 7 | 0.062236% | \$287.89 |
| | Dwelling Unit | 809 | A/1C+D | 625 | 44 | 7 | 0.062236% | \$287.89 |
| | Dwelling Unit | 810 | A/2H+D | 1,019 | 45 | 7 | 0.101469% | \$469.38 |
| | Dwelling Unit | 811 | A/1D+D BF | 698 | 46 | 7 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 901 | C/2P+D | 1,056 | 1 | 8 | 0.105153% | \$486.42 |
| | Dwelling Unit | 902 | C/1A | 557 | 2 | 8 | 0.055464% | \$256.57 |
| | Dwelling Unit | 903 | C/1B | 572 | 3 | 8 | 0.056958% | \$263.48 |
| | Dwelling Unit | 905 | C/2N+D BF | 1,045 | 4 | 8 | 0.104058% | \$481.36 |
| | Dwelling Unit | 906 | C/2B | 768 | 5 | 8 | 0.076475% | \$353.76 |
| | Dwelling Unit | 907 | C/3A | 1,009 | 6 | 8 | 0.100473% | \$464.77 |
| | Dwelling Unit | 908 | C/1H+D | 642 | 7 | 8 | 0.063928% | \$295.72 |
| | Dwelling Unit | 909 | C/2L+D | 963 | 8 | 8 | 0.095893% | \$443.59 |
| | Dwelling Unit | 910 | C/2C | 804 | 9 | 8 | 0.080060% | \$370.34 |
| | Dwelling Unit | 911 | C/1F+D | 635 | 10 | 8 | 0.063231% | \$292.50 |
| | Dwelling Unit | 912 | C/1J+D BF | 652 | 11 | 8 | 0.064924% | \$300.33 |
| | Dwelling Unit | 915 | C/1J+D BF | 652 | 12 | 8 | 0.064924% | \$300.33 |
| | Dwelling Unit | 916 | C/1J+D BF | 652 | 13 | 8 | 0.064924% | \$300.33 |
| | Dwelling Unit | 917 | C/2A | 719 | 14 | 8 | 0.071596% | \$331.19 |
| | Dwelling Unit | 918 | C/2Q+D | 1,082 | 15 | 8 | 0.107742% | \$498.40 |
| | Dwelling Unit | 919 | C/1L+D | 714 | 16 | 8 | 0.071098% | \$328.89 |
| | Dwelling Unit | 920 | C/1L+D | 714 | 17 | 8 | 0.071098% | \$328.89 |
| | Dwelling Unit | 921 | C/1L+D | 714 | 18 | 8 | 0.071098% | \$328.89 |
| | Dwelling Unit | 922 | C/2F | 854 | 19 | 8 | 0.085039% | \$393.38 |
| | Dwelling Unit | 923 | C/2E | 842 | 20 | 8 | 0.083844% | \$387.85 |
| | Dwelling Unit | 925 | C/2G | 871 | 21 | 8 | 0.086731% | \$401.20 |
| | Dwelling Unit | 926 | C/1G+D BF | 638 | 22 | 8 | 0.063530% | \$293.88 |
| | Dwelling Unit | 927 | C/1G+D BF | 638 | 23 | 8 | 0.063530% | \$293.88 |
| | Dwelling Unit | 928 | C/1G+D BF | 638 | 24 | 8 | 0.063530% | \$293.88 |
| | Dwelling Unit | 929 | C/1D+D | 617 | 25 | 8 | 0.061439% | \$284.21 |
| | Dwelling Unit | 930 | C/1C+D | 587 | 26 | 8 | 0.058452% | \$270.39 |
| | Dwelling Unit | 931 | C/1K+D | 712 | 27 | 8 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 901 | B/1B BF | 649 | 28 | 8 | 0.064625% | \$298.95 |
| | Dwelling Unit | 902 | B/1D+D | 704 | 29 | 8 | 0.070102% | \$324.28 |
| | Dwelling Unit | 903 | B/2H+D BF | 1,054 | 30 | 8 | 0.104954% | \$485.50 |
| | Dwelling Unit | 905 | B/2F+D | 1,030 | 31 | 8 | 0.102564% | \$474.44 |
| | Dwelling Unit | 906 | B/2E+D | 1,032 | 32 | 8 | 0.102763% | \$475.37 |
| | Dwelling Unit | 907 | B/1C+D | 681 | 33 | 8 | 0.067812% | \$313.69 |
| | Dwelling Unit | 908 | B/2G+D | 1,032 | 34 | 8 | 0.102763% | \$475.37 |
| | Dwelling Unit | 909 | B/2A | 800 | 35 | 8 | 0.079661% | \$368.50 |
| | Dwelling Unit | 910 | B/1A+D | 643 | 36 | 8 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 901 | A/3C BF | 1,201 | 37 | 8 | 0.119592% | \$553.20 |
| | Dwelling Unit | 902 | A/2B | 742 | 38 | 8 | 0.073886% | \$341.78 |
| | Dwelling Unit | 903 | A/2A | 725 | 39 | 8 | 0.072193% | \$333.95 |
| | Dwelling Unit | 905 | A/2J+D | 1,081 | 40 | 8 | 0.107644% | \$497.93 |
| | Dwelling Unit | 906 | A/2C BF | 800 | 41 | 8 | 0.079661% | \$368.50 |
| | Dwelling Unit | 907 | A/2K+D | 1,139 | 42 | 8 | 0.113419% | \$524.66 |
| | Dwelling Unit | 908 | A/1C+D | 625 | 43 | 8 | 0.062236% | \$287.89 |
| | Dwelling Unit | 909 | A/1C+D | 625 | 44 | 8 | 0.062236% | \$287.89 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 910 | A/2H+D | 1,019 | 45 | 8 | 0.101469% | \$469.38 |
| | Dwelling Unit | 911 | A/1D+D BF | 698 | 46 | 8 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 1001 | C/2P+D | 1,056 | 1 | 9 | 0.105153% | \$486.42 |
| | Dwelling Unit | 1002 | C/1A | 557 | 2 | 9 | 0.055464% | \$256.57 |
| | Dwelling Unit | 1003 | C/1B | 572 | 3 | 9 | 0.056958% | \$263.48 |
| | Dwelling Unit | 1005 | C/2N+D BF | 1,045 | 4 | 9 | 0.104058% | \$481.36 |
| | Dwelling Unit | 1006 | C/2B | 768 | 5 | 9 | 0.076475% | \$353.76 |
| | Dwelling Unit | 1007 | C/3A | 1,009 | 6 | 9 | 0.100473% | \$464.77 |
| | Dwelling Unit | 1008 | C/1H+D | 642 | 7 | 9 | 0.063928% | \$295.72 |
| | Dwelling Unit | 1009 | C/2L+D | 963 | 8 | 9 | 0.095893% | \$443.59 |
| | Dwelling Unit | 1010 | C/2C | 804 | 9 | 9 | 0.080060% | \$370.34 |
| | Dwelling Unit | 1011 | C/1F+D | 635 | 10 | 9 | 0.063231% | \$292.50 |
| | Dwelling Unit | 1012 | C/1J+D BF | 652 | 11 | 9 | 0.064924% | \$300.33 |
| | Dwelling Unit | 1015 | C/1J+D BF | 652 | 12 | 9 | 0.064924% | \$300.33 |
| | Dwelling Unit | 1016 | C/1J+D BF | 652 | 13 | 9 | 0.064924% | \$300.33 |
| | Dwelling Unit | 1017 | C/2A | 719 | 14 | 9 | 0.071596% | \$331.19 |
| | Dwelling Unit | 1018 | C/2Q+D | 1,082 | 15 | 9 | 0.107742% | \$498.40 |
| | Dwelling Unit | 1019 | C/1L+D | 714 | 16 | 9 | 0.071098% | \$328.89 |
| | Dwelling Unit | 1020 | C/1L+D | 714 | 17 | 9 | 0.071098% | \$328.89 |
| | Dwelling Unit | 1021 | C/1L+D | 714 | 18 | 9 | 0.071098% | \$328.89 |
| | Dwelling Unit | 1022 | C/2F | 854 | 19 | 9 | 0.085039% | \$393.38 |
| | Dwelling Unit | 1023 | C/2E | 842 | 20 | 9 | 0.083844% | \$387.85 |
| | Dwelling Unit | 1025 | C/2G | 871 | 21 | 9 | 0.086731% | \$401.20 |
| | Dwelling Unit | 1026 | C/1G+D BF | 638 | 22 | 9 | 0.063530% | \$293.88 |
| | Dwelling Unit | 1027 | C/1G+D BF | 638 | 23 | 9 | 0.063530% | \$293.88 |
| | Dwelling Unit | 1028 | C/1G+D BF | 638 | 24 | 9 | 0.063530% | \$293.88 |
| | Dwelling Unit | 1029 | C/1D+D | 617 | 25 | 9 | 0.061439% | \$284.21 |
| | Dwelling Unit | 1030 | C/1C+D | 587 | 26 | 9 | 0.058452% | \$270.39 |
| | Dwelling Unit | 1031 | C/1K+D | 712 | 27 | 9 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 1001 | B/1B BF | 649 | 28 | 9 | 0.064625% | \$298.95 |
| | Dwelling Unit | 1002 | B/1D+D | 704 | 29 | 9 | 0.070102% | \$324.28 |
| | Dwelling Unit | 1003 | B/2H+D BF | 1,054 | 30 | 9 | 0.104954% | \$485.50 |
| | Dwelling Unit | 1005 | B/2F+D | 1,030 | 31 | 9 | 0.102564% | \$474.44 |
| | Dwelling Unit | 1006 | B/2E+D | 1,032 | 32 | 9 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1007 | B/1C+D | 681 | 33 | 9 | 0.067812% | \$313.69 |
| | Dwelling Unit | 1008 | B/2G+D | 1,032 | 34 | 9 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1009 | B/2A | 800 | 35 | 9 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1010 | B/1A+D | 643 | 36 | 9 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 1001 | A/3C BF | 1,201 | 37 | 9 | 0.119592% | \$553.20 |
| | Dwelling Unit | 1002 | A/2B | 742 | 38 | 9 | 0.073886% | \$341.78 |
| | Dwelling Unit | 1003 | A/2A | 725 | 39 | 9 | 0.072193% | \$333.95 |
| | Dwelling Unit | 1005 | A/2J+D | 1,081 | 40 | 9 | 0.107644% | \$497.93 |
| | Dwelling Unit | 1006 | A/2C BF | 800 | 41 | 9 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1007 | A/2K+D | 1,139 | 42 | 9 | 0.113419% | \$524.66 |
| | Dwelling Unit | 1008 | A/1C+D | 625 | 43 | 9 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1009 | A/1C+D | 625 | 44 | 9 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1010 | A/2H+D | 1,019 | 45 | 9 | 0.101469% | \$469.38 |
| | Dwelling Unit | 1011 | A/1D+D BF | 698 | 46 | 9 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 1101 | C/2P+D | 1,056 | 1 | 10 | 0.105153% | \$486.42 |
| | Dwelling Unit | 1102 | C/1A | 557 | 2 | 10 | 0.055464% | \$256.57 |
| | Dwelling Unit | 1103 | C/1B | 572 | 3 | 10 | 0.056958% | \$263.48 |
| | Dwelling Unit | 1105 | C/2N+D BF | 1,045 | 4 | 10 | 0.104058% | \$481.36 |
| | Dwelling Unit | 1106 | C/2B | 768 | 5 | 10 | 0.076475% | \$353.76 |
| | Dwelling Unit | 1107 | C/3A | 1,009 | 6 | 10 | 0.100473% | \$464.77 |
| | Dwelling Unit | 1108 | C/1H+D | 642 | 7 | 10 | 0.063928% | \$295.72 |
| | Dwelling Unit | 1109 | C/1E+D | 625 | 8 | 10 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1110 | C/2K BF | 938 | 9 | 10 | 0.093403% | \$432.07 |
| | Dwelling Unit | 1111 | C/1K+D | 712 | 10 | 10 | 0.070899% | \$327.97 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|-------------------|---------------|-----------|---------|----------|-----------|--|-----------------------------------|
| Building B | Dwelling Unit | 1101 | B/1B BF | 649 | 11 | 10 | 0.064625% | \$298.95 |
| | Dwelling Unit | 1102 | B/1D+D | 704 | 12 | 10 | 0.070102% | \$324.28 |
| | Dwelling Unit | 1103 | B/2H+D BF | 1,054 | 13 | 10 | 0.104954% | \$485.50 |
| | Dwelling Unit | 1105 | B/2F+D | 1,030 | 14 | 10 | 0.102564% | \$474.44 |
| | Dwelling Unit | 1106 | B/2E+D | 1,032 | 15 | 10 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1107 | B/1C+D | 681 | 16 | 10 | 0.067812% | \$313.69 |
| | Dwelling Unit | 1108 | B/2G+D | 1,032 | 17 | 10 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1109 | B/2A | 800 | 18 | 10 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1110 | B/1A+D | 643 | 19 | 10 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 1101 | A/3C BF | 1,201 | 20 | 10 | 0.119592% | \$553.20 |
| | Dwelling Unit | 1102 | A/2B | 742 | 21 | 10 | 0.073886% | \$341.78 |
| | Dwelling Unit | 1103 | A/2A | 725 | 22 | 10 | 0.072193% | \$333.95 |
| | Dwelling Unit | 1105 | A/2J+D | 1,081 | 23 | 10 | 0.107644% | \$497.93 |
| | Dwelling Unit | 1106 | A/2C BF | 800 | 24 | 10 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1107 | A/2K+D | 1,139 | 25 | 10 | 0.113419% | \$524.66 |
| | Dwelling Unit | 1108 | A/1C+D | 625 | 26 | 10 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1109 | A/1C+D | 625 | 27 | 10 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1110 | A/2H+D | 1,019 | 28 | 10 | 0.101469% | \$469.38 |
| | Dwelling Unit | 1111 | A/1D+D BF | 698 | 29 | 10 | 0.069505% | \$321.52 |
| | Building C | Dwelling Unit | 1201 | C/2P+D | 1,056 | 1 | 11 | 0.105153% |
| Dwelling Unit | | 1202 | C/1A | 557 | 2 | 11 | 0.055464% | \$256.57 |
| Dwelling Unit | | 1203 | C/1B | 572 | 3 | 11 | 0.056958% | \$263.48 |
| Dwelling Unit | | 1205 | C/2N+D BF | 1,045 | 4 | 11 | 0.104058% | \$481.36 |
| Dwelling Unit | | 1206 | C/2B | 768 | 5 | 11 | 0.076475% | \$353.76 |
| Dwelling Unit | | 1207 | C/3A | 1,009 | 6 | 11 | 0.100473% | \$464.77 |
| Dwelling Unit | | 1208 | C/1H+D | 642 | 7 | 11 | 0.063928% | \$295.72 |
| Dwelling Unit | | 1209 | C/1E+D | 625 | 8 | 11 | 0.062236% | \$287.89 |
| Dwelling Unit | | 1210 | C/2K BF | 938 | 9 | 11 | 0.093403% | \$432.07 |
| Dwelling Unit | | 1211 | C/1K+D | 712 | 10 | 11 | 0.070899% | \$327.97 |
| Building B | | Dwelling Unit | 1201 | B/1B BF | 649 | 11 | 11 | 0.064625% |
| | Dwelling Unit | 1202 | B/1D+D | 704 | 12 | 11 | 0.070102% | \$324.28 |
| | Dwelling Unit | 1203 | B/2H+D BF | 1,054 | 13 | 11 | 0.104954% | \$485.50 |
| | Dwelling Unit | 1205 | B/2F+D | 1,030 | 14 | 11 | 0.102564% | \$474.44 |
| | Dwelling Unit | 1206 | B/2E+D | 1,032 | 15 | 11 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1207 | B/1C+D | 681 | 16 | 11 | 0.067812% | \$313.69 |
| | Dwelling Unit | 1208 | B/2G+D | 1,032 | 17 | 11 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1209 | B/2A | 800 | 18 | 11 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1210 | B/1A+D | 643 | 19 | 11 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 1201 | A/3C | 1,201 | 20 | 11 | 0.119593% | \$553.22 |
| | Dwelling Unit | 1202 | A/2B | 742 | 21 | 11 | 0.073886% | \$341.78 |
| | Dwelling Unit | 1203 | A/2A | 725 | 22 | 11 | 0.072193% | \$333.95 |
| | Dwelling Unit | 1205 | A/2J+D | 1,081 | 23 | 11 | 0.107644% | \$497.93 |
| | Dwelling Unit | 1206 | A/2C BF | 800 | 24 | 11 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1207 | A/2K+D | 1,139 | 25 | 11 | 0.113419% | \$524.66 |
| | Dwelling Unit | 1208 | A/1C+D | 625 | 26 | 11 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1209 | A/1C+D | 625 | 27 | 11 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1210 | A/2H+D | 1,019 | 28 | 11 | 0.101469% | \$469.38 |
| | Dwelling Unit | 1211 | A/1D+D BF | 698 | 29 | 11 | 0.069505% | \$321.52 |
| | Building C | Dwelling Unit | 1501 | C/2P+D | 1,056 | 1 | 12 | 0.105153% |
| Dwelling Unit | | 1502 | C/1A | 557 | 2 | 12 | 0.055464% | \$256.57 |
| Dwelling Unit | | 1503 | C/1B | 572 | 3 | 12 | 0.056958% | \$263.48 |
| Dwelling Unit | | 1505 | C/2N+D BF | 1,045 | 4 | 12 | 0.104058% | \$481.36 |
| Dwelling Unit | | 1506 | C/2B | 768 | 5 | 12 | 0.076475% | \$353.76 |
| Dwelling Unit | | 1507 | C/3A | 1,009 | 6 | 12 | 0.100473% | \$464.77 |
| Dwelling Unit | | 1508 | C/1H+D | 642 | 7 | 12 | 0.063928% | \$295.72 |
| Dwelling Unit | | 1509 | C/1E+D | 625 | 8 | 12 | 0.062236% | \$287.89 |
| Dwelling Unit | | 1510 | C/2K BF | 938 | 9 | 12 | 0.093403% | \$432.07 |
| Dwelling Unit | | 1511 | C/1K+D | 712 | 10 | 12 | 0.070899% | \$327.97 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses based as percentages to each | Monthly Common Element Assessment |
|-------------------|-------------------|---------------|-----------|---------|----------|-----------|--|-----------------------------------|
| Building B | Dwelling Unit | 1501 | B/1B BF | 649 | 11 | 12 | 0.064625% | \$298.95 |
| | Dwelling Unit | 1502 | B/1D+D | 704 | 12 | 12 | 0.070102% | \$324.28 |
| | Dwelling Unit | 1503 | B/2H+D BF | 1,054 | 13 | 12 | 0.104954% | \$485.50 |
| | Dwelling Unit | 1505 | B/2F+D | 1,030 | 14 | 12 | 0.102564% | \$474.44 |
| | Dwelling Unit | 1506 | B/2E+D | 1,032 | 15 | 12 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1507 | B/1C+D | 681 | 16 | 12 | 0.067812% | \$313.69 |
| | Dwelling Unit | 1508 | B/2G+D | 1,032 | 17 | 12 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1509 | B/2A | 800 | 18 | 12 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1510 | B/1A+D | 643 | 19 | 12 | 0.064028% | \$296.18 |
| | Building A | Dwelling Unit | 1501 | A/3C | 1,201 | 20 | 12 | 0.119593% |
| Dwelling Unit | | 1502 | A/2B | 742 | 21 | 12 | 0.073886% | \$341.78 |
| Dwelling Unit | | 1503 | A/2A | 725 | 22 | 12 | 0.072193% | \$333.95 |
| Dwelling Unit | | 1505 | A/2J+D | 1,081 | 23 | 12 | 0.107644% | \$497.93 |
| Dwelling Unit | | 1506 | A/2C BF | 800 | 24 | 12 | 0.079661% | \$368.50 |
| Dwelling Unit | | 1507 | A/2K+D | 1,139 | 25 | 12 | 0.113419% | \$524.66 |
| Dwelling Unit | | 1508 | A/1C+D | 625 | 26 | 12 | 0.062236% | \$287.89 |
| Dwelling Unit | | 1509 | A/1C+D | 625 | 27 | 12 | 0.062236% | \$287.89 |
| Dwelling Unit | | 1510 | A/2H+D | 1,019 | 28 | 12 | 0.101469% | \$469.38 |
| Dwelling Unit | | 1511 | A/1D+D BF | 698 | 29 | 12 | 0.069505% | \$321.52 |
| Building C | | Dwelling Unit | 1601 | C/2P+D | 1,056 | 1 | 13 | 0.105153% |
| | Dwelling Unit | 1602 | C/1A | 557 | 2 | 13 | 0.055464% | \$256.57 |
| | Dwelling Unit | 1603 | C/1B | 572 | 3 | 13 | 0.056958% | \$263.48 |
| | Dwelling Unit | 1605 | C/2N+D BF | 1,045 | 4 | 13 | 0.104058% | \$481.36 |
| | Dwelling Unit | 1606 | C/2B | 768 | 5 | 13 | 0.076475% | \$353.76 |
| | Dwelling Unit | 1607 | C/3A | 1,009 | 6 | 13 | 0.100473% | \$464.77 |
| | Dwelling Unit | 1608 | C/1H+D | 642 | 7 | 13 | 0.063928% | \$295.72 |
| | Dwelling Unit | 1609 | C/1E+D | 625 | 8 | 13 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1610 | C/2K BF | 938 | 9 | 13 | 0.093403% | \$432.07 |
| | Dwelling Unit | 1611 | C/1K+D | 712 | 10 | 13 | 0.070899% | \$327.97 |
| | Building B | Dwelling Unit | 1601 | B/1B BF | 649 | 11 | 13 | 0.064625% |
| Dwelling Unit | | 1602 | B/1D+D | 704 | 12 | 13 | 0.070102% | \$324.28 |
| Dwelling Unit | | 1603 | B/2H+D BF | 1,054 | 13 | 13 | 0.104954% | \$485.50 |
| Dwelling Unit | | 1605 | B/2F+D | 1,030 | 14 | 13 | 0.102564% | \$474.44 |
| Dwelling Unit | | 1606 | B/2E+D | 1,032 | 15 | 13 | 0.102763% | \$475.37 |
| Dwelling Unit | | 1607 | B/1C+D | 681 | 16 | 13 | 0.067812% | \$313.69 |
| Dwelling Unit | | 1608 | B/2G+D | 1,032 | 17 | 13 | 0.102763% | \$475.37 |
| Dwelling Unit | | 1609 | B/2A | 800 | 18 | 13 | 0.079661% | \$368.50 |
| Dwelling Unit | | 1610 | B/1A+D | 643 | 19 | 13 | 0.064028% | \$296.18 |
| Building A | | Dwelling Unit | 1601 | A/3C | 1,201 | 20 | 13 | 0.119593% |
| | Dwelling Unit | 1602 | A/2B | 742 | 21 | 13 | 0.073886% | \$341.78 |
| | Dwelling Unit | 1603 | A/2A | 725 | 22 | 13 | 0.072193% | \$333.95 |
| | Dwelling Unit | 1605 | A/2J+D | 1,081 | 23 | 13 | 0.107644% | \$497.93 |
| | Dwelling Unit | 1606 | A/2C BF | 800 | 24 | 13 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1607 | A/2K+D | 1,139 | 25 | 13 | 0.113419% | \$524.66 |
| | Dwelling Unit | 1608 | A/1C+D | 625 | 26 | 13 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1609 | A/1C+D | 625 | 27 | 13 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1610 | A/2H+D | 1,019 | 28 | 13 | 0.101469% | \$469.38 |
| | Dwelling Unit | 1611 | A/1D+D BF | 698 | 29 | 13 | 0.069505% | \$321.52 |
| | Building C | Dwelling Unit | 1701 | C/2P+D | 1,056 | 1 | 14 | 0.105153% |
| Dwelling Unit | | 1702 | C/1A | 557 | 2 | 14 | 0.055464% | \$256.57 |
| Dwelling Unit | | 1703 | C/1B | 572 | 3 | 14 | 0.056958% | \$263.48 |
| Dwelling Unit | | 1705 | C/2N+D BF | 1,045 | 4 | 14 | 0.104058% | \$481.36 |
| Dwelling Unit | | 1706 | C/2B | 768 | 5 | 14 | 0.076475% | \$353.76 |
| Dwelling Unit | | 1707 | C/3A | 1,009 | 6 | 14 | 0.100473% | \$464.77 |
| Dwelling Unit | | 1708 | C/1H+D | 642 | 7 | 14 | 0.063928% | \$295.72 |
| Dwelling Unit | | 1709 | C/1E+D | 625 | 8 | 14 | 0.062236% | \$287.89 |
| Dwelling Unit | | 1710 | C/2K BF | 938 | 9 | 14 | 0.093403% | \$432.07 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 1711 | C/1K+D | 712 | 10 | 14 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 1701 | B/1B BF | 649 | 11 | 14 | 0.064625% | \$298.95 |
| | Dwelling Unit | 1702 | B/1D+D | 704 | 12 | 14 | 0.070102% | \$324.28 |
| | Dwelling Unit | 1703 | B/2H+D BF | 1,054 | 13 | 14 | 0.104954% | \$485.50 |
| | Dwelling Unit | 1705 | B/2F+D | 1,030 | 14 | 14 | 0.102564% | \$474.44 |
| | Dwelling Unit | 1706 | B/2E+D | 1,032 | 15 | 14 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1707 | B/1C+D | 681 | 16 | 14 | 0.067812% | \$313.69 |
| | Dwelling Unit | 1708 | B/2G+D | 1,032 | 17 | 14 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1709 | B/2A | 800 | 18 | 14 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1710 | B/1A+D | 643 | 19 | 14 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 1701 | A/3C | 1,201 | 20 | 14 | 0.119593% | \$553.22 |
| | Dwelling Unit | 1702 | A/2B | 742 | 21 | 14 | 0.073886% | \$341.78 |
| | Dwelling Unit | 1703 | A/2A | 725 | 22 | 14 | 0.072193% | \$333.95 |
| | Dwelling Unit | 1705 | A/2J+D | 1,081 | 23 | 14 | 0.107644% | \$497.93 |
| | Dwelling Unit | 1706 | A/2C BF | 800 | 24 | 14 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1707 | A/2K+D | 1,139 | 25 | 14 | 0.113419% | \$524.66 |
| | Dwelling Unit | 1708 | A/1C+D | 625 | 26 | 14 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1709 | A/1C+D | 625 | 27 | 14 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1710 | A/2H+D | 1,019 | 28 | 14 | 0.101469% | \$469.38 |
| | Dwelling Unit | 1711 | A/1D+D BF | 698 | 29 | 14 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 1801 | C/2P+D | 1,056 | 1 | 15 | 0.105153% | \$486.42 |
| | Dwelling Unit | 1802 | C/1A | 557 | 2 | 15 | 0.055464% | \$256.57 |
| | Dwelling Unit | 1803 | C/1B | 572 | 3 | 15 | 0.056958% | \$263.48 |
| | Dwelling Unit | 1805 | C/2N+D BF | 1,045 | 4 | 15 | 0.104058% | \$481.36 |
| | Dwelling Unit | 1806 | C/2B | 768 | 5 | 15 | 0.076475% | \$353.76 |
| | Dwelling Unit | 1807 | C/3A | 1,009 | 6 | 15 | 0.100473% | \$464.77 |
| | Dwelling Unit | 1808 | C/1H+D | 642 | 7 | 15 | 0.063928% | \$295.72 |
| | Dwelling Unit | 1809 | C/1E+D | 625 | 8 | 15 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1810 | C/2K BF | 938 | 9 | 15 | 0.093403% | \$432.07 |
| | Dwelling Unit | 1811 | C/1K+D | 712 | 10 | 15 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 1801 | B/1B BF | 649 | 11 | 15 | 0.064625% | \$298.95 |
| | Dwelling Unit | 1802 | B/1D+D | 704 | 12 | 15 | 0.070102% | \$324.28 |
| | Dwelling Unit | 1803 | B/2H+D BF | 1,054 | 13 | 15 | 0.104954% | \$485.50 |
| | Dwelling Unit | 1805 | B/2F+D | 1,030 | 14 | 15 | 0.102564% | \$474.44 |
| | Dwelling Unit | 1806 | B/2E+D | 1,032 | 15 | 15 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1807 | B/1C+D | 681 | 16 | 15 | 0.067812% | \$313.69 |
| | Dwelling Unit | 1808 | B/2G+D | 1,032 | 17 | 15 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1809 | B/2A | 800 | 18 | 15 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1810 | B/1A+D | 643 | 19 | 15 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 1801 | A/3C | 1,201 | 20 | 15 | 0.119593% | \$553.22 |
| | Dwelling Unit | 1802 | A/2B | 742 | 21 | 15 | 0.073886% | \$341.78 |
| | Dwelling Unit | 1803 | A/2A | 725 | 22 | 15 | 0.072193% | \$333.95 |
| | Dwelling Unit | 1805 | A/2J+D | 1,081 | 23 | 15 | 0.107644% | \$497.93 |
| | Dwelling Unit | 1806 | A/2C BF | 800 | 24 | 15 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1807 | A/2K+D | 1,139 | 25 | 15 | 0.113419% | \$524.66 |
| | Dwelling Unit | 1808 | A/1C+D | 625 | 26 | 15 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1809 | A/1C+D | 625 | 27 | 15 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1810 | A/2H+D | 1,019 | 28 | 15 | 0.101469% | \$469.38 |
| | Dwelling Unit | 1811 | A/1D+D BF | 698 | 29 | 15 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 1901 | C/2P+D | 1,056 | 1 | 16 | 0.105153% | \$486.42 |
| | Dwelling Unit | 1902 | C/1A | 557 | 2 | 16 | 0.055464% | \$256.57 |
| | Dwelling Unit | 1903 | C/1B | 572 | 3 | 16 | 0.056958% | \$263.48 |
| | Dwelling Unit | 1905 | C/2N+D BF | 1,045 | 4 | 16 | 0.104058% | \$481.36 |
| | Dwelling Unit | 1906 | C/2B | 768 | 5 | 16 | 0.076475% | \$353.76 |
| | Dwelling Unit | 1907 | C/3A | 1,009 | 6 | 16 | 0.100473% | \$464.77 |
| | Dwelling Unit | 1908 | C/1H+D | 642 | 7 | 16 | 0.063928% | \$295.72 |
| | Dwelling Unit | 1909 | C/1E+D | 625 | 8 | 16 | 0.062236% | \$287.89 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 1910 | C/2K BF | 938 | 9 | 16 | 0.093403% | \$432.07 |
| | Dwelling Unit | 1911 | C/1K+D | 712 | 10 | 16 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 1901 | B/1B BF | 649 | 11 | 16 | 0.064625% | \$298.95 |
| | Dwelling Unit | 1902 | B/1D+D | 704 | 12 | 16 | 0.070102% | \$324.28 |
| | Dwelling Unit | 1903 | B/2H+D BF | 1,054 | 13 | 16 | 0.104954% | \$485.50 |
| | Dwelling Unit | 1905 | B/2F+D | 1,030 | 14 | 16 | 0.102564% | \$474.44 |
| | Dwelling Unit | 1906 | B/2E+D | 1,032 | 15 | 16 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1907 | B/1C+D | 681 | 16 | 16 | 0.067812% | \$313.69 |
| | Dwelling Unit | 1908 | B/2G+D | 1,032 | 17 | 16 | 0.102763% | \$475.37 |
| | Dwelling Unit | 1909 | B/2A | 800 | 18 | 16 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1910 | B/1A+D | 643 | 19 | 16 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 1901 | A/3C | 1,201 | 20 | 16 | 0.119593% | \$553.22 |
| | Dwelling Unit | 1902 | A/2B | 742 | 21 | 16 | 0.073886% | \$341.78 |
| | Dwelling Unit | 1903 | A/2A | 725 | 22 | 16 | 0.072193% | \$333.95 |
| | Dwelling Unit | 1905 | A/2J+D | 1,081 | 23 | 16 | 0.107644% | \$497.93 |
| | Dwelling Unit | 1906 | A/2C BF | 800 | 24 | 16 | 0.079661% | \$368.50 |
| | Dwelling Unit | 1907 | A/2K+D | 1,139 | 25 | 16 | 0.113419% | \$524.66 |
| | Dwelling Unit | 1908 | A/1C+D | 625 | 26 | 16 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1909 | A/1C+D | 625 | 27 | 16 | 0.062236% | \$287.89 |
| | Dwelling Unit | 1910 | A/2H+D | 1,019 | 28 | 16 | 0.101469% | \$469.38 |
| | Dwelling Unit | 1911 | A/1D+D BF | 698 | 29 | 16 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 2001 | C/2P+D | 1,056 | 1 | 17 | 0.105153% | \$486.42 |
| | Dwelling Unit | 2002 | C/1A | 557 | 2 | 17 | 0.055464% | \$256.57 |
| | Dwelling Unit | 2003 | C/1B | 572 | 3 | 17 | 0.056958% | \$263.48 |
| | Dwelling Unit | 2005 | C/2N+D BF | 1,045 | 4 | 17 | 0.104058% | \$481.36 |
| | Dwelling Unit | 2006 | C/2B | 768 | 5 | 17 | 0.076475% | \$353.76 |
| | Dwelling Unit | 2007 | C/3A | 1,009 | 6 | 17 | 0.100473% | \$464.77 |
| | Dwelling Unit | 2008 | C/1H+D | 642 | 7 | 17 | 0.063928% | \$295.72 |
| | Dwelling Unit | 2009 | C/1E+D | 625 | 8 | 17 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2010 | C/2K BF | 938 | 9 | 17 | 0.093403% | \$432.07 |
| | Dwelling Unit | 2011 | C/1K+D | 712 | 10 | 17 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 2001 | B/1B BF | 649 | 11 | 17 | 0.064625% | \$298.95 |
| | Dwelling Unit | 2002 | B/1D+D | 704 | 12 | 17 | 0.070102% | \$324.28 |
| | Dwelling Unit | 2003 | B/2H+D BF | 1,054 | 13 | 17 | 0.104954% | \$485.50 |
| | Dwelling Unit | 2005 | B/2F+D | 1,030 | 14 | 17 | 0.102564% | \$474.44 |
| | Dwelling Unit | 2006 | B/2E+D | 1,032 | 15 | 17 | 0.102763% | \$475.37 |
| | Dwelling Unit | 2007 | B/1C+D | 681 | 16 | 17 | 0.067812% | \$313.69 |
| | Dwelling Unit | 2008 | B/2G+D | 1,032 | 17 | 17 | 0.102763% | \$475.37 |
| | Dwelling Unit | 2009 | B/2A | 800 | 18 | 17 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2010 | B/1A+D | 643 | 19 | 17 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 2001 | A/3C | 1,201 | 20 | 17 | 0.119593% | \$553.22 |
| | Dwelling Unit | 2002 | A/2B | 742 | 21 | 17 | 0.073886% | \$341.78 |
| | Dwelling Unit | 2003 | A/2A | 725 | 22 | 17 | 0.072193% | \$333.95 |
| | Dwelling Unit | 2005 | A/2J+D | 1,081 | 23 | 17 | 0.107644% | \$497.93 |
| | Dwelling Unit | 2006 | A/2C BF | 800 | 24 | 17 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2007 | A/2K+D | 1,139 | 25 | 17 | 0.113419% | \$524.66 |
| | Dwelling Unit | 2008 | A/1C+D | 625 | 26 | 17 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2009 | A/1C+D | 625 | 27 | 17 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2010 | A/2H+D | 1,019 | 28 | 17 | 0.101469% | \$469.38 |
| | Dwelling Unit | 2011 | A/1D+D BF | 698 | 29 | 17 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | 2101 | C/2P+D | 1,056 | 1 | 18 | 0.105153% | \$486.42 |
| | Dwelling Unit | 2102 | C/1A | 557 | 2 | 18 | 0.055464% | \$256.57 |
| | Dwelling Unit | 2103 | C/1B | 572 | 3 | 18 | 0.056958% | \$263.48 |
| | Dwelling Unit | 2105 | C/2N+D BF | 1,045 | 4 | 18 | 0.104058% | \$481.36 |
| | Dwelling Unit | 2106 | C/2B | 768 | 5 | 18 | 0.076475% | \$353.76 |
| | Dwelling Unit | 2107 | C/3A | 1,009 | 6 | 18 | 0.100473% | \$464.77 |
| | Dwelling Unit | 2108 | C/1H+D | 642 | 7 | 18 | 0.063928% | \$295.72 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 2109 | C/1E+D | 625 | 8 | 18 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2110 | C/2K BF | 938 | 9 | 18 | 0.093403% | \$432.07 |
| | Dwelling Unit | 2111 | C/1K+D | 712 | 10 | 18 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 2101 | B/1B BF | 649 | 11 | 18 | 0.064625% | \$298.95 |
| | Dwelling Unit | 2102 | B/1D+D | 704 | 12 | 18 | 0.070102% | \$324.28 |
| | Dwelling Unit | 2103 | B/2H+D BF | 1,054 | 13 | 18 | 0.104954% | \$485.50 |
| | Dwelling Unit | 2105 | B/2F+D | 1,030 | 14 | 18 | 0.102564% | \$474.44 |
| | Dwelling Unit | 2106 | B/2E+D | 1,032 | 15 | 18 | 0.102763% | \$475.37 |
| | Dwelling Unit | 2107 | B/1C+D | 681 | 16 | 18 | 0.067812% | \$313.69 |
| | Dwelling Unit | 2108 | B/2G+D | 1,032 | 17 | 18 | 0.102763% | \$475.37 |
| | Dwelling Unit | 2109 | B/2A | 800 | 18 | 18 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2110 | B/1A+D | 643 | 19 | 18 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 2101 | A/3C | 1,201 | 20 | 18 | 0.119593% | \$553.22 |
| | Dwelling Unit | 2102 | A/2B | 742 | 21 | 18 | 0.073886% | \$341.78 |
| | Dwelling Unit | 2103 | A/2A | 725 | 22 | 18 | 0.072193% | \$333.95 |
| | Dwelling Unit | 2105 | A/2J+D | 1,081 | 23 | 18 | 0.107644% | \$497.93 |
| | Dwelling Unit | 2106 | A/2C BF | 800 | 24 | 18 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2107 | A/2K+D | 1,139 | 25 | 18 | 0.113419% | \$524.66 |
| | Dwelling Unit | 2108 | A/1C+D | 625 | 26 | 18 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2109 | A/1C+D | 625 | 27 | 18 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2110 | A/2H+D | 1,019 | 28 | 18 | 0.101469% | \$469.38 |
| | Dwelling Unit | 2111 | A/1D+D BF | 698 | 29 | 18 | 0.069505% | \$321.52 |
| Building C | Dwelling Unit | PH01 | C/2P+D | 1,056 | 1 | 19 | 0.105153% | \$486.42 |
| | Dwelling Unit | PH02 | C/3B | 1,123 | 2 | 19 | 0.111825% | \$517.28 |
| | Dwelling Unit | PH03 | C/2N+D BF | 1,045 | 3 | 19 | 0.104058% | \$481.36 |
| | Dwelling Unit | PH05 | C/2B | 768 | 4 | 19 | 0.076475% | \$353.76 |
| | Dwelling Unit | PH06 | C/3A | 1,009 | 5 | 19 | 0.100473% | \$464.77 |
| | Dwelling Unit | PH07 | C/1H+D | 642 | 6 | 19 | 0.063928% | \$295.72 |
| | Dwelling Unit | PH08 | C/1E+D | 625 | 7 | 19 | 0.062236% | \$287.89 |
| | Dwelling Unit | PH09 | C/2K BF | 938 | 8 | 19 | 0.093403% | \$432.07 |
| | Dwelling Unit | PH10 | C/1K+D | 712 | 9 | 19 | 0.070899% | \$327.97 |
| Building B | Dwelling Unit | 2201 | B/1B BF | 649 | 10 | 19 | 0.064625% | \$298.95 |
| | Dwelling Unit | 2202 | B/1D+D | 704 | 11 | 19 | 0.070102% | \$324.28 |
| | Dwelling Unit | 2203 | B/2H+D BF | 1,054 | 12 | 19 | 0.104954% | \$485.50 |
| | Dwelling Unit | 2205 | B/2F+D | 1,030 | 13 | 19 | 0.102564% | \$474.44 |
| | Dwelling Unit | 2206 | B/2E+D | 1,032 | 14 | 19 | 0.102763% | \$475.37 |
| | Dwelling Unit | 2207 | B/1C+D | 681 | 15 | 19 | 0.067812% | \$313.69 |
| | Dwelling Unit | 2208 | B/2G+D | 1,032 | 16 | 19 | 0.102763% | \$475.37 |
| | Dwelling Unit | 2209 | B/2A | 800 | 17 | 19 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2210 | B/1A+D | 643 | 18 | 19 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 2201 | A/3C | 1,201 | 19 | 19 | 0.119593% | \$553.22 |
| | Dwelling Unit | 2202 | A/2B | 742 | 20 | 19 | 0.073886% | \$341.78 |
| | Dwelling Unit | 2203 | A/2A | 725 | 21 | 19 | 0.072193% | \$333.95 |
| | Dwelling Unit | 2205 | A/2J+D | 1,081 | 22 | 19 | 0.107644% | \$497.93 |
| | Dwelling Unit | 2206 | A/2C BF | 800 | 23 | 19 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2207 | A/2K+D | 1,139 | 24 | 19 | 0.113419% | \$524.66 |
| | Dwelling Unit | 2208 | A/1C+D | 625 | 25 | 19 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2209 | A/1C+D | 625 | 26 | 19 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2210 | A/2H+D | 1,019 | 27 | 19 | 0.101469% | \$469.38 |
| | Dwelling Unit | 2211 | A/1D+D BF | 698 | 28 | 19 | 0.069505% | \$321.52 |
| Building B | Dwelling Unit | 2301 | B/1B BF | 649 | 1 | 20 | 0.064625% | \$298.95 |
| | Dwelling Unit | 2302 | B/1D+D | 704 | 2 | 20 | 0.070102% | \$324.28 |
| | Dwelling Unit | 2303 | B/2H+D BF | 1,054 | 3 | 20 | 0.104954% | \$485.50 |
| | Dwelling Unit | 2305 | B/2F+D | 1,030 | 4 | 20 | 0.102564% | \$474.44 |
| | Dwelling Unit | 2306 | B/2E+D | 1,032 | 5 | 20 | 0.102763% | \$475.37 |
| | Dwelling Unit | 2307 | B/1C+D | 681 | 6 | 20 | 0.067812% | \$313.69 |
| | Dwelling Unit | 2308 | B/2G+D | 1,032 | 7 | 20 | 0.102763% | \$475.37 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment | |
|---------------|---------------|---------------|-----------|---------|----------|-----------|--|-----------------------------------|----------|
| Building A | Dwelling Unit | 2309 | B/2A | 800 | 8 | 20 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 2310 | B/1A+D | 643 | 9 | 20 | 0.064028% | \$296.18 | |
| | Dwelling Unit | 2301 | A/3C | 1,201 | 10 | 20 | 0.119593% | \$553.22 | |
| | Dwelling Unit | 2302 | A/2B | 742 | 11 | 20 | 0.073886% | \$341.78 | |
| | Dwelling Unit | 2303 | A/2A | 725 | 12 | 20 | 0.072193% | \$333.95 | |
| | Dwelling Unit | 2305 | A/2J+D | 1,081 | 13 | 20 | 0.107644% | \$497.93 | |
| | Dwelling Unit | 2306 | A/2C BF | 800 | 14 | 20 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 2307 | A/2K+D | 1,139 | 15 | 20 | 0.113419% | \$524.66 | |
| | Dwelling Unit | 2308 | A/1C+D | 625 | 16 | 20 | 0.062236% | \$287.89 | |
| | Dwelling Unit | 2309 | A/1C+D | 625 | 17 | 20 | 0.062236% | \$287.89 | |
| | Dwelling Unit | 2310 | A/2H+D | 1,019 | 18 | 20 | 0.101469% | \$469.38 | |
| | Dwelling Unit | 2311 | A/1D+D BF | 698 | 19 | 20 | 0.069505% | \$321.52 | |
| Building B | Dwelling Unit | 2501 | B/1B BF | 649 | 1 | 21 | 0.064625% | \$298.95 | |
| | Dwelling Unit | 2502 | B/1D+D | 704 | 2 | 21 | 0.070102% | \$324.28 | |
| | Dwelling Unit | 2503 | B/2H+D BF | 1,054 | 3 | 21 | 0.104954% | \$485.50 | |
| | Dwelling Unit | 2505 | B/2F+D | 1,030 | 4 | 21 | 0.102564% | \$474.44 | |
| | Dwelling Unit | 2506 | B/2E+D | 1,032 | 5 | 21 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 2507 | B/1C+D | 681 | 6 | 21 | 0.067812% | \$313.69 | |
| | Dwelling Unit | 2508 | B/2G+D | 1,032 | 7 | 21 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 2509 | B/2A | 800 | 8 | 21 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 2510 | B/1A+D | 643 | 9 | 21 | 0.064028% | \$296.18 | |
| | Building A | Dwelling Unit | 2501 | A/3C | 1,201 | 10 | 21 | 0.119593% | \$553.22 |
| Dwelling Unit | | 2502 | A/2B | 742 | 11 | 21 | 0.073886% | \$341.78 | |
| Dwelling Unit | | 2503 | A/2A | 725 | 12 | 21 | 0.072193% | \$333.95 | |
| Dwelling Unit | | 2505 | A/2J+D | 1,081 | 13 | 21 | 0.107644% | \$497.93 | |
| Dwelling Unit | | 2506 | A/2C BF | 800 | 14 | 21 | 0.079661% | \$368.50 | |
| Dwelling Unit | | 2507 | A/2K+D | 1,139 | 15 | 21 | 0.113419% | \$524.66 | |
| Dwelling Unit | | 2508 | A/1C+D | 625 | 16 | 21 | 0.062236% | \$287.89 | |
| Dwelling Unit | | 2509 | A/1C+D | 625 | 17 | 21 | 0.062236% | \$287.89 | |
| Dwelling Unit | | 2510 | A/2H+D | 1,019 | 18 | 21 | 0.101469% | \$469.38 | |
| Dwelling Unit | | 2511 | A/1D+D BF | 698 | 19 | 21 | 0.069505% | \$321.52 | |
| Building B | | Dwelling Unit | 2601 | B/1B BF | 649 | 1 | 22 | 0.064625% | \$298.95 |
| | | Dwelling Unit | 2602 | B/1D+D | 704 | 2 | 22 | 0.070102% | \$324.28 |
| | Dwelling Unit | 2603 | B/2H+D BF | 1,054 | 3 | 22 | 0.104954% | \$485.50 | |
| | Dwelling Unit | 2605 | B/2F+D | 1,030 | 4 | 22 | 0.102564% | \$474.44 | |
| | Dwelling Unit | 2606 | B/2E+D | 1,032 | 5 | 22 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 2607 | B/1C+D | 681 | 6 | 22 | 0.067812% | \$313.69 | |
| | Dwelling Unit | 2608 | B/2G+D | 1,032 | 7 | 22 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 2609 | B/2A | 800 | 8 | 22 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 2610 | B/1A+D | 643 | 9 | 22 | 0.064028% | \$296.18 | |
| | Building A | Dwelling Unit | 2601 | A/3C | 1,201 | 10 | 22 | 0.119593% | \$553.22 |
| Dwelling Unit | | 2602 | A/2B | 742 | 11 | 22 | 0.073886% | \$341.78 | |
| Dwelling Unit | | 2603 | A/2A | 725 | 12 | 22 | 0.072193% | \$333.95 | |
| Dwelling Unit | | 2605 | A/2J+D | 1,081 | 13 | 22 | 0.107644% | \$497.93 | |
| Dwelling Unit | | 2606 | A/2C BF | 800 | 14 | 22 | 0.079661% | \$368.50 | |
| Dwelling Unit | | 2607 | A/2K+D | 1,139 | 15 | 22 | 0.113419% | \$524.66 | |
| Dwelling Unit | | 2608 | A/1C+D | 625 | 16 | 22 | 0.062236% | \$287.89 | |
| Dwelling Unit | | 2609 | A/1C+D | 625 | 17 | 22 | 0.062236% | \$287.89 | |
| Dwelling Unit | | 2610 | A/2H+D | 1,019 | 18 | 22 | 0.101469% | \$469.38 | |
| Dwelling Unit | | 2611 | A/1D+D BF | 698 | 19 | 22 | 0.069505% | \$321.52 | |
| Building B | | Dwelling Unit | 2701 | B/1B BF | 649 | 1 | 23 | 0.064625% | \$298.95 |
| | | Dwelling Unit | 2702 | B/1D+D | 704 | 2 | 23 | 0.070102% | \$324.28 |
| | Dwelling Unit | 2703 | B/2H+D BF | 1,054 | 3 | 23 | 0.104954% | \$485.50 | |
| | Dwelling Unit | 2705 | B/2F+D | 1,030 | 4 | 23 | 0.102564% | \$474.44 | |
| | Dwelling Unit | 2706 | B/2E+D | 1,032 | 5 | 23 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 2707 | B/1C+D | 681 | 6 | 23 | 0.067812% | \$313.69 | |
| | Dwelling Unit | 2708 | B/2G+D | 1,032 | 7 | 23 | 0.102763% | \$475.37 | |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|---------------|---------------|---------------|-----------|---------|----------|-----------|--|-----------------------------------|
| Building A | Dwelling Unit | 2709 | B/2A | 800 | 8 | 23 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2710 | B/1A+D | 643 | 9 | 23 | 0.064028% | \$296.18 |
| | Dwelling Unit | 2701 | A/3C | 1,201 | 10 | 23 | 0.119593% | \$553.22 |
| | Dwelling Unit | 2702 | A/2B | 742 | 11 | 23 | 0.073886% | \$341.78 |
| | Dwelling Unit | 2703 | A/2A | 725 | 12 | 23 | 0.072193% | \$333.95 |
| | Dwelling Unit | 2705 | A/2J+D | 1,081 | 13 | 23 | 0.107644% | \$497.93 |
| | Dwelling Unit | 2706 | A/2C BF | 800 | 14 | 23 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2707 | A/2K+D | 1,139 | 15 | 23 | 0.113419% | \$524.66 |
| | Dwelling Unit | 2708 | A/1C+D | 625 | 16 | 23 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2709 | A/1C+D | 625 | 17 | 23 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2710 | A/2H+D | 1,019 | 18 | 23 | 0.101469% | \$469.38 |
| Dwelling Unit | 2711 | A/1D+D BF | 698 | 19 | 23 | 0.069505% | \$321.52 | |
| Building B | Dwelling Unit | 2801 | B/1B BF | 649 | 1 | 24 | 0.064625% | \$298.95 |
| | Dwelling Unit | 2802 | B/1D+D | 704 | 2 | 24 | 0.070102% | \$324.28 |
| | Dwelling Unit | 2803 | B/2H+D BF | 1,054 | 3 | 24 | 0.104954% | \$485.50 |
| | Dwelling Unit | 2805 | B/2F+D | 1,030 | 4 | 24 | 0.102564% | \$474.44 |
| | Dwelling Unit | 2806 | B/2E+D | 1,032 | 5 | 24 | 0.102763% | \$475.37 |
| | Dwelling Unit | 2807 | B/1C+D | 681 | 6 | 24 | 0.067812% | \$313.69 |
| | Dwelling Unit | 2808 | B/2G+D | 1,032 | 7 | 24 | 0.102763% | \$475.37 |
| | Dwelling Unit | 2809 | B/2A | 800 | 8 | 24 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2810 | B/1A+D | 643 | 9 | 24 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 2801 | A/3C | 1,201 | 10 | 24 | 0.119593% | \$553.22 |
| | Dwelling Unit | 2802 | A/2B | 742 | 11 | 24 | 0.073886% | \$341.78 |
| | Dwelling Unit | 2803 | A/2A | 725 | 12 | 24 | 0.072193% | \$333.95 |
| | Dwelling Unit | 2805 | A/2J+D | 1,081 | 13 | 24 | 0.107644% | \$497.93 |
| | Dwelling Unit | 2806 | A/2C BF | 800 | 14 | 24 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2807 | A/2K+D | 1,139 | 15 | 24 | 0.113419% | \$524.66 |
| | Dwelling Unit | 2808 | A/1C+D | 625 | 16 | 24 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2809 | A/1C+D | 625 | 17 | 24 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2810 | A/2H+D | 1,019 | 18 | 24 | 0.101469% | \$469.38 |
| | Dwelling Unit | 2811 | A/1D+D BF | 698 | 19 | 24 | 0.069505% | \$321.52 |
| | Building B | Dwelling Unit | 2901 | B/1B BF | 649 | 1 | 25 | 0.064625% |
| Dwelling Unit | | 2902 | B/1D+D | 704 | 2 | 25 | 0.070102% | \$324.28 |
| Dwelling Unit | | 2903 | B/2H+D BF | 1,054 | 3 | 25 | 0.104954% | \$485.50 |
| Dwelling Unit | | 2905 | B/2F+D | 1,030 | 4 | 25 | 0.102564% | \$474.44 |
| Dwelling Unit | | 2906 | B/2E+D | 1,032 | 5 | 25 | 0.102763% | \$475.37 |
| Dwelling Unit | | 2907 | B/1C+D | 681 | 6 | 25 | 0.067812% | \$313.69 |
| Dwelling Unit | | 2908 | B/2G+D | 1,032 | 7 | 25 | 0.102763% | \$475.37 |
| Dwelling Unit | | 2909 | B/2A | 800 | 8 | 25 | 0.079661% | \$368.50 |
| Dwelling Unit | | 2910 | B/1A+D | 643 | 9 | 25 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 2901 | A/3C | 1,201 | 10 | 25 | 0.119593% | \$553.22 |
| | Dwelling Unit | 2902 | A/2B | 742 | 11 | 25 | 0.073886% | \$341.78 |
| | Dwelling Unit | 2903 | A/2A | 725 | 12 | 25 | 0.072193% | \$333.95 |
| | Dwelling Unit | 2905 | A/2J+D | 1,081 | 13 | 25 | 0.107644% | \$497.93 |
| | Dwelling Unit | 2906 | A/2C BF | 800 | 14 | 25 | 0.079661% | \$368.50 |
| | Dwelling Unit | 2907 | A/2K+D | 1,139 | 15 | 25 | 0.113419% | \$524.66 |
| | Dwelling Unit | 2908 | A/1C+D | 625 | 16 | 25 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2909 | A/1C+D | 625 | 17 | 25 | 0.062236% | \$287.89 |
| | Dwelling Unit | 2910 | A/2H+D | 1,019 | 18 | 25 | 0.101469% | \$469.38 |
| | Dwelling Unit | 2911 | A/1D+D BF | 698 | 19 | 25 | 0.069505% | \$321.52 |
| | Building B | Dwelling Unit | 3001 | B/1B BF | 649 | 1 | 26 | 0.064625% |
| Dwelling Unit | | 3002 | B/1D+D | 704 | 2 | 26 | 0.070102% | \$324.28 |
| Dwelling Unit | | 3003 | B/2H+D BF | 1,054 | 3 | 26 | 0.104954% | \$485.50 |
| Dwelling Unit | | 3005 | B/2F+D | 1,030 | 4 | 26 | 0.102564% | \$474.44 |
| Dwelling Unit | | 3006 | B/2E+D | 1,032 | 5 | 26 | 0.102763% | \$475.37 |
| Dwelling Unit | | 3007 | B/1C+D | 681 | 6 | 26 | 0.067812% | \$313.69 |
| Dwelling Unit | | 3008 | B/2G+D | 1,032 | 7 | 26 | 0.102763% | \$475.37 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 3009 | B/2A | 800 | 8 | 26 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3010 | B/1A+D | 643 | 9 | 26 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 3001 | A/3C | 1,201 | 10 | 26 | 0.119593% | \$553.22 |
| | Dwelling Unit | 3002 | A/2B | 742 | 11 | 26 | 0.073886% | \$341.78 |
| | Dwelling Unit | 3003 | A/2A | 725 | 12 | 26 | 0.072193% | \$333.95 |
| | Dwelling Unit | 3005 | A/2J+D | 1,081 | 13 | 26 | 0.107644% | \$497.93 |
| | Dwelling Unit | 3006 | A/2C BF | 800 | 14 | 26 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3007 | A/2K+D | 1,139 | 15 | 26 | 0.113419% | \$524.66 |
| | Dwelling Unit | 3008 | A/1C+D | 625 | 16 | 26 | 0.062236% | \$287.89 |
| | Dwelling Unit | 3009 | A/1C+D | 625 | 17 | 26 | 0.062236% | \$287.89 |
| | Dwelling Unit | 3010 | A/2H+D | 1,019 | 18 | 26 | 0.101469% | \$469.38 |
| | Dwelling Unit | 3011 | A/1D+D BF | 698 | 19 | 26 | 0.069505% | \$321.52 |
| Building B | Dwelling Unit | 3101 | B/1B BF | 649 | 1 | 27 | 0.064625% | \$298.95 |
| | Dwelling Unit | 3102 | B/1D+D | 704 | 2 | 27 | 0.070102% | \$324.28 |
| | Dwelling Unit | 3103 | B/2H+D BF | 1,054 | 3 | 27 | 0.104954% | \$485.50 |
| | Dwelling Unit | 3105 | B/2F+D | 1,030 | 4 | 27 | 0.102564% | \$474.44 |
| | Dwelling Unit | 3106 | B/2E+D | 1,032 | 5 | 27 | 0.102763% | \$475.37 |
| | Dwelling Unit | 3107 | B/1C+D | 681 | 6 | 27 | 0.067812% | \$313.69 |
| | Dwelling Unit | 3108 | B/2G+D | 1,032 | 7 | 27 | 0.102763% | \$475.37 |
| | Dwelling Unit | 3109 | B/2A | 800 | 8 | 27 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3110 | B/1A+D | 643 | 9 | 27 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 3101 | A/3C | 1,201 | 10 | 27 | 0.119593% | \$553.22 |
| | Dwelling Unit | 3102 | A/2B | 742 | 11 | 27 | 0.073886% | \$341.78 |
| | Dwelling Unit | 3103 | A/2A | 725 | 12 | 27 | 0.072193% | \$333.95 |
| | Dwelling Unit | 3105 | A/2J+D | 1,081 | 13 | 27 | 0.107644% | \$497.93 |
| | Dwelling Unit | 3106 | A/2C BF | 800 | 14 | 27 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3107 | A/2K+D | 1,139 | 15 | 27 | 0.113419% | \$524.66 |
| | Dwelling Unit | 3108 | A/1C+D | 625 | 16 | 27 | 0.062236% | \$287.89 |
| | Dwelling Unit | 3109 | A/1C+D | 625 | 17 | 27 | 0.062236% | \$287.89 |
| | Dwelling Unit | 3110 | A/2H+D | 1,019 | 18 | 27 | 0.101469% | \$469.38 |
| | Dwelling Unit | 3111 | A/1D+D BF | 698 | 19 | 27 | 0.069505% | \$321.52 |
| Building B | Dwelling Unit | 3201 | B/1B BF | 649 | 1 | 28 | 0.064625% | \$298.95 |
| | Dwelling Unit | 3202 | B/1D+D | 704 | 2 | 28 | 0.070102% | \$324.28 |
| | Dwelling Unit | 3203 | B/2H+D BF | 1,054 | 3 | 28 | 0.104954% | \$485.50 |
| | Dwelling Unit | 3205 | B/2F+D | 1,030 | 4 | 28 | 0.102564% | \$474.44 |
| | Dwelling Unit | 3206 | B/2E+D | 1,032 | 5 | 28 | 0.102763% | \$475.37 |
| | Dwelling Unit | 3207 | B/1C+D | 681 | 6 | 28 | 0.067812% | \$313.69 |
| | Dwelling Unit | 3208 | B/2G+D | 1,032 | 7 | 28 | 0.102763% | \$475.37 |
| | Dwelling Unit | 3209 | B/2A | 800 | 8 | 28 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3210 | B/1A+D | 643 | 9 | 28 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 3201 | A/3C | 1,201 | 10 | 28 | 0.119593% | \$553.22 |
| | Dwelling Unit | 3202 | A/2B | 742 | 11 | 28 | 0.073886% | \$341.78 |
| | Dwelling Unit | 3203 | A/2A | 725 | 12 | 28 | 0.072193% | \$333.95 |
| | Dwelling Unit | 3205 | A/2J+D | 1,081 | 13 | 28 | 0.107644% | \$497.93 |
| | Dwelling Unit | 3206 | A/2C BF | 800 | 14 | 28 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3207 | A/2K+D | 1,139 | 15 | 28 | 0.113419% | \$524.66 |
| | Dwelling Unit | 3208 | A/1C+D | 625 | 16 | 28 | 0.062236% | \$287.89 |
| | Dwelling Unit | 3209 | A/1C+D | 625 | 17 | 28 | 0.062236% | \$287.89 |
| | Dwelling Unit | 3210 | A/2H+D | 1,019 | 18 | 28 | 0.101469% | \$469.38 |
| | Dwelling Unit | 3211 | A/1D+D BF | 698 | 19 | 28 | 0.069505% | \$321.52 |
| Building B | Dwelling Unit | 3301 | B/1B BF | 649 | 1 | 29 | 0.064625% | \$298.95 |
| | Dwelling Unit | 3302 | B/1D+D | 704 | 2 | 29 | 0.070102% | \$324.28 |
| | Dwelling Unit | 3303 | B/2H+D BF | 1,054 | 3 | 29 | 0.104954% | \$485.50 |
| | Dwelling Unit | 3305 | B/2F+D | 1,030 | 4 | 29 | 0.102564% | \$474.44 |
| | Dwelling Unit | 3306 | B/2E+D | 1,032 | 5 | 29 | 0.102763% | \$475.37 |
| | Dwelling Unit | 3307 | B/1C+D | 681 | 6 | 29 | 0.067812% | \$313.69 |
| | Dwelling Unit | 3308 | B/2G+D | 1,032 | 7 | 29 | 0.102763% | \$475.37 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses based as percentages to etc | Monthly Common Element Assessment | |
|---------------|---------------|---------------|-----------|---------|----------|-----------|---|-----------------------------------|----------|
| Building A | Dwelling Unit | 3309 | B/2A | 800 | 8 | 29 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 3310 | B/1A+D | 643 | 9 | 29 | 0.064028% | \$296.18 | |
| | Dwelling Unit | 3301 | A/3C | 1,201 | 10 | 29 | 0.119593% | \$553.22 | |
| | Dwelling Unit | 3302 | A/2B | 742 | 11 | 29 | 0.073886% | \$341.78 | |
| | Dwelling Unit | 3303 | A/2A | 725 | 12 | 29 | 0.072193% | \$333.95 | |
| | Dwelling Unit | 3305 | A/2J+D | 1,081 | 13 | 29 | 0.107644% | \$497.93 | |
| | Dwelling Unit | 3306 | A/2C BF | 800 | 14 | 29 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 3307 | A/2K+D | 1,139 | 15 | 29 | 0.113419% | \$524.66 | |
| | Dwelling Unit | 3308 | A/1C+D | 625 | 16 | 29 | 0.062236% | \$287.89 | |
| | Dwelling Unit | 3309 | A/1C+D | 625 | 17 | 29 | 0.062236% | \$287.89 | |
| | Dwelling Unit | 3310 | A/2H+D | 1,019 | 18 | 29 | 0.101469% | \$469.38 | |
| | Dwelling Unit | 3311 | A/1D+D BF | 698 | 19 | 29 | 0.069505% | \$321.52 | |
| Building B | Dwelling Unit | 3501 | B/1B BF | 649 | 1 | 30 | 0.064625% | \$298.95 | |
| | Dwelling Unit | 3502 | B/1D+D | 704 | 2 | 30 | 0.070102% | \$324.28 | |
| | Dwelling Unit | 3503 | B/2H+D BF | 1,054 | 3 | 30 | 0.104954% | \$485.50 | |
| | Dwelling Unit | 3505 | B/2F+D | 1,030 | 4 | 30 | 0.102564% | \$474.44 | |
| | Dwelling Unit | 3506 | B/2E+D | 1,032 | 5 | 30 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 3507 | B/1C+D | 681 | 6 | 30 | 0.067812% | \$313.69 | |
| | Dwelling Unit | 3508 | B/2G+D | 1,032 | 7 | 30 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 3509 | B/2A | 800 | 8 | 30 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 3510 | B/1A+D | 643 | 9 | 30 | 0.064028% | \$296.18 | |
| | Building A | Dwelling Unit | 3501 | A/3C | 1,201 | 10 | 30 | 0.119593% | \$553.22 |
| Dwelling Unit | | 3502 | A/2B | 742 | 11 | 30 | 0.073886% | \$341.78 | |
| Dwelling Unit | | 3503 | A/2A | 725 | 12 | 30 | 0.072193% | \$333.95 | |
| Dwelling Unit | | 3505 | A/2J+D | 1,081 | 13 | 30 | 0.107644% | \$497.93 | |
| Dwelling Unit | | 3506 | A/2C BF | 800 | 14 | 30 | 0.079661% | \$368.50 | |
| Dwelling Unit | | 3507 | A/2K+D | 1,139 | 15 | 30 | 0.113419% | \$524.66 | |
| Dwelling Unit | | 3508 | A/1C+D | 625 | 16 | 30 | 0.062236% | \$287.89 | |
| Dwelling Unit | | 3509 | A/1C+D | 625 | 17 | 30 | 0.062236% | \$287.89 | |
| Dwelling Unit | | 3510 | A/2H+D | 1,019 | 18 | 30 | 0.101469% | \$469.38 | |
| Dwelling Unit | | 3511 | A/1D+D BF | 698 | 19 | 30 | 0.069505% | \$321.52 | |
| Building B | | Dwelling Unit | 3601 | B/1B BF | 649 | 1 | 31 | 0.064625% | \$298.95 |
| | | Dwelling Unit | 3602 | B/1D+D | 704 | 2 | 31 | 0.070102% | \$324.28 |
| | Dwelling Unit | 3603 | B/2H+D BF | 1,054 | 3 | 31 | 0.104954% | \$485.50 | |
| | Dwelling Unit | 3605 | B/2F+D | 1,030 | 4 | 31 | 0.102564% | \$474.44 | |
| | Dwelling Unit | 3606 | B/2E+D | 1,032 | 5 | 31 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 3607 | B/1C+D | 681 | 6 | 31 | 0.067812% | \$313.69 | |
| | Dwelling Unit | 3608 | B/2G+D | 1,032 | 7 | 31 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 3609 | B/2A | 800 | 8 | 31 | 0.079661% | \$368.50 | |
| | Dwelling Unit | 3610 | B/1A+D | 643 | 9 | 31 | 0.064028% | \$296.18 | |
| | Building A | Dwelling Unit | 3601 | A/3C | 1,201 | 10 | 31 | 0.119593% | \$553.22 |
| Dwelling Unit | | 3602 | A/2B | 742 | 11 | 31 | 0.073886% | \$341.78 | |
| Dwelling Unit | | 3603 | A/2A | 725 | 12 | 31 | 0.072193% | \$333.95 | |
| Dwelling Unit | | 3605 | A/2J+D | 1,081 | 13 | 31 | 0.107644% | \$497.93 | |
| Dwelling Unit | | 3606 | A/2C BF | 800 | 14 | 31 | 0.079661% | \$368.50 | |
| Dwelling Unit | | 3607 | A/2K+D | 1,139 | 15 | 31 | 0.113419% | \$524.66 | |
| Dwelling Unit | | 3608 | A/1C+D | 625 | 16 | 31 | 0.062236% | \$287.89 | |
| Dwelling Unit | | 3609 | A/1C+D | 625 | 17 | 31 | 0.062236% | \$287.89 | |
| Dwelling Unit | | 3610 | A/2H+D | 1,019 | 18 | 31 | 0.101469% | \$469.38 | |
| Dwelling Unit | | 3611 | A/1D+D BF | 698 | 19 | 31 | 0.069505% | \$321.52 | |
| Building B | | Dwelling Unit | 3701 | B/1B BF | 649 | 1 | 32 | 0.064625% | \$298.95 |
| | | Dwelling Unit | 3702 | B/1D+D | 704 | 2 | 32 | 0.070102% | \$324.28 |
| | Dwelling Unit | 3703 | B/2H+D BF | 1,054 | 3 | 32 | 0.104954% | \$485.50 | |
| | Dwelling Unit | 3705 | B/2F+D | 1,030 | 4 | 32 | 0.102564% | \$474.44 | |
| | Dwelling Unit | 3706 | B/2E+D | 1,032 | 5 | 32 | 0.102763% | \$475.37 | |
| | Dwelling Unit | 3707 | B/1C+D | 681 | 6 | 32 | 0.067812% | \$313.69 | |
| | Dwelling Unit | 3708 | B/2G+D | 1,032 | 7 | 32 | 0.102763% | \$475.37 | |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|-------------------|---------------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 3709 | B/2A | 800 | 8 | 32 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3710 | B/1A+D | 643 | 9 | 32 | 0.064028% | \$296.18 |
| Building A | Dwelling Unit | 3701 | A/3C | 1,201 | 10 | 32 | 0.119593% | \$553.22 |
| | Dwelling Unit | 3702 | A/2B | 742 | 11 | 32 | 0.073886% | \$341.78 |
| | Dwelling Unit | 3703 | A/2A | 725 | 12 | 32 | 0.072193% | \$333.95 |
| | Dwelling Unit | 3705 | A/2J+D | 1,081 | 13 | 32 | 0.107644% | \$497.93 |
| | Dwelling Unit | 3706 | A/2C BF | 800 | 14 | 32 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3707 | A/2K+D | 1,139 | 15 | 32 | 0.113419% | \$524.66 |
| | Dwelling Unit | 3708 | A/1C+D | 625 | 16 | 32 | 0.062236% | \$287.89 |
| | Dwelling Unit | 3709 | A/1C+D | 625 | 17 | 32 | 0.062236% | \$287.89 |
| | Dwelling Unit | 3710 | A/2H+D | 1,019 | 18 | 32 | 0.101469% | \$469.38 |
| | Dwelling Unit | 3711 | A/1D+D BF | 698 | 19 | 32 | 0.069505% | \$321.52 |
| Building B | Dwelling Unit | 3801 | B/1B BF | 649 | 1 | 33 | 0.064625% | \$298.95 |
| | Dwelling Unit | 3802 | B/1D+D | 704 | 2 | 33 | 0.070102% | \$324.28 |
| | Dwelling Unit | 3803 | B/2H+D BF | 1,054 | 3 | 33 | 0.104954% | \$485.50 |
| | Dwelling Unit | 3805 | B/2F+D | 1,030 | 4 | 33 | 0.102564% | \$474.44 |
| | Dwelling Unit | 3806 | B/2E+D | 1,032 | 5 | 33 | 0.102763% | \$475.37 |
| | Dwelling Unit | 3807 | B/1C+D | 681 | 6 | 33 | 0.067812% | \$313.69 |
| | Dwelling Unit | 3808 | B/2G+D | 1,032 | 7 | 33 | 0.102763% | \$475.37 |
| | Dwelling Unit | 3809 | B/2A | 800 | 8 | 33 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3810 | B/1A+D | 643 | 9 | 33 | 0.064028% | \$296.18 |
| | Building A | Dwelling Unit | 3801 | A/3C | 1,201 | 10 | 33 | 0.119593% |
| Dwelling Unit | | 3802 | A/2B | 742 | 11 | 33 | 0.073886% | \$341.78 |
| Dwelling Unit | | 3803 | A/2A | 725 | 12 | 33 | 0.072193% | \$333.95 |
| Dwelling Unit | | 3805 | A/2J+D | 1,081 | 13 | 33 | 0.107644% | \$497.93 |
| Dwelling Unit | | 3806 | A/2C BF | 800 | 14 | 33 | 0.079661% | \$368.50 |
| Dwelling Unit | | 3807 | A/2K+D | 1,139 | 15 | 33 | 0.113419% | \$524.66 |
| Dwelling Unit | | 3808 | A/1C+D | 625 | 16 | 33 | 0.062236% | \$287.89 |
| Dwelling Unit | | 3809 | A/1C+D | 625 | 17 | 33 | 0.062236% | \$287.89 |
| Dwelling Unit | | 3810 | A/2H+D | 1,019 | 18 | 33 | 0.101469% | \$469.38 |
| Dwelling Unit | | 3811 | A/1D+D BF | 698 | 19 | 33 | 0.069505% | \$321.52 |
| Building B | Dwelling Unit | 3901 | B/1B BF | 649 | 1 | 34 | 0.064625% | \$298.95 |
| | Dwelling Unit | 3902 | B/1D+D | 704 | 2 | 34 | 0.070102% | \$324.28 |
| | Dwelling Unit | 3903 | B/2H+D BF | 1,054 | 3 | 34 | 0.104954% | \$485.50 |
| | Dwelling Unit | 3905 | B/2F+D | 1,030 | 4 | 34 | 0.102564% | \$474.44 |
| | Dwelling Unit | 3906 | B/2E+D | 1,032 | 5 | 34 | 0.102763% | \$475.37 |
| | Dwelling Unit | 3907 | B/1C+D | 681 | 6 | 34 | 0.067812% | \$313.69 |
| | Dwelling Unit | 3908 | B/2G+D | 1,032 | 7 | 34 | 0.102763% | \$475.37 |
| | Dwelling Unit | 3909 | B/2A | 800 | 8 | 34 | 0.079661% | \$368.50 |
| | Dwelling Unit | 3910 | B/1A+D | 643 | 9 | 34 | 0.064028% | \$296.18 |
| | Building A | Dwelling Unit | 3901 | A/3C | 1,201 | 10 | 34 | 0.119593% |
| Dwelling Unit | | 3902 | A/2B | 742 | 11 | 34 | 0.073886% | \$341.78 |
| Dwelling Unit | | 3903 | A/2A | 725 | 12 | 34 | 0.072193% | \$333.95 |
| Dwelling Unit | | 3905 | A/2J+D | 1,081 | 13 | 34 | 0.107644% | \$497.93 |
| Dwelling Unit | | 3906 | A/2C BF | 800 | 14 | 34 | 0.079661% | \$368.50 |
| Dwelling Unit | | 3907 | A/2K+D | 1,139 | 15 | 34 | 0.113419% | \$524.66 |
| Dwelling Unit | | 3908 | A/1C+D | 625 | 16 | 34 | 0.062236% | \$287.89 |
| Dwelling Unit | | 3909 | A/1C+D | 625 | 17 | 34 | 0.062236% | \$287.89 |
| Dwelling Unit | | 3910 | A/2H+D | 1,019 | 18 | 34 | 0.101469% | \$469.38 |
| Dwelling Unit | | 3911 | A/1D+D BF | 698 | 19 | 34 | 0.069505% | \$321.52 |
| Building B | Dwelling Unit | PH01 | B/2K | 1,411 | 1 | 35 | 0.140503% | \$649.94 |
| | Dwelling Unit | PH02 | B/2J | 1,365 | 2 | 35 | 0.135922% | \$628.75 |
| | Dwelling Unit | PH03 | B/2L | 1,605 | 3 | 35 | 0.159821% | \$739.31 |
| | Dwelling Unit | PH05 | B/3B+D | 1,904 | 4 | 35 | 0.189594% | \$877.03 |
| | Dwelling Unit | PH06 | B/3C | 1,918 | 5 | 35 | 0.190988% | \$883.48 |
| | Dwelling Unit | PH07 | B/2M+D | 1,660 | 6 | 35 | 0.165298% | \$764.64 |
| | Dwelling Unit | PH08 | B/2P+D | 1,875 | 7 | 35 | 0.186707% | \$863.68 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|---------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | PH09 | B/2N+D | 1,569 | 8 | 35 | 0.156236% | \$722.72 |
| | Dwelling Unit | PH10 | B/2Q+D | 1,330 | 9 | 35 | 0.132437% | \$612.63 |
| Building A | Dwelling Unit | 4001 | A/3C | 1,201 | 10 | 35 | 0.119593% | \$553.22 |
| | Dwelling Unit | 4002 | A/2B | 742 | 11 | 35 | 0.073886% | \$341.78 |
| | Dwelling Unit | 4003 | A/2A | 725 | 12 | 35 | 0.072193% | \$333.95 |
| | Dwelling Unit | 4005 | A/2J+D | 1,081 | 13 | 35 | 0.107644% | \$497.93 |
| | Dwelling Unit | 4006 | A/2C BF | 800 | 14 | 35 | 0.079661% | \$368.50 |
| | Dwelling Unit | 4007 | A/2K+D | 1,139 | 15 | 35 | 0.113419% | \$524.66 |
| | Dwelling Unit | 4008 | A/1C+D | 625 | 16 | 35 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4009 | A/1C+D | 625 | 17 | 35 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4010 | A/2H+D | 1,019 | 18 | 35 | 0.101469% | \$469.38 |
| | Dwelling Unit | 4011 | A/1D+D BF | 698 | 19 | 35 | 0.069505% | \$321.52 |
| Building A | Dwelling Unit | 4101 | A/3C | 1,201 | 1 | 36 | 0.119593% | \$553.22 |
| | Dwelling Unit | 4102 | A/2B | 742 | 2 | 36 | 0.073886% | \$341.78 |
| | Dwelling Unit | 4103 | A/2A | 725 | 3 | 36 | 0.072193% | \$333.95 |
| | Dwelling Unit | 4105 | A/2J+D | 1,081 | 4 | 36 | 0.107644% | \$497.93 |
| | Dwelling Unit | 4106 | A/2C BF | 800 | 5 | 36 | 0.079661% | \$368.50 |
| | Dwelling Unit | 4107 | A/2K+D | 1,139 | 6 | 36 | 0.113419% | \$524.66 |
| | Dwelling Unit | 4108 | A/1C+D | 625 | 7 | 36 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4109 | A/1C+D | 625 | 8 | 36 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4110 | A/2H+D | 1,019 | 9 | 36 | 0.101469% | \$469.38 |
| | Dwelling Unit | 4111 | A/1D+D BF | 698 | 10 | 36 | 0.069505% | \$321.52 |
| Building A | Dwelling Unit | 4201 | A/3C | 1,201 | 1 | 37 | 0.119593% | \$553.22 |
| | Dwelling Unit | 4202 | A/2B | 742 | 2 | 37 | 0.073886% | \$341.78 |
| | Dwelling Unit | 4203 | A/2A | 725 | 3 | 37 | 0.072193% | \$333.95 |
| | Dwelling Unit | 4205 | A/2J+D | 1,081 | 4 | 37 | 0.107644% | \$497.93 |
| | Dwelling Unit | 4206 | A/2C BF | 800 | 5 | 37 | 0.079661% | \$368.50 |
| | Dwelling Unit | 4207 | A/2K+D | 1,139 | 6 | 37 | 0.113419% | \$524.66 |
| | Dwelling Unit | 4208 | A/1C+D | 625 | 7 | 37 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4209 | A/1C+D | 625 | 8 | 37 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4210 | A/2H+D | 1,019 | 9 | 37 | 0.101469% | \$469.38 |
| | Dwelling Unit | 4211 | A/1D+D BF | 698 | 10 | 37 | 0.069505% | \$321.52 |
| Building A | Dwelling Unit | 4301 | A/3C | 1,201 | 1 | 38 | 0.119593% | \$553.22 |
| | Dwelling Unit | 4302 | A/2B | 742 | 2 | 38 | 0.073886% | \$341.78 |
| | Dwelling Unit | 4303 | A/2A | 725 | 3 | 38 | 0.072193% | \$333.95 |
| | Dwelling Unit | 4305 | A/2J+D | 1,081 | 4 | 38 | 0.107644% | \$497.93 |
| | Dwelling Unit | 4306 | A/2C BF | 800 | 5 | 38 | 0.079661% | \$368.50 |
| | Dwelling Unit | 4307 | A/2K+D | 1,139 | 6 | 38 | 0.113419% | \$524.66 |
| | Dwelling Unit | 4308 | A/1C+D | 625 | 7 | 38 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4309 | A/1C+D | 625 | 8 | 38 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4310 | A/2H+D | 1,019 | 9 | 38 | 0.101469% | \$469.38 |
| | Dwelling Unit | 4311 | A/1D+D BF | 698 | 10 | 38 | 0.069505% | \$321.52 |
| Building A | Dwelling Unit | 4501 | A/3C | 1,201 | 1 | 39 | 0.119593% | \$553.22 |
| | Dwelling Unit | 4502 | A/2B | 742 | 2 | 39 | 0.073886% | \$341.78 |
| | Dwelling Unit | 4503 | A/2A | 725 | 3 | 39 | 0.072193% | \$333.95 |
| | Dwelling Unit | 4505 | A/2J+D | 1,081 | 4 | 39 | 0.107644% | \$497.93 |
| | Dwelling Unit | 4506 | A/2C BF | 800 | 5 | 39 | 0.079661% | \$368.50 |
| | Dwelling Unit | 4507 | A/2K+D | 1,139 | 6 | 39 | 0.113419% | \$524.66 |
| | Dwelling Unit | 4508 | A/1C+D | 625 | 7 | 39 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4509 | A/1C+D | 625 | 8 | 39 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4510 | A/2H+D | 1,019 | 9 | 39 | 0.101469% | \$469.38 |
| | Dwelling Unit | 4511 | A/1D+D BF | 698 | 10 | 39 | 0.069505% | \$321.52 |
| Building A | Dwelling Unit | 4601 | A/3C | 1,201 | 1 | 40 | 0.119593% | \$553.22 |
| | Dwelling Unit | 4602 | A/2B | 742 | 2 | 40 | 0.073886% | \$341.78 |
| | Dwelling Unit | 4603 | A/2A | 725 | 3 | 40 | 0.072193% | \$333.95 |
| | Dwelling Unit | 4605 | A/2J+D | 1,081 | 4 | 40 | 0.107644% | \$497.93 |
| | Dwelling Unit | 4606 | A/2C BF | 800 | 5 | 40 | 0.079661% | \$368.50 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|-------------------|------------------------------|-----------|-----------|-------|----------|-----------|--|-----------------------------------|
| | Dwelling Unit | 4607 | A/2K+D | 1,139 | 6 | 40 | 0.113419% | \$524.66 |
| | Dwelling Unit | 4608 | A/1C+D | 625 | 7 | 40 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4609 | A/1C+D | 625 | 8 | 40 | 0.062236% | \$287.89 |
| | Dwelling Unit | 4610 | A/2H+D | 1,019 | 9 | 40 | 0.101469% | \$469.38 |
| | Dwelling Unit | 4611 | A/1D+D BF | 698 | 10 | 40 | 0.069505% | \$321.52 |
| Building A | Dwelling Unit | LPH01 | A/3K | 1,609 | 1 | 41 | 0.160220% | \$741.14 |
| | Dwelling Unit | LPH02 | A/2L+D | 1,372 | 2 | 41 | 0.136620% | \$631.98 |
| | Dwelling Unit | LPH03 | A/3L+D | 1,676 | 3 | 41 | 0.166891% | \$772.01 |
| | Dwelling Unit | LPH05 | A/3H | 1,309 | 4 | 41 | 0.130346% | \$602.96 |
| | Dwelling Unit | LPH06 | A/3F | 1,253 | 5 | 41 | 0.124770% | \$577.17 |
| | Dwelling Unit | LPH07 | A/3G+D | 1,291 | 6 | 41 | 0.128554% | \$594.67 |
| Building A | Dwelling Unit | UPH01 | A/3M | 2,981 | 1 | 42 | 0.296840% | \$1,373.12 |
| | Dwelling Unit | UPH03 | A/3L+D | 1,676 | 2 | 42 | 0.166891% | \$772.01 |
| | Dwelling Unit | UPH05 | A/3H | 1,309 | 3 | 42 | 0.130346% | \$602.96 |
| | Dwelling Unit | UPH06 | A/3F | 1,253 | 4 | 42 | 0.124770% | \$577.17 |
| | Dwelling Unit | UPH07 | A/3G+D | 1,291 | 5 | 42 | 0.128554% | \$594.67 |
| | Parking Unit (Tandem) | | | N/A | 1 | A | 0.009263% | \$42.85 |
| | Parking/Locker Unit (Tandem) | | | N/A | 2 | A | 0.010422% | \$48.21 |
| | Parking/Locker Unit (Tandem) | | | N/A | 3 | A | 0.010422% | \$48.21 |
| | Parking/Locker Unit (Tandem) | | | N/A | 4 | A | 0.010422% | \$48.21 |
| | Parking/Locker Unit (Tandem) | | | N/A | 5 | A | 0.010422% | \$48.21 |
| | Parking/Locker Unit (Tandem) | | | N/A | 6 | A | 0.010422% | \$48.21 |
| | Parking/Locker Unit (Tandem) | | | N/A | 7 | A | 0.010422% | \$48.21 |
| | Parking Unit (Tandem) | | | N/A | 8 | A | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 9 | A | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 10 | A | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 11 | A | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 12 | A | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 13 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 14 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 15 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 16 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 17 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 18 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 19 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 20 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 21 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 22 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 23 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 24 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 25 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 26 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 27 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 28 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 29 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 30 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 31 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 32 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 33 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 34 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 35 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 36 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 37 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 38 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 39 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 40 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 41 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 42 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 43 | A | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 44 | A | 0.009263% | \$42.85 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|--------------------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit (Tandem) | | | N/A | 45 | A | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 46 | A | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 47 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 48 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 49 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 50 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 51 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 52 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 53 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 54 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 55 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 56 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 57 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 58 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 59 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 60 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 61 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 62 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 63 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 64 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 65 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 66 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 67 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 68 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 69 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 70 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 71 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 72 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 73 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 74 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 75 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 76 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 77 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 78 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Parking Unit | | | N/A | 79 | A | 0.008104% | \$37.49 |
| | Commercial/Retail Storage Unit | | | N/A | 80 | A | 0.004631% | \$21.42 |
| | Commercial/Retail Storage Unit | | | N/A | 81 | A | 0.004631% | \$21.42 |
| | Commercial/Retail Storage Unit | | | N/A | 82 | A | 0.004631% | \$21.42 |
| | Commercial/Retail Storage Unit | | | N/A | 83 | A | 0.004631% | \$21.42 |
| | Commercial/Retail Storage Unit | | | N/A | 84 | A | 0.004631% | \$21.42 |
| | Commercial/Retail Storage Unit | | | N/A | 85 | A | 0.004631% | \$21.42 |
| | Commercial/Retail Storage Unit | | | N/A | 86 | A | 0.004631% | \$21.42 |
| | Locker Unit | | | N/A | 87 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 88 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 89 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 90 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 91 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 92 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 93 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 94 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 95 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 96 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 97 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 98 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 99 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 100 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 101 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 102 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 103 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 104 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 105 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 106 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 107 | A | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 108 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 109 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 110 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 111 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 112 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 113 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 114 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 115 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 116 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 117 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 118 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 119 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 120 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 121 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 122 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 123 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 124 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 125 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 126 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 127 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 128 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 129 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 130 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 131 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 132 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 133 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 134 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 135 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 136 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 137 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 138 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 139 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 140 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 141 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 142 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 143 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 144 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 145 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 146 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 147 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 148 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 149 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 150 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 151 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 152 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 153 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 154 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 155 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 156 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 157 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 158 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 159 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 160 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 161 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 162 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 163 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 164 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 165 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 166 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 167 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 168 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 169 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 170 | A | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 171 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 172 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 173 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 174 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 175 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 176 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 177 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 178 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 179 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 180 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 181 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 182 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 183 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 184 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 185 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 186 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 187 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 188 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 189 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 190 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 191 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 192 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 193 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 194 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 195 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 196 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 197 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 198 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 199 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 200 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 201 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 202 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 203 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 204 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 205 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 206 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 207 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 208 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 209 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 210 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 211 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 212 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 213 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 214 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 215 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 216 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 217 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 218 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 219 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 220 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 221 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 222 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 223 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 224 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 225 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 226 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 227 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 228 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 229 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 230 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 231 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 232 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 233 | A | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|--------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 234 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 235 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 236 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 237 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 238 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 239 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 240 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 241 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 242 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 243 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 244 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 245 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 246 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 247 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 248 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 249 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 250 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 251 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 252 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 253 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 254 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 255 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 256 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 257 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 258 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 259 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 260 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 261 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 262 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 263 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 264 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 265 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 266 | A | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 267 | A | 0.001853% | \$8.57 |
| | Parking Unit | | | N/A | 268 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 269 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 270 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 271 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 272 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 273 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 274 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 275 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 276 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 277 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 278 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 279 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 280 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 281 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 282 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 283 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 284 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 285 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 286 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 287 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 288 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 289 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 290 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 291 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 292 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 293 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 294 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 295 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 296 | A | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|--------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 297 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 298 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 299 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 300 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 301 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 302 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 303 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 304 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 305 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 306 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 307 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 308 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 309 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 310 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 311 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 312 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 313 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 314 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 315 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 316 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 317 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 318 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 319 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 320 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 321 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 322 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 323 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 324 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 325 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 326 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 327 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 328 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 329 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 330 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 331 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 332 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 333 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 334 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 335 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 336 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 337 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 338 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 339 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 340 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 341 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 342 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 343 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 344 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 345 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 346 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 347 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 348 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 349 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 350 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 351 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 352 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 353 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 354 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 355 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 356 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 357 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 358 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 359 | A | 0.008104% | \$37.49 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|------------------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 360 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 361 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 362 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 363 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 364 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 365 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 366 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 367 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 368 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 369 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 370 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 371 | A | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 1 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 2 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 3 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 4 | B | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 5 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 6 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 7 | B | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 8 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 9 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 10 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 11 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 12 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 13 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 14 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 15 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 16 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 17 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 18 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 19 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 20 | B | 0.008104% | \$37.49 |
| | Parking/Locker Unit (Tandem) | | | N/A | 21 | B | 0.010422% | \$48.21 |
| | Parking Unit (Tandem) | | | N/A | 22 | B | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 23 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 24 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 25 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 26 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 27 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 28 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 29 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 30 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 31 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 32 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 33 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 34 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 35 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 36 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 37 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 38 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 39 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 40 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 41 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 42 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 43 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 44 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 45 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 46 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 47 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 48 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 49 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 50 | B | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 51 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 52 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 53 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 54 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 55 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 56 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 57 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 58 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 59 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 60 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 61 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 62 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 63 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 64 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 65 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 66 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 67 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 68 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 69 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 70 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 71 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 72 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 73 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 74 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 75 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 76 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 77 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 78 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 79 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 80 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 81 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 82 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 83 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 84 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 85 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 86 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 87 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 88 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 89 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 90 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 91 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 92 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 93 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 94 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 95 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 96 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 97 | B | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 98 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 99 | B | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 100 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 101 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 102 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 103 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 104 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 105 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 106 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 107 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 108 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 109 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 110 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 111 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 112 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 113 | B | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|---------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 114 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 115 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 116 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 117 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 118 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 119 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 120 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 121 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 122 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 123 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 124 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 125 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 126 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 127 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 128 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 129 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 130 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 131 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 132 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 133 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 134 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 135 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 136 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 137 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 138 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 139 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 140 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 141 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 142 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 143 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 144 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 145 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 146 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 147 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 148 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 149 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 150 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 151 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 152 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 153 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 154 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 155 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 156 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 157 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 158 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 159 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 160 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 161 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 162 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 163 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 164 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 165 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 166 | B | 0.008104% | \$37.49 |
| | Parking/Locker Unit | | | N/A | 167 | B | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 168 | B | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 169 | B | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 170 | B | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 171 | B | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 172 | B | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 173 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 174 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 175 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 176 | B | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses expressed as percentages to each | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 177 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 178 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 179 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 180 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 181 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 182 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 183 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 184 | B | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 185 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 186 | B | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 187 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 188 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 189 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 190 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 191 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 192 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 193 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 194 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 195 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 196 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 197 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 198 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 199 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 200 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 201 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 202 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 203 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 204 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 205 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 206 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 207 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 208 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 209 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 210 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 211 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 212 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 213 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 214 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 215 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 216 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 217 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 218 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 219 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 220 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 221 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 222 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 223 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 224 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 225 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 226 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 227 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 228 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 229 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 230 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 231 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 232 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 233 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 234 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 235 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 236 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 237 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 238 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 239 | B | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 240 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 241 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 242 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 243 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 244 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 245 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 246 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 247 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 248 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 249 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 250 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 251 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 252 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 253 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 254 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 255 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 256 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 257 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 258 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 259 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 260 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 261 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 262 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 263 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 264 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 265 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 266 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 267 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 268 | B | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 269 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 270 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 271 | B | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 272 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 273 | B | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 274 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 275 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 276 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 277 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 278 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 279 | B | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 280 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 281 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 282 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 283 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 284 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 285 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 286 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 287 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 288 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 289 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 290 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 291 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 292 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 293 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 294 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 295 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 296 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 297 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 298 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 299 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 300 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 301 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 302 | B | 0.008104% | \$37.49 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 303 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 304 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 305 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 306 | B | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 307 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 308 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 309 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 310 | B | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 311 | B | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 312 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 313 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 314 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 315 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 316 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 317 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 318 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 319 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 320 | B | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 321 | B | 0.008104% | \$37.49 |
| | Locker Unit | | | N/A | 322 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 323 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 324 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 325 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 326 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 327 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 328 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 329 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 330 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 331 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 332 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 333 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 334 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 335 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 336 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 337 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 338 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 339 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 340 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 341 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 342 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 343 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 344 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 345 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 346 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 347 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 348 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 349 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 350 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 351 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 352 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 353 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 354 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 355 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 356 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 357 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 358 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 359 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 360 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 361 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 362 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 363 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 364 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 365 | B | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 366 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 367 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 368 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 369 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 370 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 371 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 372 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 373 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 374 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 375 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 376 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 377 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 378 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 379 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 380 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 381 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 382 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 383 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 384 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 385 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 386 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 387 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 388 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 389 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 390 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 391 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 392 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 393 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 394 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 395 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 396 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 397 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 398 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 399 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 400 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 401 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 402 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 403 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 404 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 405 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 406 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 407 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 408 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 409 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 410 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 411 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 412 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 413 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 414 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 415 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 416 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 417 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 418 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 419 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 420 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 421 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 422 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 423 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 424 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 425 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 426 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 427 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 428 | B | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 429 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 430 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 431 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 432 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 433 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 434 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 435 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 436 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 437 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 438 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 439 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 440 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 441 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 442 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 443 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 444 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 445 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 446 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 447 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 448 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 449 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 450 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 451 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 452 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 453 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 454 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 455 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 456 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 457 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 458 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 459 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 460 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 461 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 462 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 463 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 464 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 465 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 466 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 467 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 468 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 469 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 470 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 471 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 472 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 473 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 474 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 475 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 476 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 477 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 478 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 479 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 480 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 481 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 482 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 483 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 484 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 485 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 486 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 487 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 488 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 489 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 490 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 491 | B | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 492 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 493 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 494 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 495 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 496 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 497 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 498 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 499 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 500 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 501 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 502 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 503 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 504 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 505 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 506 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 507 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 508 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 509 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 510 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 511 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 512 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 513 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 514 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 515 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 516 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 517 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 518 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 519 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 520 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 521 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 522 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 523 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 524 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 525 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 526 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 527 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 528 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 529 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 530 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 531 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 532 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 533 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 534 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 535 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 536 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 537 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 538 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 539 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 540 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 541 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 542 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 543 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 544 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 545 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 546 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 547 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 548 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 549 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 550 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 551 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 552 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 553 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 554 | B | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 555 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 556 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 557 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 558 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 559 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 560 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 561 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 562 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 563 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 564 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 565 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 566 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 567 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 568 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 569 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 570 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 571 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 572 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 573 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 574 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 575 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 576 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 577 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 578 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 579 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 580 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 581 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 582 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 583 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 584 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 585 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 586 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 587 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 588 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 589 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 590 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 591 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 592 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 593 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 594 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 595 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 596 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 597 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 598 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 599 | B | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 600 | B | 0.001853% | \$8.57 |
| | Parking Unit | | | N/A | 1 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 2 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 3 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 4 | C | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 5 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 6 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 7 | C | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 8 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 9 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 10 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 11 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 12 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 13 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 14 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 15 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 16 | C | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|------------------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 17 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 18 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 19 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 20 | C | 0.008104% | \$37.49 |
| | Parking/Locker Unit (Tandem) | | | N/A | 21 | C | 0.010422% | \$48.21 |
| | Parking Unit (Tandem) | | | N/A | 22 | C | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 23 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 24 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 25 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 26 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 27 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 28 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 29 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 30 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 31 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 32 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 33 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 34 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 35 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 36 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 37 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 38 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 39 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 40 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 41 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 42 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 43 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 44 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 45 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 46 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 47 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 48 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 49 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 50 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 51 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 52 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 53 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 54 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 55 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 56 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 57 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 58 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 59 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 60 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 61 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 62 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 63 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 64 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 65 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 66 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 67 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 68 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 69 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 70 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 71 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 72 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 73 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 74 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 75 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 76 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 77 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 78 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 79 | C | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to e | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|---|-----------------------------------|
| | Parking Unit | | | N/A | 80 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 81 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 82 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 83 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 84 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 85 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 86 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 87 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 88 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 89 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 90 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 91 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 92 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 93 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 94 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 95 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 96 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 97 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 98 | C | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 99 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 100 | C | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 101 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 102 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 103 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 104 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 105 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 106 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 107 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 108 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 109 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 110 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 111 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 112 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 113 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 114 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 115 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 116 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 117 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 118 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 119 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 120 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 121 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 122 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 123 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 124 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 125 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 126 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 127 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 128 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 129 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 130 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 131 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 132 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 133 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 134 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 135 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 136 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 137 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 138 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 139 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 140 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 141 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 142 | C | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to e | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|---|-----------------------------------|
| | Parking Unit | | | N/A | 143 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 144 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 145 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 146 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 147 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 148 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 149 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 150 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 151 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 152 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 153 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 154 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 155 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 156 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 157 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 158 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 159 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 160 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 161 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 162 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 163 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 164 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 165 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 166 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 167 | C | 0.008104% | \$37.49 |
| | Parking/Locker Unit | | | N/A | 168 | C | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 169 | C | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 170 | C | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 171 | C | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 172 | C | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 173 | C | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 174 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 175 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 176 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 177 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 178 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 179 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 180 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 181 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 182 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 183 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 184 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 185 | C | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 186 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 187 | C | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 188 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 189 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 190 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 191 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 192 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 193 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 194 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 195 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 196 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 197 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 198 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 199 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 200 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 201 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 202 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 203 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 204 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 205 | C | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|--------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 206 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 207 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 208 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 209 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 210 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 211 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 212 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 213 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 214 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 215 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 216 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 217 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 218 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 219 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 220 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 221 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 222 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 223 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 224 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 225 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 226 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 227 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 228 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 229 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 230 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 231 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 232 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 233 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 234 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 235 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 236 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 237 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 238 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 239 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 240 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 241 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 242 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 243 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 244 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 245 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 246 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 247 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 248 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 249 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 250 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 251 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 252 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 253 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 254 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 255 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 256 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 257 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 258 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 259 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 260 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 261 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 262 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 263 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 264 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 265 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 266 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 267 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 268 | C | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to total | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|---|-----------------------------------|
| | Parking Unit | | | N/A | 269 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 270 | C | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 271 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 272 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 273 | C | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 274 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 275 | C | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 276 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 277 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 278 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 279 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 280 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 281 | C | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 282 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 283 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 284 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 285 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 286 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 287 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 288 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 289 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 290 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 291 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 292 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 293 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 294 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 295 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 296 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 297 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 298 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 299 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 300 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 301 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 302 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 303 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 304 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 305 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 306 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 307 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 308 | C | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 309 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 310 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 311 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 312 | C | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 313 | C | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 314 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 315 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 316 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 317 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 318 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 319 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 320 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 321 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 322 | C | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 323 | C | 0.008104% | \$37.49 |
| | Locker Unit | | | N/A | 324 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 325 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 326 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 327 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 328 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 329 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 330 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 331 | C | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to e | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|---|-----------------------------------|
| | Locker Unit | | | N/A | 332 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 333 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 334 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 335 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 336 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 337 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 338 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 339 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 340 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 341 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 342 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 343 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 344 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 345 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 346 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 347 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 348 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 349 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 350 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 351 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 352 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 353 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 354 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 355 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 356 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 357 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 358 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 359 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 360 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 361 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 362 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 363 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 364 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 365 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 366 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 367 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 368 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 369 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 370 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 371 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 372 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 373 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 374 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 375 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 376 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 377 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 378 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 379 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 380 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 381 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 382 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 383 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 384 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 385 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 386 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 387 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 388 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 389 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 390 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 391 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 392 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 393 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 394 | C | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 395 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 396 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 397 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 398 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 399 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 400 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 401 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 402 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 403 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 404 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 405 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 406 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 407 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 408 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 409 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 410 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 411 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 412 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 413 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 414 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 415 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 416 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 417 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 418 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 419 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 420 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 421 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 422 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 423 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 424 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 425 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 426 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 427 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 428 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 429 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 430 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 431 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 432 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 433 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 434 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 435 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 436 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 437 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 438 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 439 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 440 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 441 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 442 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 443 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 444 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 445 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 446 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 447 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 448 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 449 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 450 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 451 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 452 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 453 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 454 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 455 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 456 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 457 | C | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 458 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 459 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 460 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 461 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 462 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 463 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 464 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 465 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 466 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 467 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 468 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 469 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 470 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 471 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 472 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 473 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 474 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 475 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 476 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 477 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 478 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 479 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 480 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 481 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 482 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 483 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 484 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 485 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 486 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 487 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 488 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 489 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 490 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 491 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 492 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 493 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 494 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 495 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 496 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 497 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 498 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 499 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 500 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 501 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 502 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 503 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 504 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 505 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 506 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 507 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 508 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 509 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 510 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 511 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 512 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 513 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 514 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 515 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 516 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 517 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 518 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 519 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 520 | C | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses sed as percentages to e | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|---|-----------------------------------|
| | Locker Unit | | | N/A | 521 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 522 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 523 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 524 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 525 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 526 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 527 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 528 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 529 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 530 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 531 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 532 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 533 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 534 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 535 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 536 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 537 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 538 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 539 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 540 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 541 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 542 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 543 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 544 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 545 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 546 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 547 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 548 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 549 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 550 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 551 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 552 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 553 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 554 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 555 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 556 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 557 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 558 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 559 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 560 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 561 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 562 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 563 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 564 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 565 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 566 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 567 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 568 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 569 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 570 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 571 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 572 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 573 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 574 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 575 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 576 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 577 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 578 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 579 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 580 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 581 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 582 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 583 | C | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to e | Monthly Common Element Assessment |
|----------|------------------------------|-----------|-------|------|----------|-----------|---|-----------------------------------|
| | Locker Unit | | | N/A | 584 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 585 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 586 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 587 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 588 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 589 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 590 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 591 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 592 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 593 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 594 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 595 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 596 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 597 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 598 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 599 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 600 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 601 | C | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 602 | C | 0.001853% | \$8.57 |
| | Parking Unit | | | N/A | 1 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 2 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 3 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 4 | D | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 5 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 6 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 7 | D | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 8 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 9 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 10 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 11 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 12 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 13 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 14 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 15 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 16 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 17 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 18 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 19 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 20 | D | 0.008104% | \$37.49 |
| | Parking/Locker Unit (Tandem) | | | N/A | 21 | D | 0.010422% | \$48.21 |
| | Parking Unit (Tandem) | | | N/A | 22 | D | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 23 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 24 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 25 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 26 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 27 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 28 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 29 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 30 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 31 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 32 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 33 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 34 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 35 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 36 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 37 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 38 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 39 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 40 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 41 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 42 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 43 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 44 | D | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 45 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 46 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 47 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 48 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 49 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 50 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 51 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 52 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 53 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 54 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 55 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 56 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 57 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 58 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 59 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 60 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 61 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 62 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 63 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 64 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 65 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 66 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 67 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 68 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 69 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 70 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 71 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 72 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 73 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 74 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 75 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 76 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 77 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 78 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 79 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 80 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 81 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 82 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 83 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 84 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 85 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 86 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 87 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 88 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 89 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 90 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 91 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 92 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 93 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 94 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 95 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 96 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 97 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 98 | D | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 99 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 100 | D | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 101 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 102 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 103 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 104 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 105 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 106 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 107 | D | 0.008104% | \$37.49 |

Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|---------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 108 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 109 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 110 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 111 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 112 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 113 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 114 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 115 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 116 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 117 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 118 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 119 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 120 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 121 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 122 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 123 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 124 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 125 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 126 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 127 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 128 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 129 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 130 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 131 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 132 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 133 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 134 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 135 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 136 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 137 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 138 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 139 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 140 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 141 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 142 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 143 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 144 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 145 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 146 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 147 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 148 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 149 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 150 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 151 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 152 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 153 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 154 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 155 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 156 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 157 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 158 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 159 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 160 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 161 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 162 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 163 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 164 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 165 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 166 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 167 | D | 0.008104% | \$37.49 |
| | Parking/Locker Unit | | | N/A | 168 | D | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 169 | D | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 170 | D | 0.009263% | \$42.85 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking/Locker Unit | | | N/A | 171 | D | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 172 | D | 0.009263% | \$42.85 |
| | Parking/Locker Unit | | | N/A | 173 | D | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 174 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 175 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 176 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 177 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 178 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 179 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 180 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 181 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 182 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 183 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 184 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 185 | D | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 186 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 187 | D | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 188 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 189 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 190 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 191 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 192 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 193 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 194 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 195 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 196 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 197 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 198 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 199 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 200 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 201 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 202 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 203 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 204 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 205 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 206 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 207 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 208 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 209 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 210 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 211 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 212 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 213 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 214 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 215 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 216 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 217 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 218 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 219 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 220 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 221 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 222 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 223 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 224 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 225 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 226 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 227 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 228 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 229 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 230 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 231 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 232 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 233 | D | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 234 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 235 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 236 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 237 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 238 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 239 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 240 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 241 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 242 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 243 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 244 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 245 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 246 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 247 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 248 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 249 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 250 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 251 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 252 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 253 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 254 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 255 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 256 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 257 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 258 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 259 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 260 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 261 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 262 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 263 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 264 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 265 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 266 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 267 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 268 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 269 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 270 | D | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 271 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 272 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 273 | D | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 274 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 275 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 276 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 277 | D | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 278 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 279 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 280 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 281 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 282 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 283 | D | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 284 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 285 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 286 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 287 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 288 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 289 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 290 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 291 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 292 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 293 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 294 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 295 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 296 | D | 0.008104% | \$37.49 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-----------------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Parking Unit | | | N/A | 297 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 298 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 299 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 300 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 301 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 302 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 303 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 304 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 305 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 306 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 307 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 308 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 309 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 310 | D | 0.008104% | \$37.49 |
| | Parking Unit (Tandem) | | | N/A | 311 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 312 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 313 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 314 | D | 0.009263% | \$42.85 |
| | Parking Unit (Tandem) | | | N/A | 315 | D | 0.009263% | \$42.85 |
| | Parking Unit | | | N/A | 316 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 317 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 318 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 319 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 320 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 321 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 322 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 323 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 324 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 325 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 326 | D | 0.008104% | \$37.49 |
| | Parking Unit | | | N/A | 327 | D | 0.008104% | \$37.49 |
| | Locker Unit | | | N/A | 328 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 329 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 330 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 331 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 332 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 333 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 334 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 335 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 336 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 337 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 338 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 339 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 340 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 341 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 342 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 343 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 344 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 345 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 346 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 347 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 348 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 349 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 350 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 351 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 352 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 353 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 354 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 355 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 356 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 357 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 358 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 359 | D | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 360 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 361 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 362 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 363 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 364 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 365 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 366 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 367 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 368 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 369 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 370 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 371 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 372 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 373 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 374 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 375 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 376 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 377 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 378 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 379 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 380 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 381 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 382 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 383 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 384 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 385 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 386 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 387 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 388 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 389 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 390 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 391 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 392 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 393 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 394 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 395 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 396 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 397 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 398 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 399 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 400 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 401 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 402 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 403 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 404 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 405 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 406 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 407 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 408 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 409 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 410 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 411 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 412 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 413 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 414 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 415 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 416 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 417 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 418 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 419 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 420 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 421 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 422 | D | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 423 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 424 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 425 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 426 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 427 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 428 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 429 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 430 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 431 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 432 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 433 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 434 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 435 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 436 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 437 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 438 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 439 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 440 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 441 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 442 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 443 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 444 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 445 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 446 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 447 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 448 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 449 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 450 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 451 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 452 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 453 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 454 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 455 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 456 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 457 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 458 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 459 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 460 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 461 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 462 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 463 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 464 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 465 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 466 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 467 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 468 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 469 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 470 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 471 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 472 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 473 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 474 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 475 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 476 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 477 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 478 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 479 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 480 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 481 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 482 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 483 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 484 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 485 | D | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
Schedule of Common Element Assessments
For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses as percentages to each | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|--|-----------------------------------|
| | Locker Unit | | | N/A | 486 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 487 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 488 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 489 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 490 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 491 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 492 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 493 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 494 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 495 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 496 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 497 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 498 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 499 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 500 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 501 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 502 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 503 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 504 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 505 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 506 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 507 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 508 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 509 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 510 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 511 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 512 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 513 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 514 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 515 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 516 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 517 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 518 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 519 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 520 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 521 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 522 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 523 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 524 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 525 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 526 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 527 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 528 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 529 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 530 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 531 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 532 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 533 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 534 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 535 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 536 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 537 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 538 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 539 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 540 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 541 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 542 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 543 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 544 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 545 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 546 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 547 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 548 | D | 0.001853% | \$8.57 |

**Uptown Markham - Riverview Condominiums (Buildings A, B & C)
 Schedule of Common Element Assessments
 For the First Year Following Registration**

| Building | Unit Type | Suite No. | Model | Size | Unit No. | Level No. | Proportion of Common Interests and Expenses sed as percentages to e | Monthly Common Element Assessment |
|----------|-------------|-----------|-------|------|----------|-----------|---|-----------------------------------|
| | Locker Unit | | | N/A | 549 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 550 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 551 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 552 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 553 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 554 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 555 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 556 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 557 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 558 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 559 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 560 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 561 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 562 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 563 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 564 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 565 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 566 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 567 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 568 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 569 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 570 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 571 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 572 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 573 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 574 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 575 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 576 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 577 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 578 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 579 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 580 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 581 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 582 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 583 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 584 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 585 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 586 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 587 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 588 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 589 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 590 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 591 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 592 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 593 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 594 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 595 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 596 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 597 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 598 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 599 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 600 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 601 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 602 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 603 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 604 | D | 0.001853% | \$8.57 |
| | Locker Unit | | | N/A | 605 | D | 0.001853% | \$8.57 |
| | | | | | | | | \$462,584.21 |
| | | | | | | | | x 12 |
| | | | | | | | | \$5,551,010.52 |